| Parent agency | Department | Make | Model Number | Serial Number | Туре | Airtime Minutes |
|----------------------------------|---------------------------------------|----------|--------------|---------------|--------------------|-----------------|
| Ashippun Fire Department | Ashippun Fire Department | Motorola | H01UCF6PW1BN | 466ABW3162 | MTS-2000 Model II | 1.47 |
| | Ashippun Fire Department Total | | | | | 1.47 |
| Ashippun Fire Department Total | | | | | | 1.47 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2336 | MTS-2000 Model I | 0.35 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2293 | MTS-2000 Model I | 0.37 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2287 | MTS-2000 Model I | 0.37 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2308 | MTS-2000 Model I | 0.81 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2319 | MTS-2000 Model I | 1.40 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2295 | MTS-2000 Model I | 1.69 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2325 | MTS-2000 Model I | 2.17 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE4920 | MTS-2000 Model I | 2.19 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2297 | MTS-2000 Model I | 2.31 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2296 | MTS-2000 Model I | 2.33 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE5013 | MTS-2000 Model I | 2.37 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE4933 | MTS-2000 Model I | 2.55 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2299 | MTS-2000 Model I | 3.22 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE5020 | MTS-2000 Model I | 4.80 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2327 | MTS-2000 Model I | 4.89 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2312 | MTS-2000 Model I | 5.15 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2290 | MTS-2000 Model I | 5.39 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2305 | MTS-2000 Model I | 6.83 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCD6PW1BN | 466ABE2315 | MTS-2000 Model I | 9.22 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | H01UCH6PW1BN | 466AAE3942 | MTS-2000 Model III | 1.04 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0943 | LCS-2000 w/scan | 0.45 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0935 | LCS-2000 w/scan | 0.48 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0952 | LCS-2000 w/scan | 0.50 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0903 | LCS-2000 w/scan | 0.74 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0904 | LCS-2000 w/scan | 2.05 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0907 | LCS-2000 w/scan | 2.23 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0114 | LCS-2000 w/scan | 4.89 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0918 | LCS-2000 w/scan | 10.80 |
| Big Bend/Vernon Fire Dept. | Big Bend/Vernon Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0118 | LCS-2000 w/scan | 12.75 |
| | Big Bend/Vernon Fire Department Total | | | | | 94.35 |
| Big Bend/Vernon Fire Dept. Total | | | | | | 94.35 |
| Brookfield, City | Brookfield City Comm. Dev. Department | Motorola | H10UCH6DC5BN | 678SAYDX06 | LTS-2000 w/o scan | 0.77 |
| Brookfield, City | Brookfield City Comm. Dev. Department | Motorola | H10UCH6DC5BN | 678SAYDX11 | LTS-2000 w/o scan | 2.01 |

| Brookfield, City | Brookfield City Comm. Dev. Department | Motorola | H10UCH6DC5BN | 678SAYDV93 | LTS-2000 w/o scan | 2.71 |
|------------------|--|----------|--------------|------------|-------------------|--------|
| Brookfield, City | Brookfield City Comm. Dev. Department | Motorola | H10UCH6DC5BN | 678SAW1557 | LTS-2000 w/o scan | 3.17 |
| Brookfield, City | Brookfield City Comm. Dev. Department | Motorola | H10UCH6DC5BN | 678SAYDX14 | LTS-2000 w/o scan | 3.26 |
| Brookfield, City | Brookfield City Comm. Dev. Department | Motorola | H10UCH6DC5BN | 678SAYEB65 | LTS-2000 w/o scan | 3.45 |
| Brookfield, City | Brookfield City Comm. Dev. Department | Motorola | H10UCH6DC5BN | 678SAYDY62 | LTS-2000 w/o scan | 4.76 |
| Brookfield, City | Brookfield City Comm. Dev. Department | Motorola | H10UCH6DC5BN | 678SAYDX17 | LTS-2000 w/o scan | 8.13 |
| Brookfield, City | Brookfield City Comm. Dev. Department | Motorola | H10UCH6DC5BN | 678SAYDX05 | LTS-2000 w/o scan | 10.93 |
| Brookfield, City | Brookfield City Comm. Dev. Department | Motorola | M10UGD6DC5BN | 760SAYFB64 | LCS-2000 w/o scan | 7.59 |
| | Brookfield City Comm. Dev. Department Total | | | | | 46.79 |
| Brookfield, City | Brookfield City Engineering Department | Motorola | H10UCH6DC5BN | 678SAYEB67 | LTS-2000 w/o scan | 2.59 |
| Brookfield, City | Brookfield City Engineering Department | Motorola | H10UCH6DC5BN | 678SAYDX61 | LTS-2000 w/o scan | 7.03 |
| Brookfield, City | Brookfield City Engineering Department | Motorola | H10UCH6DC5BN | 678SAYDX07 | LTS-2000 w/o scan | 7.21 |
| Brookfield, City | Brookfield City Engineering Department | Motorola | H10UCH6DC5BN | 678SAYDX09 | LTS-2000 w/o scan | 8.66 |
| Brookfield, City | Brookfield City Engineering Department | Motorola | H10UCH6DC5BN | 678SAYDX24 | LTS-2000 w/o scan | 9.33 |
| Brookfield, City | Brookfield City Engineering Department | Motorola | H10UCH6DC5BN | 678SAYDX98 | LTS-2000 w/o scan | 9.71 |
| Brookfield, City | Brookfield City Engineering Department | Motorola | H10UCH6DC5BN | 678SAYDX50 | LTS-2000 w/o scan | 9.93 |
| Brookfield, City | Brookfield City Engineering Department | Motorola | H10UCH6DC5BN | 678SEW0629 | LTS-2000 w/o scan | 9.93 |
| Brookfield, City | Brookfield City Engineering Department | Motorola | H10UCH6DC5BN | 678SAYDX62 | LTS-2000 w/o scan | 25.62 |
| Brookfield, City | Brookfield City Engineering Department | Motorola | H10UCH6DC5BN | 678SAYDX55 | LTS-2000 w/o scan | 41.61 |
| Brookfield, City | Brookfield City Engineering Department | Motorola | H10UCH6DC5BN | 678SAYDX22 | LTS-2000 w/o scan | 60.19 |
| Brookfield, City | Brookfield City Engineering Department | Motorola | M10UGD6DC5BN | 760SAYFG90 | LCS-2000 w/o scan | 2.77 |
| | Brookfield City Engineering Department Total | | | | | 194.58 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABQ0728 | MTS-2000 Model II | 0.36 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1903 | MTS-2000 Model II | 0.43 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABQ0726 | MTS-2000 Model II | 0.44 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1874 | MTS-2000 Model II | 0.47 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466CDC1975 | MTS-2000 Model II | 0.79 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1906 | MTS-2000 Model II | 0.80 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1913 | MTS-2000 Model II | 0.90 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1883 | MTS-2000 Model II | 0.91 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABQ0730 | MTS-2000 Model II | 1.01 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABQ0734 | MTS-2000 Model II | 1.04 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1897 | MTS-2000 Model II | 1.08 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABQ0729 | MTS-2000 Model II | 1.41 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1872 | MTS-2000 Model II | 1.44 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1905 | MTS-2000 Model II | 1.57 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1914 | MTS-2000 Model II | 1.71 |

| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABQ0735 | MTS-2000 Model II | 2.04 |
|------------------|---|----------|--------------|------------|-----------------------|--------|
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1888 | MTS-2000 Model II | 2.15 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1867 | MTS-2000 Model II | 3.49 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1873 | MTS-2000 Model II | 4.04 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1895 | MTS-2000 Model II | 4.11 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1868 | MTS-2000 Model II | 6.41 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABQ0731 | MTS-2000 Model II | 6.47 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1908 | MTS-2000 Model II | 6.83 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1894 | MTS-2000 Model II | 11.53 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1907 | MTS-2000 Model II | 13.93 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1898 | MTS-2000 Model II | 15.87 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H01UCF6PW1BN | 466ABE1890 | MTS-2000 Model II | 16.85 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UGL6PW4BN | 722ABE1054 | MCS-2000 Control Base | 0.67 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01ugl6pw4bn | 722ABE1055 | MCS-2000 Control Base | 1.18 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1288 | MCS-2000 | 1.06 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1292 | MCS-2000 | 6.57 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1287 | MCS-2000 | 7.67 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1314 | MCS-2000 | 13.79 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1294 | MCS-2000 | 28.49 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1296 | MCS-2000 | 29.29 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1302 | MCS-2000 | 37.79 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1289 | MCS-2000 | 48.66 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1301 | MCS-2000 | 53.62 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1291 | MCS-2000 | 59.39 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UJM6PW6BN | 722CDC0319 | MCS-2000 Dual Control | 23.81 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M10UGD6DC5BN | 760SBA0634 | LCS-2000 w/scan | 0.43 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M10UGD6DC5BN | 760SBA0740 | LCS-2000 w/scan | 0.68 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M10UGD6DC5BN | 760SBA0591 | LCS-2000 w/scan | 1.49 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M10UGD6DC5BN | 760SBA0755 | LCS-2000 w/scan | 4.34 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M10UGD6DC5BN | 760SBA0835 | LCS-2000 w/scan | 6.05 |
| | Brookfield City Fire Department Total | | | | | 433.07 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | H10UCH6DC5BN | 678SAW1553 | LTS-2000 w/o scan | 4.96 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | H10UCH6DC5BN | 678SAYDX25 | LTS-2000 w/o scan | 5.16 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | H10UCH6DC5BN | 678SAYDX19 | LTS-2000 w/o scan | 9.77 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | H10UCH6DC5BN | 678SAW2408 | LTS-2000 w/o scan | 10.84 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | H10UCH6DC5BN | 678SAYDX04 | LTS-2000 w/o scan | 16.23 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYEY94 | LCS-2000 w/o scan | 1.56 |

| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYEZ44 | LCS-2000 w/o scan | 2.85 |
|------------------|---|----------|--------------|------------|-------------------|--------|
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFE62 | LCS-2000 w/o scan | 2.87 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYEZ98 | LCS-2000 w/o scan | 5.39 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFF48 | LCS-2000 w/o scan | 5.83 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFC74 | LCS-2000 w/o scan | 5.99 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYEY60 | LCS-2000 w/o scan | 7.96 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFD11 | LCS-2000 w/o scan | 9.85 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYEY62 | LCS-2000 w/o scan | 10.35 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFC76 | LCS-2000 w/o scan | 11.28 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFD12 | LCS-2000 w/o scan | 12.41 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYEZ51 | LCS-2000 w/o scan | 12.56 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFF06 | LCS-2000 w/o scan | 13.79 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFG20 | LCS-2000 w/o scan | 15.24 |
| | Brookfield City Parks and Recreation Department Total | | | | | 164.89 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1826 | MTS-2000 Model II | 0.36 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1814 | MTS-2000 Model II | 0.37 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1844 | MTS-2000 Model II | 0.41 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1819 | MTS-2000 Model II | 2.23 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1815 | MTS-2000 Model II | 2.29 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1837 | MTS-2000 Model II | 2.35 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1830 | MTS-2000 Model II | 2.54 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1822 | MTS-2000 Model II | 2.55 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1857 | MTS-2000 Model II | 2.61 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1833 | MTS-2000 Model II | 2.98 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1859 | MTS-2000 Model II | 3.91 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1817 | MTS-2000 Model II | 5.07 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1835 | MTS-2000 Model II | 8.47 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1834 | MTS-2000 Model II | 9.39 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1841 | MTS-2000 Model II | 9.82 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1843 | MTS-2000 Model II | 10.19 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1862 | MTS-2000 Model II | 11.83 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1838 | MTS-2000 Model II | 12.87 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1821 | MTS-2000 Model II | 13.13 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1861 | MTS-2000 Model II | 13.33 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1853 | MTS-2000 Model II | 13.57 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1823 | MTS-2000 Model II | 16.46 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1854 | MTS-2000 Model II | 18.55 |

| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1860 | MTS-2000 Model II | 19.07 |
|------------------|-----------------------------------|----------|--------------|------------|-----------------------|--------|
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1845 | MTS-2000 Model II | 20.13 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1849 | MTS-2000 Model II | 20.72 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1832 | MTS-2000 Model II | 20.85 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1848 | MTS-2000 Model II | 21.65 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1813 | MTS-2000 Model II | 21.89 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1824 | MTS-2000 Model II | 24.26 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1842 | MTS-2000 Model II | 26.95 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1827 | MTS-2000 Model II | 28.66 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1852 | MTS-2000 Model II | 29.11 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1825 | MTS-2000 Model II | 32.19 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1855 | MTS-2000 Model II | 33.21 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1850 | MTS-2000 Model II | 37.43 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1820 | MTS-2000 Model II | 39.69 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1836 | MTS-2000 Model II | 41.80 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1829 | MTS-2000 Model II | 41.96 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1831 | MTS-2000 Model II | 50.03 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1856 | MTS-2000 Model II | 65.86 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGL6PW4BN | 722ABJ0514 | MCS-2000 Control Base | 16.41 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1347 | MCS-2000 | 1.17 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1326 | MCS-2000 | 2.33 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1269 | MCS-2000 | 3.97 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1350 | MCS-2000 | 5.05 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1324 | MCS-2000 | 7.41 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1338 | MCS-2000 | 8.51 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1323 | MCS-2000 | 10.99 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1340 | MCS-2000 | 14.57 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1335 | MCS-2000 | 44.50 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1332 | MCS-2000 | 66.73 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1329 | MCS-2000 | 78.19 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1348 | MCS-2000 | 89.28 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1327 | MCS-2000 | 95.21 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1336 | MCS-2000 | 99.85 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1330 | MCS-2000 | 101.92 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1297 | MCS-2000 | 103.81 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1333 | MCS-2000 | 110.22 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1328 | MCS-2000 | 124.31 |

| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1319 | MCS-2000 | 125.69 |
|------------------|---|----------|--------------|------------|-------------------|----------|
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1321 | MCS-2000 | 143.55 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1322 | MCS-2000 | 145.14 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1339 | MCS-2000 | 149.75 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1331 | MCS-2000 | 154.95 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1320 | MCS-2000 | 158.58 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1353 | MCS-2000 | 171.19 |
| | Brookfield City Police Department Total | | | | | 2,774.03 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAYDX54 | LTS-2000 w/o scan | 0.37 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAYDX59 | LTS-2000 w/o scan | 0.47 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAYEA59 | LTS-2000 w/o scan | 0.51 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAW1556 | LTS-2000 w/o scan | 1.28 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAYDX13 | LTS-2000 w/o scan | 1.94 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAW1551 | LTS-2000 w/o scan | 2.01 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAYDV94 | LTS-2000 w/o scan | 2.17 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAYDW41 | LTS-2000 w/o scan | 2.23 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAYDY41 | LTS-2000 w/o scan | 2.42 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAYDX53 | LTS-2000 w/o scan | 3.65 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678sby7423 | LCS-2000 w/o scan | 3.67 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAYDW44 | LTS-2000 w/o scan | 7.15 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAW2349 | LTS-2000 w/o scan | 7.61 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAYEB68 | LTS-2000 w/o scan | 8.22 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAYDX52 | LTS-2000 w/o scan | 9.87 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | H10UCH6DC5BN | 678SAYDX65 | LTS-2000 w/o scan | 13.19 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFA42 | LCS-2000 w/o scan | 0.39 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFF34 | LCS-2000 w/o scan | 0.41 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFF67 | LCS-2000 w/o scan | 0.47 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEY99 | LCS-2000 w/o scan | 0.47 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ64 | LCS-2000 w/o scan | 0.48 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFF99 | LCS-2000 w/o scan | 0.50 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ25 | LCS-2000 w/o scan | 0.52 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SBA0435 | LCS-2000 w/o scan | 0.67 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFA44 | LCS-2000 w/o scan | 0.70 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ26 | LCS-2000 w/o scan | 0.71 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFF33 | LCS-2000 w/o scan | 0.78 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ56 | LCS-2000 w/o scan | 0.78 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFG77 | LCS-2000 w/o scan | 0.83 |

| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ61 | LCS-2000 w/o scan | 0.83 |
|------------------|--|----------|--------------|------------|-------------------|--------|
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ95 | LCS-2000 w/o scan | 0.85 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFA46 | LCS-2000 w/o scan | 1.00 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFB95 | LCS-2000 w/o scan | 1.05 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEY51 | LCS-2000 w/o scan | 1.06 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ23 | LCS-2000 w/o scan | 1.10 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFA02 | LCS-2000 w/o scan | 1.13 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFC13 | LCS-2000 w/o scan | 1.15 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFF44 | LCS-2000 w/o scan | 1.19 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFB73 | LCS-2000 w/o scan | 1.33 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFF57 | LCS-2000 w/o scan | 1.80 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFF60 | LCS-2000 w/o scan | 2.17 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ70 | LCS-2000 w/o scan | 2.49 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ19 | LCS-2000 w/o scan | 2.53 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFF70 | LCS-2000 w/o scan | 2.90 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ12 | LCS-2000 w/o scan | 4.82 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ43 | LCS-2000 w/o scan | 4.84 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SBA0434 | LCS-2000 w/o scan | 5.17 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ93 | LCS-2000 w/o scan | 5.25 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFA52 | LCS-2000 w/o scan | 7.93 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFA47 | LCS-2000 w/o scan | 8.09 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFG07 | LCS-2000 w/o scan | 11.18 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SBA0423 | LCS-2000 w/o scan | 13.25 |
| Brookfield, City | Brookfield City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYFB90 | LCS-2000 w/o scan | 16.67 |
| | Brookfield City Public Works Department Total | | | | | 174.25 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | H10UCH6DC5BN | 678SAYDX18 | LTS-2000 w/o scan | 0.34 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | H10UCH6DC5BN | 678SAYDY63 | LTS-2000 w/o scan | 1.48 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | H10UCH6DC5BN | 678SAYDX96 | LTS-2000 w/o scan | 2.84 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | H10UCH6DC5BN | 678SAYDX83 | LTS-2000 w/o scan | 2.94 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | H10UCH6DC5BN | 678SAYDY20 | LTS-2000 w/o scan | 5.17 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M10UGD6DC5BN | 760SAYEZ45 | LCS-2000 w/o scan | 0.38 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M10UGD6DC5BN | 760SAYFC69 | LCS-2000 w/o scan | 0.51 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M10UGD6DC5BN | 760SAYEZ60 | LCS-2000 w/o scan | 0.75 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M10UGD6DC5BN | 760SAYEZ42 | LCS-2000 w/o scan | 0.77 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M10UGD6DC5BN | 760SAYEZ50 | LCS-2000 w/o scan | 0.81 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M10UGD6DC5BN | 760SAYEZ39 | LCS-2000 w/o scan | 1.41 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M10UGD6DC5BN | 760SAYFD09 | LCS-2000 w/o scan | 1.63 |

| Brookfield, City | Brookfield City Sewer Utility | Motorola | M10UGD6DC5BN | 760SAYEZ41 | LCS-2000 w/o scan | 2.27 |
|------------------------|-------------------------------------|----------|--------------|------------|-------------------|----------|
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M10UGD6DC5BN | 760SAYFC75 | LCS-2000 w/o scan | 4.11 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M10UGD6DC5BN | 760SAYFG83 | LCS-2000 w/o scan | 12.70 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M10UGD6DC5BN | 760SAYFD10 | LCS-2000 w/o scan | 12.87 |
| | Brookfield City Sewer Utility Total | | | | | 50.98 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SBE0830 | LTS-2000 w/o scan | 1.12 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SBE0832 | LTS-2000 w/o scan | 2.32 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SAYDX12 | LTS-2000 w/o scan | 2.86 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SBE0816 | LTS-2000 w/o scan | 8.03 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SBE0827 | LTS-2000 w/o scan | 9.53 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SBE0857 | LTS-2000 w/o scan | 13.29 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SBE0822 | LTS-2000 w/o scan | 15.15 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SBE0850 | LTS-2000 w/o scan | 15.59 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SBE0835 | LTS-2000 w/o scan | 16.85 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SBE0831 | LTS-2000 w/o scan | 18.57 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SAW1552 | LTS-2000 w/o scan | 21.17 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SBE0837 | LTS-2000 w/o scan | 26.18 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H10UCH6DC5BN | 678SBE0845 | LTS-2000 w/o scan | 38.65 |
| | Brookfield City Water Utility Total | | | | | 189.29 |
| Brookfield, City Total | | | | | | 4,027.89 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3193 | MTS-2000 Model II | 0.50 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3158 | MTS-2000 Model II | 1.32 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3212 | MTS-2000 Model II | 1.45 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3213 | MTS-2000 Model II | 1.60 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3198 | MTS-2000 Model II | 1.75 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3208 | MTS-2000 Model II | 1.98 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3190 | MTS-2000 Model II | 2.03 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3236 | MTS-2000 Model II | 2.06 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3205 | MTS-2000 Model II | 2.54 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3202 | MTS-2000 Model II | 2.89 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3197 | MTS-2000 Model II | 3.09 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3188 | MTS-2000 Model II | 3.41 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3207 | MTS-2000 Model II | 3.52 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3210 | MTS-2000 Model II | 3.87 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3155 | MTS-2000 Model II | 4.45 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3171 | MTS-2000 Model II | 13.36 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H01UCF6PW1BN | 466abl3209 | MTS-2000 Model II | 27.78 |

| Brookfield, Town | Brookfield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1341 | MCS-2000 | 0.76 |
|------------------|---|----------|--------------|------------|-----------------------|--------|
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1298 | MCS-2000 | 1.09 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1327 | MCS-2000 | 1.15 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M01UGM6PW6BN | 722AWL1066 | MCS-2000 | 8.35 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1389 | MCS-2000 Dual Control | 13.06 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M01UGM6PW6BN | 722AWL1097 | MCS-2000 | 33.52 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1332 | MCS-2000 | 47.09 |
| | Brookfield Town Fire Department Total | | | | | 182.61 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3231 | MTS-2000 Model II | 0.89 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3222 | MTS-2000 Model II | 2.84 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3216 | MTS-2000 Model II | 3.17 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3214 | MTS-2000 Model II | 3.41 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3242 | MTS-2000 Model II | 4.39 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3244 | MTS-2000 Model II | 5.57 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3230 | MTS-2000 Model II | 5.82 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3237 | MTS-2000 Model II | 10.52 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3224 | MTS-2000 Model II | 19.07 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3235 | MTS-2000 Model II | 20.35 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3218 | MTS-2000 Model II | 20.63 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3226 | MTS-2000 Model II | 21.23 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3217 | MTS-2000 Model II | 21.51 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3243 | MTS-2000 Model II | 22.03 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3215 | MTS-2000 Model II | 22.33 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3234 | MTS-2000 Model II | 23.93 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H01UCF6PW1BN | 466abl3241 | MTS-2000 Model II | 38.83 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H18UCF9PW6AN | 721CEG0207 | XTS-5000 Model II | 0.73 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H18UCF9PW6AN | 721CEG0206 | XTS-5000 Model II | 1.05 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H18UCF9PW6AN | 721CEG0202 | XTS-5000 Model II | 3.44 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H18UCF9PW6AN | 721CEG0201 | XTS-5000 Model II | 11.31 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M01UGM6PW6BN | 722abl1336 | MCS-2000 | 1.32 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | m01ugm6pw6bn | 722abl1329 | MCS-2000 | 1.37 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M01UGM6PW6BN | 722abl1333 | MCS-2000 | 29.87 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M01UGM6PW6BN | 722abl1335 | MCS-2000 | 61.38 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M01UGM6PW6BN | 722abl1321 | MCS-2000 | 88.57 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M01UGM6PW6BN | 722abl1317 | MCS-2000 | 189.53 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M01UGM6PW6BN | 722abl1343 | MCS-2000 | 206.92 |
| | Brookfield Town Police Department Total | | | | | 842.01 |

| Brookfield, Town Total | | | | | | 1,024.62 |
|------------------------|--|----------|--------------|------------|----------------------|----------|
| Butler | Butler Fire Department | Motorola | H01UCF6PW1BN | 466cen0314 | MTS-2000 Model II FM | 6.17 |
| Butler | Butler Fire Department | Motorola | H18UCF9PW6AN | 721CFV1380 | XTS-5000 Model II FM | 1.36 |
| Butler | Butler Fire Department | Motorola | H18UCF9PW6AN | 721CFV1370 | XTS-5000 Model II FM | 1.38 |
| Butler | Butler Fire Department | Motorola | H18UCF9PW6AN | 721CFV1382 | XTS-5000 Model II FM | 1.83 |
| Butler | Butler Fire Department | Motorola | H18UCF9PW6AN | 721CFV1373 | XTS-5000 Model II FM | 3.02 |
| Butler | Butler Fire Department | Motorola | H18UCF9PW6AN | 721CFV1371 | XTS-5000 Model II FM | 3.78 |
| Butler | Butler Fire Department | Motorola | H18UCF9PW6AN | 721CFV1383 | XTS-5000 Model II FM | 5.19 |
| Butler | Butler Fire Department | Motorola | M01UGM6PW6BN | 722cen0356 | MCS-2000 | 2.46 |
| Butler | Butler Fire Department | Motorola | M01UGM6PW6BN | 722cen0352 | MCS-2000 | 2.71 |
| Butler | Butler Fire Department | Motorola | M01UGM6PW6BN | 722cen0351 | MCS-2000 | 3.21 |
| Butler | Butler Fire Department | Motorola | M01UGM6PW6BN | 722cen0350 | MCS-2000 | 3.54 |
| Butler | Butler Fire Department | Motorola | M01UGM6PW6BN | 722cen0357 | MCS-2000 | 4.37 |
| Butler | Butler Fire Department | Motorola | M01UGM6PW6BN | 722cen0354 | MCS-2000 | 9.75 |
| | Butler Fire Department Total | | | | | 48.77 |
| Butler | Butler Police Department | Motorola | H01UCF6PW1BN | 466CEN0351 | MTS-2000 Model II | 0.48 |
| Butler | Butler Police Department | Motorola | H01UCF6PW1BN | 466CEN0349 | MTS-2000 Model II | 6.00 |
| Butler | Butler Police Department | Motorola | H01UCF6PW1BN | 466CEN0353 | MTS-2000 Model II | 6.81 |
| Butler | Butler Police Department | Motorola | H01UCF6PW1BN | 466CEN0347 | MTS-2000 Model II | 9.66 |
| Butler | Butler Police Department | Motorola | H01UCF6PW1BN | 466CEN0354 | MTS-2000 Model II | 11.83 |
| Butler | Butler Police Department | Motorola | H01UCF6PW1BN | 466CEN0355 | MTS-2000 Model II | 13.01 |
| Butler | Butler Police Department | Motorola | H01UCF6PW1BN | 466CEN0350 | MTS-2000 Model II | 13.19 |
| Butler | Butler Police Department | Motorola | H01UCF6PW1BN | 466CEN0346 | MTS-2000 Model II | 13.91 |
| Butler | Butler Police Department | Motorola | H01UCF6PW1BN | 466CEN0348 | MTS-2000 Model II | 15.50 |
| Butler | Butler Police Department | Motorola | M01UGM6PW6BN | 722CEN0539 | MCS-2000 | 51.74 |
| Butler | Butler Police Department | Motorola | M01UGM6PW6BN | 722CEN0540 | MCS-2000 | 75.54 |
| Butler | Butler Police Department | Motorola | M20URS9PW1AN | 500CFX2015 | XTL-5000 Mobile | 17.12 |
| | Butler Police Department Total | | | | | 234.79 |
| Butler Total | | | | | | 283.57 |
| Chenequa | Chenequa Village Fire Department | Motorola | H01UCD6PW1BN | 466ABE4988 | MTS-2000 Model I | 0.37 |
| Chenequa | Chenequa Village Fire Department | Motorola | H01UCD6PW1BN | 466ABE5015 | MTS-2000 Model I | 0.49 |
| Chenequa | Chenequa Village Fire Department | Motorola | H01UCD6PW1BN | 466ABE4990 | MTS-2000 Model I | 1.14 |
| Chenequa | Chenequa Village Fire Department | Motorola | H01UCD6PW1BN | 466ABE5006 | MTS-2000 Model I | 1.51 |
| Chenequa | Chenequa Village Fire Department | Motorola | H01UCD6PW1BN | 466ABE5018 | MTS-2000 Model I | 10.98 |
| Chenequa | Chenequa Village Fire Department | Motorola | M10UGD6DC5BN | 760SAW0988 | LCS-2000 w/scan | 0.37 |
| | Chenequa Village Fire Department Total | | | | | 14.86 |
| Chenequa | Chenequa Village Highway/Forestry Department | Motorola | H01UCF6PW1BN | 466ABW4506 | MTS-2000 Model II | 8.09 |

| Chenequa | Chenequa Village Highway/Forestry Department | Motorola | H01UCF6PW1BN | 466ABW5371 | MTS-2000 Model II | 20.53 |
|-----------------------------------|--|----------|--------------|------------|---------------------|--------|
| | Chenequa Village Highway/Forestry Department Total | | | | | 28.62 |
| Chenequa | Chenequa Village Police Department | Motorola | H01UCD6PW1BN | 466ABE4839 | MTS-2000 Model I | 0.92 |
| Chenequa | Chenequa Village Police Department | Motorola | H01UCD6PW1BN | 466ABE4894 | MTS-2000 Model I | 1.37 |
| Chenequa | Chenequa Village Police Department | Motorola | H01UCD6PW1BN | 466ABE4903 | MTS-2000 Model I | 1.46 |
| Chenequa | Chenequa Village Police Department | Motorola | H01UCD6PW1BN | 466ABE4892 | MTS-2000 Model I | 2.03 |
| Chenequa | Chenequa Village Police Department | Motorola | H01UCD6PW1BN | 466ABE4899 | MTS-2000 Model I | 2.65 |
| Chenequa | Chenequa Village Police Department | Motorola | H01UCD6PW1BN | 466ABE4906 | MTS-2000 Model I | 3.07 |
| Chenequa | Chenequa Village Police Department | Motorola | H01UCD6PW1BN | 466ABE4901 | MTS-2000 Model I | 3.25 |
| Chenequa | Chenequa Village Police Department | Motorola | H01UCD6PW1BN | 466ABE4905 | MTS-2000 Model I | 5.49 |
| Chenequa | Chenequa Village Police Department | Motorola | H01UCD6PW1BN | 466ABE4897 | MTS-2000 Model I | 6.59 |
| Chenequa | Chenequa Village Police Department | Motorola | M01UGM6PW6AN | 722AWE1231 | MCS-2000 | 3.95 |
| Chenequa | Chenequa Village Police Department | Motorola | M01UGM6PW6BN | 722ABS1412 | MCS-2000 | 1.66 |
| Chenequa | Chenequa Village Police Department | Motorola | M01UGM6PW6BN | 722ABS1405 | MCS-2000 | 42.09 |
| Chenequa | Chenequa Village Police Department | Motorola | M01UGM6PW6BN | 722ABS1390 | MCS-2000 | 47.83 |
| Chenequa | Chenequa Village Police Department | Motorola | M10UGD6DC5BN | 760SBQ0081 | LCS-2000 w/scan | 9.80 |
| Chenequa | Chenequa Village Police Department | Motorola | M10UGD6DC5BN | 760SBQ0031 | LCS-2000 w/scan | 14.63 |
| | Chenequa Village Police Department Total | | | | | 146.79 |
| Chenequa Total | | | | | | 190.27 |
| Community Memorial Hospital | Community Memorial Hospital | Motorola | L04UJH9PW9AN | 761CEW0110 | Base, low power | 22.92 |
| | Community Memorial Hospital Total | | | | | 22.92 |
| Community Memorial Hospital Total | | | | | | 22.92 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2962 | MTS-2000 Model I FM | 0.36 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2939 | MTS-2000 Model I FM | 0.37 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2967 | MTS-2000 Model I FM | 0.38 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2966 | MTS-2000 Model I FM | 1.05 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2948 | MTS-2000 Model I FM | 1.28 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2958 | MTS-2000 Model I FM | 1.52 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2957 | MTS-2000 Model I FM | 1.53 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2959 | MTS-2000 Model I FM | 2.05 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2955 | MTS-2000 Model I FM | 2.15 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2941 | MTS-2000 Model I FM | 3.39 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2940 | MTS-2000 Model I FM | 3.59 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2950 | MTS-2000 Model I FM | 4.62 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2945 | MTS-2000 Model I FM | 5.18 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2952 | MTS-2000 Model I FM | 6.14 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2938 | MTS-2000 Model I FM | 6.79 |

| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2960 | MTS-2000 Model I FM | 17.31 |
|-----------------|--------------------------------------|----------|--------------|------------|----------------------|--------|
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2956 | MTS-2000 Model I FM | 24.03 |
| Delafield, City | Delafield City Fire Department | Motorola | H01UCD6PW1BN | 466ABS2936 | MTS-2000 Model I FM | 28.54 |
| Delafield, City | Delafield City Fire Department | Motorola | H46UCF9PW6AN | 205CFT2726 | XTS-2500 Model II FM | 29.18 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2527 | MCS-2000 | 0.75 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2803 | MCS-2000 | 1.19 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2347 | MCS-2000 | 1.47 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2785 | MCS-2000 | 2.85 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2790 | MCS-2000 | 3.70 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2506 | MCS-2000 | 6.37 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE3128 | MCS-2000 | 6.61 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2802 | MCS-2000 | 9.01 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2314 | MCS-2000 | 9.74 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2378 | MCS-2000 | 9.86 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE3127 | MCS-2000 | 14.60 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2312 | MCS-2000 | 17.05 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2396 | MCS-2000 | 31.75 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2793 | MCS-2000 | 49.18 |
| | Delafield City Fire Department Total | | | | | 303.61 |
| Delafield, City | Delafield City Police Department | Motorola | H01UCD6PW1BN | 466ABE4822 | MTS-2000 Model I | 1.45 |
| Delafield, City | Delafield City Police Department | Motorola | H01UCD6PW1BN | 466ABE4843 | MTS-2000 Model I | 5.68 |
| Delafield, City | Delafield City Police Department | Motorola | H01UCD6PW1BN | 466ABS2925 | MTS-2000 Model I | 9.17 |
| Delafield, City | Delafield City Police Department | Motorola | H01UCD6PW1BN | 466ABE4886 | MTS-2000 Model I | 10.79 |
| Delafield, City | Delafield City Police Department | Motorola | H01UCD6PW1BN | 466ABE4881 | MTS-2000 Model I | 10.95 |
| Delafield, City | Delafield City Police Department | Motorola | H01UCD6PW1BN | 466ABE4862 | MTS-2000 Model I | 12.03 |
| Delafield, City | Delafield City Police Department | Motorola | H01UCD6PW1BN | 466ABE4852 | MTS-2000 Model I | 13.74 |
| Delafield, City | Delafield City Police Department | Motorola | H01UCD6PW1BN | 466ABE4864 | MTS-2000 Model I | 14.00 |
| Delafield, City | Delafield City Police Department | Motorola | H01UCD6PW1BN | 466ABE4832 | MTS-2000 Model I | 16.22 |
| Delafield, City | Delafield City Police Department | Motorola | H01UCD6PW1BN | 466ABS2924 | MTS-2000 Model I | 17.87 |
| Delafield, City | Delafield City Police Department | Motorola | H01UCD6PW1BN | 466ABE4855 | MTS-2000 Model I | 19.91 |
| Delafield, City | Delafield City Police Department | Motorola | H01UCD6PW1BN | 466ABE4884 | MTS-2000 Model I | 22.24 |
| Delafield, City | Delafield City Police Department | Motorola | M01UJM6PW6AN | 722AYE2783 | MCS-2000 | 0.51 |
| Delafield, City | Delafield City Police Department | Motorola | M01UJM6PW6AN | 722AYE2784 | MCS-2000 | 3.27 |
| Delafield, City | Delafield City Police Department | Motorola | M01UJM6PW6AN | 722AYE2799 | MCS-2000 | 10.22 |
| Delafield, City | Delafield City Police Department | Motorola | M01UJM6PW6AN | 722AYE2389 | MCS-2000 | 25.89 |
| Delafield, City | Delafield City Police Department | Motorola | M01UJM6PW6AN | 722AYE2187 | MCS-2000 | 64.70 |
| Delafield, City | Delafield City Police Department | Motorola | M01UJM6PW6AN | 722AYE2504 | MCS-2000 | 95.81 |

| Delafield, City | Delafield City Police Department | Motorola | M01UJM6PW6AN | 722AYE3122 | MCS-2000 | 100.47 |
|-----------------------|--|----------|--------------|------------|-----------------------|--------|
| | Delafield City Police Department Total | | | | | 454.91 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE3124 | MCS-2000 | 0.38 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE2313 | MCS-2000 | 0.38 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE3125 | MCS-2000 | 0.41 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE2797 | MCS-2000 | 0.47 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE2794 | MCS-2000 | 1.09 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE3126 | MCS-2000 | 1.10 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE2796 | MCS-2000 | 1.96 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE3119 | MCS-2000 | 2.73 |
| | Delafield City Public Works Department Total | | | | | 8.52 |
| Delafield, City Total | | | | | | 767.03 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466CDY1358 | MTS-2000 Model II | 0.45 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466ABL3185 | MTS-2000 Model II | 0.69 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466ABL3148 | MTS-2000 Model II | 1.11 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466ABL3152 | MTS-2000 Model II | 1.11 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466ABL3179 | MTS-2000 Model II | 1.81 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466ABL3149 | MTS-2000 Model II | 1.94 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466ABL3168 | MTS-2000 Model II | 2.94 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466ABL3163 | MTS-2000 Model II | 2.99 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466CDY1357 | MTS-2000 Model II | 3.43 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466ABL3167 | MTS-2000 Model II | 3.49 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466ABL3150 | MTS-2000 Model II | 4.24 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466ABL3186 | MTS-2000 Model II | 12.17 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H01UCF6PW1BN | 466ABL3169 | MTS-2000 Model II | 14.14 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1390 | MCS-2000 Dual Control | 0.49 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1320 | MCS-2000 | 1.23 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1391 | MCS-2000 Dual Control | 1.67 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1386 | MCS-2000 Dual Control | 1.85 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1382 | MCS-2000 | 10.43 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1381 | MCS-2000 | 11.29 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1387 | MCS-2000 Dual Control | 18.04 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M01UJL6PW4AN | 722AXE0997 | MCS-2000 | 3.71 |
| | Delafield Town Fire Department Total | | | | | 99.20 |
| Delafield, Town Total | | | | | | 99.20 |
| Dousman | Dousman Police Department | Motorola | H01UCD6PW1BN | 466ABE2328 | MTS-2000 Model I | 0.78 |
| Dousman | Dousman Police Department | Motorola | H01UCD6PW1BN | 466ABE2300 | MTS-2000 Model I | 1.51 |

| Dousman | Dousman Police Department | Motorola | H01UCD6PW1BN | 466ABE4921 | MTS-2000 Model I | 2.61 |
|-------------------------|---------------------------------|----------|--------------|------------|-------------------|-------|
| Dousman | Dousman Police Department | Motorola | H01UCD6PW1BN | 466ABE1383 | MTS-2000 Model I | 5.49 |
| Dousman | Dousman Police Department | Motorola | H01UCF6PW1BN | 466ABW4235 | MTS-2000 Model II | 1.64 |
| Dousman | Dousman Police Department | Motorola | H18UCF9PW6AN | 721CEA4980 | XTS-5000 Model II | 0.83 |
| Dousman | Dousman Police Department | Motorola | H18UCF9PW6AN | 721CEA4982 | XTS-5000 Model II | 15.13 |
| Dousman | Dousman Police Department | Motorola | M01UGM6PW6BN | 722ABS1449 | MCS-2000 | 15.01 |
| Dousman | Dousman Police Department | Motorola | M01UGM6PW6BN | 722ABS1415 | MCS-2000 | 39.63 |
| | Dousman Police Department Total | | | | | 82.63 |
| Dousman Total | | | | | | 82.63 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466CEC0419 | MTS-2000 Model II | 0.35 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3426 | MTS-2000 Model II | 0.67 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3418 | MTS-2000 Model II | 0.74 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3425 | MTS-2000 Model II | 0.77 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3434 | MTS-2000 Model II | 0.86 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABE1909 | MTS-2000 Model II | 0.87 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3420 | MTS-2000 Model II | 1.19 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3415 | MTS-2000 Model II | 1.70 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3436 | MTS-2000 Model II | 2.09 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3446 | MTS-2000 Model II | 2.49 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3454 | MTS-2000 Model II | 3.85 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3432 | MTS-2000 Model II | 5.49 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3444 | MTS-2000 Model II | 7.02 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3447 | MTS-2000 Model II | 7.69 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3429 | MTS-2000 Model II | 11.95 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3445 | MTS-2000 Model II | 12.69 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H01UCF6PW1BN | 466ABS3453 | MTS-2000 Model II | 17.11 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1379 | MCS-2000 | 0.40 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1364 | MCS-2000 | 0.41 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1408 | MCS-2000 | 0.68 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722CEC0594 | MCS-2000 | 0.82 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1395 | MCS-2000 | 1.06 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1404 | MCS-2000 | 1.95 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1397 | MCS-2000 | 2.10 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1357 | MCS-2000 | 2.67 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1409 | MCS-2000 | 5.63 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1371 | MCS-2000 | 8.87 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1410 | MCS-2000 | 19.86 |

| | Dousman Fire Department Total | | | | | 121.99 |
|-------------------------------|--|----------|--------------|------------|----------------------|--------|
| Dousman Fire Department Total | | | | | | 121.99 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6AN | 205cfz1918 | XTS-2500 Model II FM | 0.71 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6AN | 205cfz1919 | XTS-2500 Model II FM | 0.83 |
| | Eagle Fire District Total | | | | | 1.54 |
| Eagle Fire District Total | | | | | | 1.54 |
| Eagle, Village | Eagle Village Police Department | Motorola | D35KGA5JC5AK | 604AUE0123 | Spectra | 12.15 |
| Eagle, Village | Eagle Village Police Department | Motorola | H01UCD6PW1BN | 466ABA1021 | MTS-2000 Model I | 4.75 |
| Eagle, Village | Eagle Village Police Department | Motorola | H01UCD6PW1BN | 466ABA1019 | MTS-2000 Model I | 4.84 |
| Eagle, Village | Eagle Village Police Department | Motorola | H01UCD6PW1BN | 466ABA1020 | MTS-2000 Model I | 14.65 |
| Eagle, Village | Eagle Village Police Department | Motorola | H01UCD6PW1BN | 466ABA1022 | MTS-2000 Model I | 14.81 |
| Eagle, Village | Eagle Village Police Department | Motorola | M01UGM6PW6AN | 722AWE1640 | MCS-2000 | 62.35 |
| | Eagle Village Police Department Total | | | | | 113.56 |
| Eagle, Village Total | | | | | | 113.56 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H01UCF6PW1BN | 466ABS3369 | MTS-2000 Model II | 0.39 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H01UCF6PW1BN | 466ABS3371 | MTS-2000 Model II | 1.51 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | M01UGM6PW6BN | 722ABS1428 | MCS-2000 | 0.75 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | M01UGM6PW6BN | 722ABS1368 | MCS-2000 | 1.05 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | M01UGM6PW6BN | 722ABS1437 | MCS-2000 | 1.27 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | M01UGM6PW6BN | 722ABS1432 | MCS-2000 | 12.17 |
| | Elm Grove Emergency Medical Services Total | | | | | 17.16 |
| Elm Grove | Elm Grove Fire Department | Motorola | H01UCF6PW1BN | 466ABS3463 | MTS-2000 Model II FM | 0.43 |
| Elm Grove | Elm Grove Fire Department | Motorola | H01UCF6PW1BN | 466ABS3458 | MTS-2000 Model II FM | 0.68 |
| Elm Grove | Elm Grove Fire Department | Motorola | H01UCF6PW1BN | 466ABS3457 | MTS-2000 Model II FM | 1.16 |
| Elm Grove | Elm Grove Fire Department | Motorola | H01UCF6PW1BN | 466ABS3464 | MTS-2000 Model II FM | 1.29 |
| Elm Grove | Elm Grove Fire Department | Motorola | H01UCF6PW1BN | 466ABS3472 | MTS-2000 Model II FM | 1.49 |
| Elm Grove | Elm Grove Fire Department | Motorola | H01UCF6PW1BN | 466ABS3470 | MTS-2000 Model II FM | 1.97 |
| Elm Grove | Elm Grove Fire Department | Motorola | H01UCF6PW1BN | 466ABS3468 | MTS-2000 Model II FM | 2.79 |
| Elm Grove | Elm Grove Fire Department | Motorola | H01UCF6PW1BN | 466ABS3476 | MTS-2000 Model II FM | 3.42 |
| Elm Grove | Elm Grove Fire Department | Motorola | H01UCF6PW1BN | 466ABS3475 | MTS-2000 Model II FM | 3.75 |
| Elm Grove | Elm Grove Fire Department | Motorola | H01UCF6PW1BN | 466ABS3469 | MTS-2000 Model II FM | 4.18 |
| Elm Grove | Elm Grove Fire Department | Motorola | H01UCF6PW1BN | 466ABS3471 | MTS-2000 Model II FM | 9.64 |
| Elm Grove | Elm Grove Fire Department | Motorola | M01UGM6PW6BN | 722ABS1377 | MCS-2000 | 1.77 |
| Elm Grove | Elm Grove Fire Department | Motorola | M01UGM6PW6BN | 722ABS1430 | MCS-2000 | 1.80 |
| Elm Grove | Elm Grove Fire Department | Motorola | M01UGM6PW6BN | 722ABS1423 | MCS-2000 | 2.38 |
| Elm Grove | Elm Grove Fire Department | Motorola | M01UGM6PW6BN | 722ABS1426 | MCS-2000 | 3.02 |
| Elm Grove | Elm Grove Fire Department | Motorola | M01UGM6PW6BN | 722ABS1367 | MCS-2000 | 5.68 |

| | Elm Grove Fire Department Total | | | | | 45.44 |
|-----------|-----------------------------------|----------|--------------|------------|-----------------------|----------|
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3405 | MTS-2000 Model II | 0.77 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3382 | MTS-2000 Model II | 1.68 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466CDY1171 | MTS-2000 Model II | 1.80 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3387 | MTS-2000 Model II | 4.19 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3394 | MTS-2000 Model II | 6.16 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3412 | MTS-2000 Model II | 12.35 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3404 | MTS-2000 Model II | 14.29 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3398 | MTS-2000 Model II | 15.91 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3384 | MTS-2000 Model II | 17.87 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3385 | MTS-2000 Model II | 18.11 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3378 | MTS-2000 Model II | 20.44 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3411 | MTS-2000 Model II | 20.79 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3389 | MTS-2000 Model II | 21.21 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3410 | MTS-2000 Model II | 22.21 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3388 | MTS-2000 Model II | 25.90 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3403 | MTS-2000 Model II | 29.15 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3395 | MTS-2000 Model II | 31.65 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3393 | MTS-2000 Model II | 35.76 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGL6PW4BN | 722ABE3129 | MCS-2000 Control Base | 2.16 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGL6PW4BN | 722ABE3127 | MCS-2000 Control Base | 27.70 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGL6PW4BN | 722ABE3130 | MCS-2000 Control Base | 531.99 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGM6PW6BN | 722ABS1358 | MCS-2000 | 1.58 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGM6PW6BN | 722ABS1366 | MCS-2000 | 4.05 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGM6PW6BN | 722ABS1370 | MCS-2000 | 16.80 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGM6PW6BN | 722ABS1361 | MCS-2000 | 112.41 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGM6PW6BN | 722ABS1355 | MCS-2000 | 132.11 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGM6PW6BN | 722ABS1362 | MCS-2000 | 204.77 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGM6PW6BN | 722ABS1419 | MCS-2000 | 247.73 |
| | Elm Grove Police Department Total | | | | | 1,581.57 |
| Elm Grove | Elm Grove Public Works Department | Motorola | H01UCF6PW1BN | 466ABS3465 | MTS-2000 Model II FM | 7.51 |
| Elm Grove | Elm Grove Public Works Department | Motorola | H10UCH6DC5BN | 678SBC1121 | LTS-2000 w/scan FM | 1.69 |
| Elm Grove | Elm Grove Public Works Department | Motorola | H10UCH6DC5BN | 678SBC1170 | LTS-2000 w/scan FM | 2.21 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M01UGM6PW6BN | 722ABS1398 | MCS-2000 | 4.25 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M01UGM6PW6BN | 722ABS1374 | MCS-2000 | 8.15 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0935 | LCS-2000 w/scan | 0.43 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M10UGD6DC5BN | 760SAW3367 | LCS-2000 w/scan | 0.70 |

| Elm Grove | Elm Grove Public Works Department | Motorola | M10UGD6DC5BN | 760SAW3368 | LCS-2000 w/scan | 0.91 |
|----------------------------------|---|----------|--------------|------------|-------------------|----------|
| Elm Grove | Elm Grove Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0974 | LCS-2000 w/scan | 1.02 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0920 | LCS-2000 w/scan | 1.21 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M10UGD6DC5BN | 760SAYER37 | LCS-2000 w/scan | 1.37 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M10UGD6DC5BN | 760SAYER34 | LCS-2000 w/scan | 2.01 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M10UGD6DC5BN | 760SAYER10 | LCS-2000 w/scan | 3.44 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M10UGD6DC5BN | 760SAYER36 | LCS-2000 w/scan | 3.63 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0982 | LCS-2000 w/scan | 4.09 |
| | Elm Grove Public Works Department Total | | | | | 42.59 |
| Elm Grove Total | · | | | | | 1,686.76 |
| Elmbrook Memorial Hospital | Elmbrook Memorial Hospital | Motorola | L04UJH9PW9AN | 761ACS0143 | Base, low power | 0.45 |
| · | Elmbrook Memorial Hospital Total | | | | · | 0.45 |
| Elmbrook Memorial Hospital Total | · | | | | | 0.45 |
| Hales Corners, | Hales Corners Fire Department | Motorola | H46UCF9PW6AN | 205CGF2340 | XTS-2500 Model II | 1.10 |
| | Hales Corners Fire Department Total | | | | | 1.10 |
| Hales Corners, Total | - | | | | | 1.10 |
| Hartland | Hartland Administration | Motorola | M10UGD6DC5BN | 760SAYES87 | LCS-2000 w/scan | 3.94 |
| Hartland | Hartland Administration | Motorola | M10UGD6DC5BN | 760SAYFG84 | LCS-2000 w/o scan | 3.97 |
| | Hartland Administration Total | | | | | 7.91 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3328 | MTS-2000 Model I | 0.73 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3329 | MTS-2000 Model I | 1.87 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3333 | MTS-2000 Model I | 2.51 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3334 | MTS-2000 Model I | 2.60 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3320 | MTS-2000 Model I | 2.61 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3327 | MTS-2000 Model I | 3.69 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3326 | MTS-2000 Model I | 5.66 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3325 | MTS-2000 Model I | 12.51 |
| Hartland | Hartland Fire Department | Motorola | H10UCH6DC5BN | 678SBE1597 | LTS-2000 w/scan | 0.36 |
| Hartland | Hartland Fire Department | Motorola | H10UCH6DC5BN | 678SBG0156 | LTS-2000 w/scan | 3.87 |
| Hartland | Hartland Fire Department | Motorola | H10UCH6DC5BN | 678SBG0187 | LTS-2000 w/scan | 9.58 |
| Hartland | Hartland Fire Department | Motorola | H10UCH6DC5BN | 678SBG0066 | LTS-2000 w/scan | 13.83 |
| Hartland | Hartland Fire Department | Motorola | H10UCH6DC5BN | 678SBG0093 | LTS-2000 w/scan | 15.19 |
| Hartland | Hartland Fire Department | Motorola | H10UCH6DC5BN | 678SBE0838 | LTS-2000 w/o scan | 25.85 |
| Hartland | Hartland Fire Department | Motorola | M01UGM6PW6BN | 722ABL1325 | MCS-2000 | 0.43 |
| Hartland | Hartland Fire Department | Motorola | M10UGD6DC5BN | 760SAS4204 | LCS-2000 w/scan | 0.38 |
| Hartland | Hartland Fire Department | Motorola | M10UGD6DC5BN | 760SAS4202 | LCS-2000 w/scan | 0.42 |
| Hartland | Hartland Fire Department | Motorola | M10UGD6DC5BN | 760SAS4528 | LCS-2000 w/scan | 0.84 |

| Hartland | Hartland Fire Department | Motorola | M10UGD6DC5BN | 760SAS4478 | LCS-2000 w/scan | 1.50 |
|----------|----------------------------------|----------|--------------|------------|-------------------|--------|
| Hartland | Hartland Fire Department | Motorola | M10UGD6DC5BN | 760SAS4548 | LCS-2000 w/scan | 2.61 |
| Hartland | Hartland Fire Department | Motorola | M10UGD6DC5BN | 760SAS4502 | LCS-2000 w/scan | 3.97 |
| Hartland | Hartland Fire Department | Motorola | M10UGD6DC5BN | 760SAYES93 | LCS-2000 w/scan | 7.53 |
| Hartland | Hartland Fire Department | Motorola | M10UGD6DC5BN | 760SAS0330 | LCS-2000 w/scan | 27.07 |
| | Hartland Fire Department Total | | | | | 145.61 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0160 | LTS-2000 w/scan | 0.71 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0028 | LTS-2000 w/scan | 0.77 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBE1595 | LTS-2000 w/scan | 0.85 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0195 | LTS-2000 w/scan | 1.02 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0065 | LTS-2000 w/scan | 2.69 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0029 | LTS-2000 w/scan | 3.79 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0366 | LTS-2000 w/scan | 4.05 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0405 | LTS-2000 w/scan | 5.43 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0073 | LTS-2000 w/scan | 5.55 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0410 | LTS-2000 w/scan | 7.75 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0161 | LTS-2000 w/scan | 10.18 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0166 | LTS-2000 w/scan | 11.20 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0064 | LTS-2000 w/scan | 12.65 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0151 | LTS-2000 w/scan | 13.89 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0395 | LTS-2000 w/scan | 15.62 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0184 | LTS-2000 w/scan | 16.44 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0363 | LTS-2000 w/scan | 19.02 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0164 | LTS-2000 w/scan | 20.23 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0204 | LTS-2000 w/scan | 33.77 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0196 | LTS-2000 w/scan | 37.55 |
| Hartland | Hartland Police Department | Motorola | H10UCH6DC5BN | 678SBG0220 | LTS-2000 w/scan | 43.95 |
| Hartland | Hartland Police Department | Motorola | M10UGD6DC5BN | 760SAS4205 | LCS-2000 w/scan | 5.81 |
| Hartland | Hartland Police Department | Motorola | M10UGD6DC5BN | 760SAS4209 | LCS-2000 w/scan | 18.35 |
| Hartland | Hartland Police Department | Motorola | M10UGD6DC5BN | 760SAS4206 | LCS-2000 w/scan | 91.55 |
| Hartland | Hartland Police Department | Motorola | M10UGD6DC5BN | 760SAS4477 | LCS-2000 w/scan | 139.88 |
| Hartland | Hartland Police Department | Motorola | M10UGD6DC5BN | 760SAS4194 | LCS-2000 w/scan | 144.21 |
| | Hartland Police Department Total | | | | | 666.90 |
| Hartland | Hartland Public Works Department | Motorola | H10UCH6DC5BN | 678SBE0961 | LTS-2000 w/o scan | 2.13 |
| Hartland | Hartland Public Works Department | Motorola | H10UCH6DC5BN | 678SBG0159 | LTS-2000 w/scan | 2.53 |
| Hartland | Hartland Public Works Department | Motorola | H10UCH6DC5BN | 678SBE0968 | LTS-2000 w/o scan | 6.06 |
| Hartland | Hartland Public Works Department | Motorola | H10UCH6DC5BN | 678SBE0967 | LTS-2000 w/o scan | 7.45 |

| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SBE0462 | LCS-2000 w/o scan | 0.35 |
|--------------------|--|----------|--------------|------------|--------------------|--------|
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SBE0456 | LCS-2000 w/o scan | 0.69 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SAS0349 | LCS-2000 w/scan | 1.13 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SAS4553 | LCS-2000 w/scan | 1.17 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SBE0548 | LCS-2000 w/o scan | 1.19 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SBE0468 | LCS-2000 w/o scan | 1.34 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SBG0113 | LCS-2000 w/o scan | 1.35 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SBA0416 | LCS-2000 w/o scan | 1.59 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SBE0452 | LCS-2000 w/o scan | 1.77 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SBE0485 | LCS-2000 w/o scan | 2.31 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SBE0451 | LCS-2000 w/o scan | 2.53 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SBE0551 | LCS-2000 w/o scan | 3.12 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SAS4199 | LCS-2000 w/scan | 3.52 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SAS4472 | LCS-2000 w/scan | 3.65 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SAS0345 | LCS-2000 w/scan | 5.49 |
| Hartland | Hartland Public Works Department | Motorola | M10UGD6DC5BN | 760SBE0312 | LCS-2000 w/o scan | 6.27 |
| | Hartland Public Works Department Total | | | | | 55.63 |
| Hartland Total | | | | | | 876.05 |
| Lac La Belle | Lac La Belle Police Department | Motorola | H01UCF6PW1BN | 466ABE1911 | MTS-2000 Model II | 3.63 |
| Lac La Belle | Lac La Belle Police Department | Motorola | H01UCF6PW1BN | 466ABE1885 | MTS-2000 Model II | 6.33 |
| Lac La Belle | Lac La Belle Police Department | Motorola | M01UGM6PW6BN | 722ABE1313 | MCS-2000 | 14.93 |
| | Lac La Belle Police Department Total | | | | | 24.89 |
| Lac La Belle Total | | | | | | 24.89 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCF6PW1BN | 466ABE1878 | MTS-2000 Model II | 1.44 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCF6PW1BN | 466ABE1915 | MTS-2000 Model II | 2.89 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCF6PW1BN | 466ABE1896 | MTS-2000 Model II | 17.38 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCF6PW1BN | 466ABE1900 | MTS-2000 Model II | 25.83 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCH6PW1BN | 466ABC0140 | MTS-2000 Model III | 0.69 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCH6PW1BN | 466AAL4035 | MTS-2000 Model III | 0.85 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCH6PW1BN | 466ABC0139 | MTS-2000 Model III | 1.21 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCH6PW1BN | 466AAL4031 | MTS-2000 Model III | 1.84 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCH6PW1BN | 466AAL4026 | MTS-2000 Model III | 1.87 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCH6PW1BN | 466ABC0154 | MTS-2000 Model III | 3.36 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCH6PW1BN | 466ABC0142 | MTS-2000 Model III | 4.37 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCH6PW1BN | 466AAL4027 | MTS-2000 Model III | 4.63 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCH6PW1BN | 466AAL4015 | MTS-2000 Model III | 4.84 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCH6PW1BN | 466AAL4030 | MTS-2000 Model III | 6.81 |

| Lisbon | Lisbon Fire Department | Motorola | H10UCH6DC5BN | 678SBC0694 | LTS-2000 w/scan | 1.05 |
|-----------------|---------------------------------|----------|--------------|------------|----------------------|--------|
| Lisbon | Lisbon Fire Department | Motorola | H10UCH6DC5BN | 678SBC1118 | LTS-2000 w/scan | 1.13 |
| Lisbon | Lisbon Fire Department | Motorola | H10UCH6DC5BN | 678SBC1064 | LTS-2000 w/scan | 1.39 |
| Lisbon | Lisbon Fire Department | Motorola | H10UCH6DC5BN | 678SBC1105 | LTS-2000 w/scan | 1.78 |
| Lisbon | Lisbon Fire Department | Motorola | H10UCH6DC5BN | 678SBC1107 | LTS-2000 w/scan | 4.87 |
| Lisbon | Lisbon Fire Department | Motorola | H10UCH6DC5BN | 678SBC1092 | LTS-2000 w/scan | 10.65 |
| Lisbon | Lisbon Fire Department | Motorola | M01UGM6PW6BN | 722ABS1354 | MCS-2000 | 10.97 |
| Lisbon | Lisbon Fire Department | Motorola | M01UGM6PW6BN | 722ABS1372 | MCS-2000 | 22.02 |
| Lisbon | Lisbon Fire Department | Motorola | M01UJM6PW6AN | 722AYE2110 | MCS-2000 | 4.47 |
| Lisbon | Lisbon Fire Department | Motorola | M10UGD6DC5BN | 760SAW3371 | LCS-2000 w/scan | 0.41 |
| Lisbon | Lisbon Fire Department | Motorola | M10UGD6DC5BN | 760SAW3365 | LCS-2000 w/scan | 0.78 |
| Lisbon | Lisbon Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0057 | LCS-2000 w/scan | 1.05 |
| Lisbon | Lisbon Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0054 | LCS-2000 w/scan | 1.45 |
| Lisbon | Lisbon Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0047 | LCS-2000 w/scan | 1.74 |
| Lisbon | Lisbon Fire Department | Motorola | M10UGD6DC5BN | 760SAW0957 | LCS-2000 w/scan | 1.75 |
| Lisbon | Lisbon Fire Department | Motorola | M10UGD6DC5BN | 760SAW3382 | LCS-2000 w/scan | 2.86 |
| | Lisbon Fire Department Total | | | | | 146.37 |
| Lisbon | Lisbon Police Department | Motorola | H01UCD6PW1BN | 466ABE5014 | MTS-2000 Model I | 1.54 |
| Lisbon | Lisbon Police Department | Motorola | H01UCD6PW1BN | 466ABE4846 | MTS-2000 Model I | 2.87 |
| Lisbon | Lisbon Police Department | Motorola | H01UCD6PW1BN | 466ABE5001 | MTS-2000 Model I | 4.41 |
| Lisbon | Lisbon Police Department | Motorola | H01UCD6PW1BN | 466ABE5019 | MTS-2000 Model I | 4.83 |
| Lisbon | Lisbon Police Department | Motorola | H01UCD6PW1BN | 466ABS3060 | MTS-2000 Model I | 16.11 |
| Lisbon | Lisbon Police Department | Motorola | H01UCD6PW1BN | 466ABE4885 | MTS-2000 Model I | 17.31 |
| Lisbon | Lisbon Police Department | Motorola | H01UCD6PW1BN | 466ABE4845 | MTS-2000 Model I | 20.67 |
| Lisbon | Lisbon Police Department | Motorola | M01UGM6PW6BN | 722ABS1418 | MCS-2000 | 32.26 |
| Lisbon | Lisbon Police Department | Motorola | M01UGM6PW6BN | 722ABS1439 | MCS-2000 | 65.18 |
| Lisbon | Lisbon Police Department | Motorola | M01UGM6PW6BN | 722ABS1414 | MCS-2000 | 113.75 |
| | Lisbon Police Department Total | | | | | 278.93 |
| Lisbon Total | | | | | | 425.30 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFTB004 | XTS-2500 Model II FM | 0.36 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1728 | XTS-5000 Model II FM | 0.39 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFTB007 | XTS-2500 Model II FM | 0.43 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721cgb2405 | XTS-5000 Model II FM | 0.46 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721cgb2406 | XTS-5000 Model II FM | 0.49 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721cgb2401 | XTS-5000 Model II FM | 0.77 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721cgb2400 | XTS-5000 Model II FM | 0.86 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721cgb2403 | XTS-5000 Model II FM | 0.87 |

| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1737 | XTS-5000 Model II FM | 1.17 |
|-----------------|---------------------------------|----------|--------------|------------|----------------------|-------|
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721cgb2404 | XTS-5000 Model II FM | 1.22 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFTB005 | XTS-2500 Model II FM | 1.23 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1731 | XTS-5000 Model II FM | 1.27 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFM2685 | XTS-5000 Model II FM | 1.29 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1730 | XTS-5000 Model II FM | 1.70 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1739 | XTS-5000 Model II FM | 2.29 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1740 | XTS-5000 Model II FM | 2.31 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFM2684 | XTS-5000 Model II FM | 2.69 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1733 | XTS-5000 Model II FM | 2.73 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1732 | XTS-5000 Model II FM | 2.80 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | h18UCF9PW6AN | 721CFM2683 | XTS-5000 Model II FM | 3.79 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFM2686 | XTS-5000 Model II FM | 4.35 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1743 | XTS-5000 Model II FM | 5.39 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1734 | XTS-5000 Model II FM | 5.44 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1726 | XTS-5000 Model II FM | 6.99 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1736 | XTS-5000 Model II FM | 7.12 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1729 | XTS-5000 Model II FM | 9.27 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFM2687 | XTS-5000 Model II FM | 11.32 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1724 | XTS-5000 Model II FM | 12.53 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1741 | XTS-5000 Model II FM | 16.77 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1742 | XTS-5000 Model II FM | 19.19 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AM | 500CGF0765 | XTL-5000 Mobile | 4.95 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFM2837 | XTL-5000 Mobile | 0.37 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0392 | XTL-5000 Mobile | 0.38 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0399 | XTL-5000 Mobile | 0.43 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0400 | XTL-5000 Mobile | 0.84 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0395 | XTL-5000 Mobile | 0.88 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFX1007 | XTL-5000 Mobile | 1.25 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0606 | XTL-5000 Mobile | 1.49 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0397 | XTL-5000 Mobile | 1.59 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0403 | XTL-5000 Mobile | 2.27 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0401 | XTL-5000 Mobile | 3.17 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFM2835 | XTL-5000 Mobile | 3.27 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0393 | XTL-5000 Mobile | 4.87 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFM2838 | XTL-5000 Mobile | 4.88 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0398 | XTL-5000 Mobile | 19.11 |

| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0604 | XTL-5000 Mobile | 29.35 |
|------------------------------|---------------------------------------|----------|--------------|------------|-------------------|--------|
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0605 | XTL-5000 Mobile | 33.70 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0394 | XTL-5000 Mobile | 58.47 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0603 | XTL-5000 Mobile | 81.48 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFM2836 | XTL-5000 Mobile | 211.53 |
| | Menomonee Falls Fire Department Total | | | | | 591.74 |
| Menomonee Falls Total | | | | | | 591.74 |
| Merton Fire Department | Merton Fire Department | Motorola | H01UCH6DC5BN | 678SEW0524 | LTS-2000 w/scan | 12.87 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBC1164 | LTS-2000 w/scan | 0.35 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBC1144 | LTS-2000 w/scan | 0.75 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBC1120 | LTS-2000 w/scan | 1.13 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBC1174 | LTS-2000 w/scan | 1.29 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBC1148 | LTS-2000 w/scan | 1.41 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBE0120 | LTS-2000 w/scan | 1.49 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBC1119 | LTS-2000 w/scan | 1.53 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBE0076 | LTS-2000 w/scan | 1.55 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBC1117 | LTS-2000 w/scan | 1.61 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBE0140 | LTS-2000 w/scan | 2.03 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBC0948 | LTS-2000 w/scan | 2.68 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBC1136 | LTS-2000 w/scan | 3.93 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBC1114 | LTS-2000 w/scan | 5.07 |
| Merton Fire Department | Merton Fire Department | Motorola | H10UCH6DC5BN | 678SBC0864 | LTS-2000 w/scan | 8.66 |
| Merton Fire Department | Merton Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0945 | LCS-2000 w/scan | 0.39 |
| Merton Fire Department | Merton Fire Department | Motorola | m10ugd6dc5bn | 760sbs0312 | LCS-2000 w/scan | 0.43 |
| Merton Fire Department | Merton Fire Department | Motorola | m10ugd6dc5bn | 760sbs0283 | LCS-2000 w/scan | 0.90 |
| Merton Fire Department | Merton Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0944 | LCS-2000 w/scan | 1.48 |
| Merton Fire Department | Merton Fire Department | Motorola | M10UGD6DC5BN | 760SCN0267 | LCS-2000 w/scan | 1.90 |
| Merton Fire Department | Merton Fire Department | Motorola | m10ugd6dc5bn | 760scl0547 | LCS-2000 w/scan | 7.98 |
| | Merton Fire Department Total | | | | | 59.44 |
| Merton Fire Department Total | | | | | | 59.44 |
| Merton, Town | Merton Town Highway Department | Motorola | M10UGD6DC5BN | 760SBN0037 | LCS-2000 w/o scan | 0.35 |
| Merton, Town | Merton Town Highway Department | Motorola | M10UGD6DC5BN | 760SBN0072 | LCS-2000 w/o scan | 0.42 |
| Merton, Town | Merton Town Highway Department | Motorola | M10UGD6DC5BN | 760SBN0097 | LCS-2000 w/o scan | 0.83 |
| Merton, Town | Merton Town Highway Department | Motorola | M10UGD6DC5BN | 760SBN0118 | LCS-2000 w/o scan | 1.02 |
| Merton, Town | Merton Town Highway Department | Motorola | M28URS9PW1AN | 775TGA1901 | XTL-1500 Mobile | 1.23 |
| | Merton Town Highway Department Total | | | | | 3.85 |
| Merton, Town | Merton Town Lake Patrol | Motorola | H01UCF6PW1BN | 466ABS3455 | MTS-2000 Model II | 0.35 |

| Merton, Town | Merton Town Lake Patrol | Motorola | H01UCF6PW1BN | 466ABS3370 | MTS-2000 Model II | 0.39 |
|---------------------------|--|----------|--------------|------------|----------------------|-------|
| Merton, Town | Merton Town Lake Patrol | Motorola | M01UGM6PW6BN | 722ABS1443 | MCS-2000 | 3.74 |
| | Merton Town Lake Patrol Total | | | | | 4.49 |
| Merton, Town Total | | | | | | 8.34 |
| filwaukee County | Milwaukee County Flight for Life | Motorola | H01UCF6PW1BN | 466ABW3018 | MTS-2000 Model II | 5.90 |
| | Milwaukee County Flight for Life Total | | | | | 5.90 |
| Milwaukee County Total | | | | | | 5.90 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4296 | XTS-2500 Model II FM | 0.36 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4276 | XTS-2500 Model II FM | 0.37 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4267 | XTS-2500 Model II FM | 0.75 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4274 | XTS-2500 Model II FM | 1.03 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4307 | XTS-2500 Model II FM | 1.37 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4291 | XTS-2500 Model II FM | 1.57 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4278 | XTS-2500 Model II FM | 1.85 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4308 | XTS-2500 Model II FM | 2.07 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4303 | XTS-2500 Model II FM | 2.51 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4280 | XTS-2500 Model II FM | 2.73 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4310 | XTS-2500 Model II FM | 3.18 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4295 | XTS-2500 Model II FM | 3.27 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4272 | XTS-2500 Model II FM | 3.61 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4299 | XTS-2500 Model II FM | 3.79 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4304 | XTS-2500 Model II FM | 3.93 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4271 | XTS-2500 Model II FM | 4.39 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4300 | XTS-2500 Model II FM | 7.91 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M20URS9PW1AN | 500CGF1128 | XTL-5000 Mobile | 4.89 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M20URS9PW1AN | 500CGF1127 | XTL-5000 Mobile | 17.52 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M20URS9PW1AN | 500CGF1129 | XTL-5000 Mobile | 19.03 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0494 | XTL-2500 Mobile | 0.51 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0488 | XTL-2500 Mobile | 0.52 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0492 | XTL-2500 Mobile | 1.23 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0489 | XTL-2500 Mobile | 1.45 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0485 | XTL-2500 Mobile | 2.42 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0491 | XTL-2500 Mobile | 3.03 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0490 | XTL-2500 Mobile | 3.82 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0495 | XTL-2500 Mobile | 6.12 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0498 | XTL-2500 Mobile | 9.21 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0496 | XTL-2500 Mobile | 12.37 |

| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0497 | XTL-2500 Mobile | 36.13 |
|---------------------------------|---------------------------------|----------|--------------|------------|---------------------|--------|
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0486 | XTL-2500 Mobile | 43.09 |
| | Mukwonago Fire Department Total | | | | | 206.04 |
| Mukwonago Fire Department Total | | | | | | 206.04 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1783 | MTS-2000 Model I FM | 0.36 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1796 | MTS-2000 Model I FM | 0.43 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1800 | MTS-2000 Model I FM | 0.71 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1786 | MTS-2000 Model I FM | 0.73 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1779 | MTS-2000 Model I FM | 0.83 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0919 | MTS-2000 Model I | 0.99 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1776 | MTS-2000 Model I FM | 1.12 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1787 | MTS-2000 Model I FM | 1.15 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1774 | MTS-2000 Model I FM | 1.83 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0943 | MTS-2000 Model I | 2.55 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1784 | MTS-2000 Model I FM | 2.55 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0927 | MTS-2000 Model I | 2.93 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1780 | MTS-2000 Model I FM | 3.24 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1789 | MTS-2000 Model I FM | 3.29 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0946 | MTS-2000 Model I | 11.06 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0917 | MTS-2000 Model I | 13.06 |
| Muskego | Muskego Fire Department | Motorola | M01UGM6PW6BN | 722ABE1334 | MCS-2000 | 0.39 |
| Muskego | Muskego Fire Department | Motorola | M01UGM6PW6BN | 722ABE1345 | MCS-2000 | 0.49 |
| Muskego | Muskego Fire Department | Motorola | M01UGM6PW6BN | 722ABE1357 | MCS-2000 | 0.53 |
| Muskego | Muskego Fire Department | Motorola | M01UGM6PW6BN | 722ABE1342 | MCS-2000 | 2.42 |
| Muskego | Muskego Fire Department | Motorola | M01UGM6PW6BN | 722ABE1346 | MCS-2000 | 2.82 |
| Muskego | Muskego Fire Department | Motorola | M01UGM6PW6BN | 722ABE1325 | MCS-2000 | 3.09 |
| Muskego | Muskego Fire Department | Motorola | M01UGM6PW6BN | 722ABE1367 | MCS-2000 | 5.69 |
| | Muskego Fire Department Total | | | | | 62.25 |
| Muskego | Muskego Park Department | Motorola | H10UCH6DC5BN | 678SAQ2743 | LTS-2000 w/scan | 3.70 |
| Muskego | Muskego Park Department | Motorola | H10UCH6DC5BN | 678SAQ2744 | LTS-2000 w/scan | 3.91 |
| Muskego | Muskego Park Department | Motorola | H10UCH6DC5BN | 678SAQ2771 | LTS-2000 w/scan | 9.38 |
| Muskego | Muskego Park Department | Motorola | H10UCH6DC5BN | 678SAQ2748 | LTS-2000 w/scan | 10.45 |
| Muskego | Muskego Park Department | Motorola | H10UCH6DC5BN | 678SAQ2746 | LTS-2000 w/scan | 14.90 |
| Muskego | Muskego Park Department | Motorola | H10UCH6DC5BN | 678SAQ2772 | LTS-2000 w/scan | 22.89 |
| Muskego | Muskego Park Department | Motorola | M10UGD6DC5BN | 760SAU0875 | LCS-2000 w/scan | 0.77 |
| Muskego | Muskego Park Department | Motorola | M10UGD6DC5BN | 760SAU0879 | LCS-2000 w/scan | 1.39 |
| Muskego | Muskego Park Department | Motorola | M10UGD6DC5BN | 760SAW0320 | LCS-2000 w/scan | 1.52 |

| Muskego | Muskego Park Department | Motorola | M10UGD6DC5BN | 760SBU0268 | LCS-2000 w/scan | 2.97 |
|---------|-------------------------------|----------|--------------|------------|------------------|-------|
| Muskego | Muskego Park Department | Motorola | M10UGD6DC5BN | 760SAU0882 | LCS-2000 w/scan | 3.32 |
| Muskego | Muskego Park Department | Motorola | M10UGD6DC5BN | 760SAW0324 | LCS-2000 w/scan | 6.39 |
| Muskego | Muskego Park Department | Motorola | M10UGD6DC5BN | 760SAW0477 | LCS-2000 w/scan | 14.05 |
| | Muskego Park Department Total | | | | | 95.65 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4907 | MTS-2000 Model I | 0.37 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4937 | MTS-2000 Model I | 0.37 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4837 | MTS-2000 Model I | 0.71 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4939 | MTS-2000 Model I | 1.19 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4851 | MTS-2000 Model I | 2.23 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4812 | MTS-2000 Model I | 2.74 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4813 | MTS-2000 Model I | 3.60 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4798 | MTS-2000 Model I | 3.84 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4900 | MTS-2000 Model I | 6.00 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4828 | MTS-2000 Model I | 6.57 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4807 | MTS-2000 Model I | 6.64 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE5026 | MTS-2000 Model I | 8.37 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4908 | MTS-2000 Model I | 8.77 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4873 | MTS-2000 Model I | 10.07 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE5024 | MTS-2000 Model I | 10.09 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4829 | MTS-2000 Model I | 10.46 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4867 | MTS-2000 Model I | 11.49 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4941 | MTS-2000 Model I | 12.83 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4819 | MTS-2000 Model I | 14.58 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4883 | MTS-2000 Model I | 15.49 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4854 | MTS-2000 Model I | 15.95 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4999 | MTS-2000 Model I | 16.02 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4931 | MTS-2000 Model I | 16.69 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4827 | MTS-2000 Model I | 17.36 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4882 | MTS-2000 Model I | 17.73 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4866 | MTS-2000 Model I | 18.13 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4985 | MTS-2000 Model I | 20.67 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4914 | MTS-2000 Model I | 21.51 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466CCU0102 | MTS-2000 Model I | 25.23 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4826 | MTS-2000 Model I | 26.18 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4890 | MTS-2000 Model I | 29.61 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466CCU0101 | MTS-2000 Model I | 34.27 |

| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4938 | MTS-2000 Model I | 51.09 |
|---------|---------------------------------------|----------|--------------|------------|-----------------------|----------|
| Muskego | Muskego Police Department | Motorola | H18UCF9PW6AN | 721CEG0210 | XTS-5000 Model II | 0.76 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722abj0510 | MCS-2000 Control Base | 13.27 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABA0529 | MCS-2000 Control Base | 124.68 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABG0529 | MCS-2000 Control Base | 213.51 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABA0528 | MCS-2000 Control Base | 1,079.51 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1411 | MCS-2000 | 0.87 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1344 | MCS-2000 | 10.59 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1356 | MCS-2000 | 19.43 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1358 | MCS-2000 | 49.35 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1436 | MCS-2000 | 62.05 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1368 | MCS-2000 | 104.72 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1360 | MCS-2000 | 129.60 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1362 | MCS-2000 | 140.33 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1351 | MCS-2000 | 158.80 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1361 | MCS-2000 | 191.43 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1363 | MCS-2000 | 224.73 |
| | Muskego Police Department Total | | | | | 2,970.50 |
| Muskego | Muskego Public Works Department | Motorola | H10UCH6DC5BN | 678SAU3993 | LTS-2000 w/o scan | 0.88 |
| Muskego | Muskego Public Works Department | Motorola | H10UCH6DC5BN | 678SAU3840 | LTS-2000 w/o scan | 1.58 |
| Muskego | Muskego Public Works Department | Motorola | H10UCH6DC5BN | 678SAU3833 | LTS-2000 w/o scan | 2.81 |
| Muskego | Muskego Public Works Department | Motorola | H10UCH6DC5BN | 678SBU0747 | LTS-2000 w/scan | 2.83 |
| Muskego | Muskego Public Works Department | Motorola | H10UCH6DC5BN | 678SAU3955 | LTS-2000 w/o scan | 3.76 |
| Muskego | Muskego Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0446 | LCS-2000 w/scan | 0.37 |
| Muskego | Muskego Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0448 | LCS-2000 w/scan | 0.41 |
| Muskego | Muskego Public Works Department | Motorola | M10UGD6DC5BN | 760SAU0874 | LCS-2000 w/scan | 0.41 |
| Muskego | Muskego Public Works Department | Motorola | M10UGD6DC5BN | 760SCG0545 | LCS-2000 w/scan | 0.51 |
| Muskego | Muskego Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0470 | LCS-2000 w/scan | 0.68 |
| Muskego | Muskego Public Works Department | Motorola | M10UGD6DC5BN | 760SAU0891 | LCS-2000 w/scan | 0.72 |
| Muskego | Muskego Public Works Department | Motorola | M10UGD6DC5BN | 760SAU0869 | LCS-2000 w/scan | 0.78 |
| Muskego | Muskego Public Works Department | Motorola | M10UGD6DC5BN | 760SAU0872 | LCS-2000 w/scan | 0.83 |
| Muskego | Muskego Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0346 | LCS-2000 w/scan | 0.87 |
| Muskego | Muskego Public Works Department | Motorola | M10UGD6DC5BN | 760SAU0871 | LCS-2000 w/scan | 0.89 |
| Muskego | Muskego Public Works Department | Motorola | M10UGD6DC5BN | 760SAU0856 | LCS-2000 w/scan | 1.44 |
| Muskego | Muskego Public Works Department | Motorola | M10UGD6DC5BN | 760SAU0863 | LCS-2000 w/scan | 1.81 |
| | Muskego Public Works Department Total | | | | | 21.56 |
| Muskego | Muskego Utilities | Motorola | M10UGD6DC5BN | 760SAW0453 | LCS-2000 w/scan | 0.39 |

| Muskego | Muskego Utilities | Motorola | M10UGD6DC5BN | 760SAW0419 | LCS-2000 w/scan | 0.69 |
|---------|------------------------------|----------|--------------|------------|----------------------|-------|
| Muskego | Muskego Utilities | Motorola | M10UGD6DC5BN | 760SAW0351 | LCS-2000 w/scan | 0.73 |
| Muskego | Muskego Utilities | Motorola | M10UGD6DC5BN | 760SAW0375 | LCS-2000 w/scan | 1.26 |
| Muskego | Muskego Utilities | Motorola | M10UGD6DC5BN | 760SAW0360 | LCS-2000 w/scan | 1.31 |
| Muskego | Muskego Utilities | Motorola | M10UGD6DC5BN | 760SAW0469 | LCS-2000 w/scan | 1.98 |
| Muskego | Muskego Utilities | Motorola | M10UGD6DC5BN | 760SAW0437 | LCS-2000 w/scan | 2.37 |
| Muskego | Muskego Utilities | Motorola | M10UGD6DC5BN | 760SDA0251 | LCS-2000 w/scan | 3.52 |
| | Muskego Utilities Total | | | | | 12.25 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ACG0322 | MTS-2000 Model I FM | 0.34 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABE5025 | MTS-2000 Model I | 0.35 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CDE1793 | MTS-2000 Model I FM | 0.35 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS2906 | MTS-2000 Model I | 0.43 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CDE1777 | MTS-2000 Model I FM | 0.67 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CEL0441 | MTS-2000 Model I | 0.71 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS2910 | MTS-2000 Model I | 0.72 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS2901 | MTS-2000 Model I | 0.73 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ACG0318 | MTS-2000 Model I FM | 0.74 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS3029 | MTS-2000 Model I | 0.77 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS2914 | MTS-2000 Model I | 0.77 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CEE0426 | MTS-2000 Model I | 0.79 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS3025 | MTS-2000 Model I | 0.80 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS3020 | MTS-2000 Model I | 0.81 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CEL0439 | MTS-2000 Model I | 0.87 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CEE0427 | MTS-2000 Model I | 1.14 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS2904 | MTS-2000 Model I | 1.69 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABE5033 | MTS-2000 Model I | 1.77 |
| Muskego | Tess Corners Fire Department | Motorola | H46UCF9PW6AN | 205CFV2020 | XTS-2500 Model II FM | 0.75 |
| Muskego | Tess Corners Fire Department | Motorola | H46UCF9PW6AN | 205CFV2029 | XTS-2500 Model II FM | 1.19 |
| Muskego | Tess Corners Fire Department | Motorola | H46UCF9PW6AN | 205CFV2021 | XTS-2500 Model II FM | 5.03 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6AN | 722AWE0929 | MCS-2000 | 0.48 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6BN | 722ABE1413 | MCS-2000 | 0.45 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6BN | 722ABE1397 | MCS-2000 | 0.45 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6BN | 722ACE1792 | MCS-2000 | 0.67 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6BN | 722ABE1402 | MCS-2000 | 1.40 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6BN | 722ABE1392 | MCS-2000 | 1.61 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6BN | 722ABE1404 | MCS-2000 | 1.97 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6BN | 722ACG0721 | MCS-2000 | 6.43 |

| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6BN | 722ABE1420 | MCS-2000 | 8.31 |
|----------------|------------------------------------|----------|--------------|------------|-----------------------|----------|
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6BN | 722ABE1421 | MCS-2000 | 21.67 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6BN | 722ABE1406 | MCS-2000 | 36.26 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGN6PW6BN | 722ABS0340 | MCS-2000 Control Base | 0.73 |
| Muskego | Tess Corners Fire Department | Motorola | M01UJM6PW6AN | 722AZJ1232 | MCS-2000 | 0.34 |
| Muskego | Tess Corners Fire Department | Motorola | M01UJM6PW6AN | 722AZJ1220 | MCS-2000 | 0.49 |
| | Tess Corners Fire Department Total | | | | | 102.66 |
| Muskego Total | | | | | | 3,264.87 |
| Nashotah | Nashotah Fire Department | Motorola | H01UCD6PW1BN | 466ABS3005 | MTS-2000 Model I | 0.77 |
| Nashotah | Nashotah Fire Department | Motorola | H01UCD6PW1BN | 466ABS3003 | MTS-2000 Model I | 0.85 |
| Nashotah | Nashotah Fire Department | Motorola | H01UCD6PW1BN | 466ABS3002 | MTS-2000 Model I | 2.66 |
| Nashotah | Nashotah Fire Department | Motorola | H01UCD6PW1BN | 466ABS3007 | MTS-2000 Model I | 6.11 |
| Nashotah | Nashotah Fire Department | Motorola | H01UCD6PW1BN | 466ABS2997 | MTS-2000 Model I | 7.30 |
| Nashotah | Nashotah Fire Department | Motorola | H10UCH6DC5BN | 678SBE1879 | LTS-2000 w/o scan | 2.61 |
| Nashotah | Nashotah Fire Department | Motorola | H10UCH6DC5BN | 678SBE1872 | LTS-2000 w/o scan | 3.45 |
| Nashotah | Nashotah Fire Department | Motorola | M01UGM6PW6BN | 722ABS1450 | MCS-2000 | 2.61 |
| | Nashotah Fire Department Total | | | | | 26.36 |
| Nashotah | Nashotah Police Department | Motorola | H10UCH6DC5BN | 678SBC1171 | LTS-2000 w/scan | 1.00 |
| Nashotah | Nashotah Police Department | Motorola | M01UGM6PW6BN | 722ABS1447 | MCS-2000 | 10.31 |
| | Nashotah Police Department Total | | | | | 11.31 |
| Nashotah Total | | | | | | 37.67 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0802 | MTS-2000 Model I FM | 0.40 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0813 | MTS-2000 Model I FM | 0.41 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0820 | MTS-2000 Model I FM | 0.47 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0939 | MTS-2000 Model I FM | 0.51 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0949 | MTS-2000 Model I FM | 0.70 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0937 | MTS-2000 Model I FM | 0.73 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0948 | MTS-2000 Model I FM | 0.73 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0821 | MTS-2000 Model I FM | 0.77 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0806 | MTS-2000 Model I FM | 0.79 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0787 | MTS-2000 Model I FM | 0.79 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0945 | MTS-2000 Model I FM | 0.83 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0756 | MTS-2000 Model I FM | 1.19 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0797 | MTS-2000 Model I FM | 1.42 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0789 | MTS-2000 Model I FM | 1.91 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0932 | MTS-2000 Model I FM | 2.04 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0809 | MTS-2000 Model I FM | 2.49 |

| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0816 | MTS-2000 Model I FM | 3.13 |
|------------|---|----------|--------------|------------|---------------------|--------|
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0833 | MTS-2000 Model I FM | 3.23 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0914 | MTS-2000 Model I FM | 3.31 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0815 | MTS-2000 Model I FM | 5.31 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0807 | MTS-2000 Model I FM | 5.44 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0810 | MTS-2000 Model I FM | 6.71 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0791 | MTS-2000 Model I FM | 6.77 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0935 | MTS-2000 Model I FM | 7.74 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0801 | MTS-2000 Model I FM | 8.91 |
| New Berlin | New Berlin Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0759 | MTS-2000 Model I FM | 9.29 |
| New Berlin | New Berlin Fire Department | Motorola | M01UGM6PW6AN | 722AWE0523 | MCS-2000 | 2.99 |
| New Berlin | New Berlin Fire Department | Motorola | M01UJM6PW6AN | 722AYE2212 | MCS-2000 | 2.47 |
| New Berlin | New Berlin Fire Department | Motorola | M01UJM6PW6AN | 722AYE2094 | MCS-2000 | 2.54 |
| New Berlin | New Berlin Fire Department | Motorola | M01UJM6PW6AN | 722AYE2213 | MCS-2000 | 5.93 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SAYFM56 | LCS-2000 w/scan | 0.35 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SBA0731 | LCS-2000 w/scan | 0.36 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SBA0724 | LCS-2000 w/scan | 0.44 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SAYFM53 | LCS-2000 w/scan | 1.01 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SBA0569 | LCS-2000 w/scan | 1.25 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SBA0726 | LCS-2000 w/scan | 1.27 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SBA0616 | LCS-2000 w/scan | 1.51 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SBA0803 | LCS-2000 w/scan | 1.81 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SBA0567 | LCS-2000 w/scan | 2.11 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SAYFM63 | LCS-2000 w/scan | 2.14 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SBA0727 | LCS-2000 w/scan | 2.71 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SAYFM55 | LCS-2000 w/scan | 5.02 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SBA0733 | LCS-2000 w/scan | 5.35 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SBA0799 | LCS-2000 w/scan | 5.67 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SBA0736 | LCS-2000 w/scan | 9.03 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SAYFK06 | LCS-2000 w/scan | 10.09 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SAYFK05 | LCS-2000 w/scan | 12.69 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SBA0721 | LCS-2000 w/scan | 22.12 |
| New Berlin | New Berlin Fire Department | Motorola | M10UGD6DC5BN | 760SAYFM59 | LCS-2000 w/scan | 64.63 |
| | New Berlin Fire Department Total | | | | | 239.51 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAQ2580 | LTS-2000 w/scan | 0.35 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFB74 | LCS-2000 w/o scan | 0.51 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFF27 | LCS-2000 w/o scan | 0.52 |

| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFF24 | LCS-2000 w/o scan | 0.69 |
|------------|---|----------|--------------|------------|-------------------|-------|
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFB66 | LCS-2000 w/o scan | 1.19 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYEZ82 | LCS-2000 w/o scan | 1.53 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFB70 | LCS-2000 w/o scan | 1.57 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYEY87 | LCS-2000 w/o scan | 1.73 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFB72 | LCS-2000 w/o scan | 2.04 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYEY54 | LCS-2000 w/o scan | 2.30 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFB96 | LCS-2000 w/o scan | 2.59 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFB93 | LCS-2000 w/o scan | 2.85 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYEZ17 | LCS-2000 w/o scan | 4.18 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFB79 | LCS-2000 w/o scan | 4.52 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYEZ32 | LCS-2000 w/o scan | 5.27 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFF12 | LCS-2000 w/o scan | 6.15 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFF81 | LCS-2000 w/o scan | 6.72 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFF22 | LCS-2000 w/o scan | 7.25 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SBA0832 | LCS-2000 w/scan | 8.63 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAYFA50 | LCS-2000 w/o scan | 10.55 |
| | New Berlin Park and Recreation Department Total | | | | | 71.14 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2503 | LTS-2000 w/scan | 0.35 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2660 | LTS-2000 w/scan | 0.43 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2527 | LTS-2000 w/scan | 0.46 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2513 | LTS-2000 w/scan | 0.47 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2535 | LTS-2000 w/scan | 0.77 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2581 | LTS-2000 w/scan | 0.82 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2538 | LTS-2000 w/scan | 1.01 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2592 | LTS-2000 w/scan | 1.06 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2593 | LTS-2000 w/scan | 1.20 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2650 | LTS-2000 w/scan | 1.43 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ1066 | LTS-2000 w/scan | 2.10 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SBA0557 | LTS-2000 w/scan | 2.43 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SBA0545 | LTS-2000 w/scan | 2.47 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2653 | LTS-2000 w/scan | 2.53 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2544 | LTS-2000 w/scan | 2.65 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2685 | LTS-2000 w/scan | 3.01 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2494 | LTS-2000 w/scan | 3.45 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SBA0573 | LTS-2000 w/scan | 3.46 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2595 | LTS-2000 w/scan | 4.17 |

| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2541 | LTS-2000 w/scan | 4.36 |
|------------|------------------------------|----------|--------------|------------|-----------------|-------|
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2537 | LTS-2000 w/scan | 4.69 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ1081 | LTS-2000 w/scan | 5.64 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2504 | LTS-2000 w/scan | 7.11 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2600 | LTS-2000 w/scan | 7.17 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2654 | LTS-2000 w/scan | 7.89 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2781 | LTS-2000 w/scan | 7.91 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ1749 | LTS-2000 w/scan | 8.99 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2516 | LTS-2000 w/scan | 9.08 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2793 | LTS-2000 w/scan | 9.56 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2539 | LTS-2000 w/scan | 9.69 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2576 | LTS-2000 w/scan | 10.33 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SBA0577 | LTS-2000 w/scan | 11.95 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2522 | LTS-2000 w/scan | 11.97 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SBA0544 | LTS-2000 w/scan | 12.89 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2605 | LTS-2000 w/scan | 13.49 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2707 | LTS-2000 w/scan | 14.28 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SBA0602 | LTS-2000 w/scan | 14.52 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2505 | LTS-2000 w/scan | 15.46 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2492 | LTS-2000 w/scan | 17.09 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2575 | LTS-2000 w/scan | 17.44 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ1083 | LTS-2000 w/scan | 17.96 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2526 | LTS-2000 w/scan | 19.59 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2506 | LTS-2000 w/scan | 20.62 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SBA0546 | LTS-2000 w/scan | 20.78 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SBA0543 | LTS-2000 w/scan | 21.43 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ1104 | LTS-2000 w/scan | 21.73 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SDA0459 | LTS-2000 w/scan | 21.80 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2583 | LTS-2000 w/scan | 22.61 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SBA0551 | LTS-2000 w/scan | 23.81 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2710 | LTS-2000 w/scan | 25.87 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SDC0177 | LTS-2000 w/scan | 27.46 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2684 | LTS-2000 w/scan | 27.75 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2579 | LTS-2000 w/scan | 28.35 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2648 | LTS-2000 w/scan | 29.52 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SDC0302 | LTS-2000 w/scan | 29.61 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2646 | LTS-2000 w/scan | 29.68 |

| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ0841 | LTS-2000 w/scan | 30.46 |
|------------|------------------------------|----------|--------------|------------|-----------------------|----------|
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ1052 | LTS-2000 w/scan | 30.60 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SBA0558 | LTS-2000 w/scan | 30.64 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SDC0293 | LTS-2000 w/scan | 31.57 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SBA0583 | LTS-2000 w/scan | 32.93 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ0861 | LTS-2000 w/scan | 36.09 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2657 | LTS-2000 w/scan | 38.74 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2517 | LTS-2000 w/scan | 44.10 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ2578 | LTS-2000 w/scan | 47.29 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SBA0579 | LTS-2000 w/scan | 51.09 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ1069 | LTS-2000 w/scan | 51.24 |
| New Berlin | New Berlin Police Department | Motorola | H10UCH6DC5BN | 678SAQ0885 | LTS-2000 w/scan | 63.20 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0880 | XTS-5000 Model II | 2.74 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0896 | XTS-5000 Model II | 10.54 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0881 | XTS-5000 Model II | 16.47 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0901 | XTS-5000 Model II | 18.91 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0892 | XTS-5000 Model II | 24.07 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0889 | XTS-5000 Model II | 24.41 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0888 | XTS-5000 Model II | 27.39 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0902 | XTS-5000 Model II | 37.19 |
| New Berlin | New Berlin Police Department | Motorola | M01UGL6PW4BN | 722ABA0527 | MCS-2000 Control Base | 0.38 |
| New Berlin | New Berlin Police Department | Motorola | M01UGL6PW4BN | 722ABA0524 | MCS-2000 Control Base | 197.80 |
| New Berlin | New Berlin Police Department | Motorola | M01UGL6PW4BN | 722ABA0525 | MCS-2000 Control Base | 1,317.25 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SAYFK21 | LCS-2000 w/scan | 1.65 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SBA0620 | LCS-2000 w/scan | 3.42 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SAYFJ93 | LCS-2000 w/scan | 4.63 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SBA0798 | LCS-2000 w/scan | 4.77 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SAYFJ78 | LCS-2000 w/scan | 5.54 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SBA0804 | LCS-2000 w/scan | 6.20 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SAYFK89 | LCS-2000 w/scan | 6.49 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SBA0568 | LCS-2000 w/scan | 10.67 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SAYFM54 | LCS-2000 w/scan | 12.18 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SBA0800 | LCS-2000 w/scan | 13.75 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SAYFK09 | LCS-2000 w/scan | 15.83 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SAYFK52 | LCS-2000 w/scan | 17.34 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SBA0795 | LCS-2000 w/scan | 17.63 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SBA0782 | LCS-2000 w/scan | 21.03 |

| New Berlin | New Berlin Police Department | Motorola M | 110UGD6DC5BN | 760SBA0807 | LCS-2000 w/scan | 54.70 |
|------------|--|-------------|--------------|--------------------------|-------------------|----------|
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | 760SBA0765 | LCS-2000 w/scan | 56.83 |
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | 760SBA0797 | LCS-2000 w/scan | 76.40 |
| New Berlin | New Berlin Police Department New Berlin Police Department | | 110UGD6DC5BN | 760SBA0797 760SBA0570 | LCS-2000 w/scan | 113.25 |
| | ' | | | 760SAYFK08 | | |
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | | LCS-2000 w/scan | 132.81 |
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | 760SAYFM61 | LCS-2000 w/scan | 155.26 |
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | 760SAYFJ82 | LCS-2000 w/scan | 156.65 |
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | 760SAYFK03 | LCS-2000 w/scan | 164.76 |
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | 760SBA0805 | LCS-2000 w/scan | 178.09 |
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | 760SBA0773 | LCS-2000 w/scan | 179.93 |
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | 760SAYFK45 | LCS-2000 w/scan | 188.42 |
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | 760SAYFK96 | LCS-2000 w/scan | 204.87 |
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | 760SAYFJ74 | LCS-2000 w/scan | 207.41 |
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | 760SAYFM60 | LCS-2000 w/scan | 216.77 |
| New Berlin | New Berlin Police Department | | 110UGD6DC5BN | 760SAYFK10 | LCS-2000 w/scan | 255.46 |
| New Berlin | New Berlin Police Department | Motorola M | 110UGD6DC5BN | 760SAYFJ77 | LCS-2000 w/scan | 270.01 |
| | New Berlin Police Department Total | | | | | 5,562.25 |
| New Berlin | New Berlin Street Department | Motorola H1 | 10UCH6DC5BN | 678SAU4077 | LTS-2000 w/o scan | 0.45 |
| New Berlin | New Berlin Street Department | Motorola H1 | 10UCH6DC5BN | 678SAU4012 | LTS-2000 w/o scan | 8.53 |
| New Berlin | New Berlin Street Department | Motorola H1 | 10UCH6DC5BN | 678SAU4005 | LTS-2000 w/o scan | 8.63 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1180 | LCS-2000 w/o scan | 0.35 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1129 | LCS-2000 w/o scan | 0.36 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1153 | LCS-2000 w/o scan | 0.43 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1157 | LCS-2000 w/o scan | 0.45 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1222 | LCS-2000 w/o scan | 0.49 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1245 | LCS-2000 w/o scan | 0.52 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1228 | LCS-2000 w/o scan | 0.77 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1395 | LCS-2000 w/o scan | 0.77 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1275 | LCS-2000 w/o scan | 0.81 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1132 | LCS-2000 w/o scan | 0.81 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1272 | LCS-2000 w/o scan | 1.07 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1143 | LCS-2000 w/o scan | 1.16 |
| New Berlin | New Berlin Street Department | Motorola M | 110UGD6DC5BN | 760SAW1161 | LCS-2000 w/o scan | 1.17 |
| New Berlin | New Berlin Street Department | | 110UGD6DC5BN | 760SAW1415 | LCS-2000 w/o scan | 1.33 |
| New Berlin | New Berlin Street Department | | 110UGD6DC5BN | 760SAW1445 | LCS-2000 w/o scan | 1.61 |
| New Berlin | New Berlin Street Department | | 110UGD6DC5BN | 760SAW1343 | LCS-2000 w/o scan | 1.64 |
| New Berlin | New Berlin Street Department | | 110UGD6DC5BN | 760SAW1218 | LCS-2000 w/o scan | 2.14 |

| New Berlin | New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1155 | LCS-2000 w/o scan | 2.20 |
|------------|--|--|----------------|--------------------------|-------------------|--------|
| New Berlin | New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1142 | LCS-2000 w/o scan | 2.59 |
| New Berlin | New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1142 | LCS-2000 w/o scan | 2.91 |
| New Berlin | New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1270 | LCS-2000 w/o scan | 3.11 |
| New Berlin | New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1244 | LCS-2000 w/o scan | 4.19 |
| New Berlin | New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1172 | LCS-2000 w/o scan | 4.13 |
| New Berlin | New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1246 | LCS-2000 w/o scan | 4.01 |
| New Berlin | New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1274 | LCS-2000 w/o scan | 5.42 |
| New Berlin | New Berlin Street Department New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1437 | LCS-2000 w/o scan | 5.63 |
| New Berlin | New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1276 | LCS-2000 w/o scan | 6.03 |
| New Berlin | New Berlin Street Department New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW0476 | LCS-2000 w/scan | 6.45 |
| New Berlin | New Berlin Street Department New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1229 | LCS-2000 w/scan | 6.80 |
| New Berlin | New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1229 | LCS-2000 w/scan | 7.82 |
| New Berlin | New Berlin Street Department New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW0473 | LCS-2000 w/scan | 9.16 |
| New Berlin | New Berlin Street Department New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1427 | LCS-2000 w/o scan | 13.72 |
| New Berlin | New Berlin Street Department New Berlin Street Department | Motorola | M10UGD6DC5BN | 760SAW1313 | LCS-2000 w/o scan | 14.40 |
| New Defill | New Berlin Street Department Total | IVIOLOTOIA | MITOOGDODCSBIN | 7003AVV0472 | LU3-2000 W/SCall | 133.53 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorolo | H10UCH6DC5BN | 678SAQ2677 | LTS-2000 w/scan | 0.77 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola Motorola | H10UCH6DC5BN | 678SAQ2077 | LTS-2000 w/scan | 4.74 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SBA0822 | LCS-2000 w/scan | 0.53 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFB85 | LCS-2000 w/scan | 0.53 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFC44 | LCS-2000 w/o scan | 0.08 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFF20 | LCS-2000 w/o scan | 0.70 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SBL0071 | LCS-2000 w/o scan | 1.09 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SBL0071 | LCS-2000 w/o scan | 1.13 |
| New Berlin | New Berlin Water and Waste Water Utility | | M10UGD6DC5BN | 760SAYEZ97 | LCS-2000 w/o scan | 1.13 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFF58 | LCS-2000 w/o scan | 1.35 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFB88 | LCS-2000 w/o scan | 1.44 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola Motorola | M10UGD6DC5BN | 760SBN0032 | LCS-2000 w/o scan | 1.44 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFD80 | LCS-2000 w/o scan | 1.67 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SDA0205 | LCS-2000 w/s scan | 1.78 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFF69 | LCS-2000 w/scan | 1.78 |
| New Berlin | New Berlin Water and Waste Water Utility | + | M10UGD6DC5BN | 760SAYFG58 | LCS-2000 w/o scan | 1.95 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola Motorola | M10UGD6DC5BN | 760SAYFG56 760SAYFC47 | LCS-2000 w/o scan | 2.27 |
| New Berlin | New Berlin Water and Waste Water Utility | + | • | 760SAYEZ81 | LCS-2000 w/o scan | 2.27 |
| | · · · · · · · · · · · · · · · · · · · | Motorola | M10UGD6DC5BN | | | 2.80 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SBN0434 | LCS-2000 w/o scan | 3.42 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFF17 | LCS-2000 w/o scan | 3.42 |

| New Berlin | New Berlin Water and Waste Water Utility | Motorolo | M10UGD6DC5BN | 760SAYFB65 | LCS-2000 w/o scan | E 44 |
|----------------------------------|--|----------|--------------|------------|-------------------|----------|
| | · · · · · · · · · · · · · · · · · · · | Motorola | | | | 5.44 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFF59 | LCS-2000 w/o scan | 6.25 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFB86 | LCS-2000 w/o scan | 7.92 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SBN0014 | LCS-2000 w/o scan | 8.66 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFB63 | LCS-2000 w/o scan | 11.00 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SBN0463 | LCS-2000 w/o scan | 11.28 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SBA0820 | LCS-2000 w/scan | 11.31 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFB62 | LCS-2000 w/o scan | 27.43 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M10UGD6DC5BN | 760SAYFF68 | LCS-2000 w/o scan | 27.85 |
| | New Berlin Water and Waste Water Utility Total | | | | | 151.97 |
| New Berlin Total | | | | | | 6,158.40 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H01UCD6PW1BN | 466ABL3332 | MTS-2000 Model I | 0.35 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H01UCD6PW1BN | 466ABL3321 | MTS-2000 Model I | 0.37 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H01UCD6PW1BN | 466ABL3335 | MTS-2000 Model I | 0.87 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H01UCF6PW1BN | 466ABL3211 | MTS-2000 Model II | 1.17 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H01UCF6PW1BN | 466ABL3201 | MTS-2000 Model II | 2.88 |
| North Lake Fire Department | North Lake Fire Department | Motorola | M01UGM6PW6BN | 722ABL1376 | MCS-2000 | 0.36 |
| North Lake Fire Department | North Lake Fire Department | Motorola | M01UGM6PW6BN | 722ABL1305 | MCS-2000 | 0.40 |
| North Lake Fire Department | North Lake Fire Department | Motorola | M01UGM6PW6BN | 722ABL1303 | MCS-2000 | 0.77 |
| North Lake Fire Department | North Lake Fire Department | Motorola | M01UGM6PW6BN | 722ABL1319 | MCS-2000 | 1.03 |
| | North Lake Fire Department Total | | | | | 8.20 |
| North Lake Fire Department Total | | | | | | 8.20 |
| North Prairie | North Prairie Fire Department | Motorola | D35KGA5JC2AK | 604ASC0636 | Spectra | 1.54 |
| North Prairie | North Prairie Fire Department | Motorola | D45KGA5JB7AK | 604HQW0192 | Spectra | 8.29 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCD6PW1BN | 466AYC3159 | MTS-2000 Model I | 0.39 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCD6PW1BN | 466AYC3161 | MTS-2000 Model I | 0.40 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCF6PW1BN | 466AVG5780 | MTS-2000 Model II | 0.39 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCF6PW1BN | 466AZY7573 | MTS-2000 Model II | 0.40 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCF6PW1BN | 466ABW3763 | MTS-2000 Model II | 0.41 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCF6PW1BN | 466ABW3146 | MTS-2000 Model II | 0.45 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCF6PW1BN | 466ABW5354 | MTS-2000 Model II | 0.45 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCF6PW1BN | 466ABW5337 | MTS-2000 Model II | 0.46 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCF6PW1BN | 466ABW5348 | MTS-2000 Model II | 0.67 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCF6PW1BN | 466ABW5658 | MTS-2000 Model II | 0.83 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCF6PW1BN | 466AZG1419 | MTS-2000 Model II | 1.44 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCF6PW1BN | 466AAA2567 | MTS-2000 Model II | 1.58 |
| North Prairie | North Prairie Fire Department | Motorola | H01UCF6PW1BN | 466ABW5547 | MTS-2000 Model II | 1.67 |

| North Prairie | North Prairie Fire Department | Motorola | H01UCF6PW1BN | 466CCN2362 | MTS-2000 Model II | 12.01 |
|------------------------------------|---|----------|--------------|------------|-------------------|--------|
| North Prairie | North Prairie Fire Department | Motorola | M01UGM6PW6AN | 722AXS0640 | MCS-2000 | 4.31 |
| North Prairie | North Prairie Fire Department | Motorola | M01UGM6PW6AN | 722AWE0896 | MCS-2000 | 6.36 |
| | North Prairie Fire Department Total | | | | | 42.06 |
| North Prairie | North Prairie Police Department | Motorola | H10UCH6DC5BN | 678SBC0942 | LTS-2000 w/scan | 5.47 |
| North Prairie | North Prairie Police Department | Motorola | H10UCH6DC5BN | 678SBC1157 | LTS-2000 w/scan | 17.31 |
| North Prairie | North Prairie Police Department | Motorola | M01UGM6PW6BN | 722ABS1444 | MCS-2000 | 1.93 |
| North Prairie | North Prairie Police Department | Motorola | M01UGM6PW6BN | 722ABS1446 | MCS-2000 | 47.39 |
| | North Prairie Police Department Total | | | | | 72.09 |
| North Prairie Total | | | | | | 114.15 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4856 | MTS-2000 Model I | 0.86 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4847 | MTS-2000 Model I | 0.87 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4872 | MTS-2000 Model I | 1.59 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4853 | MTS-2000 Model I | 2.83 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4888 | MTS-2000 Model I | 3.54 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4850 | MTS-2000 Model I | 5.28 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4889 | MTS-2000 Model I | 11.53 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | M01UJM6PW6AN | 722AYE2079 | MCS-2000 | 9.83 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | M01UJM6PW6AN | 722AXY0620 | MCS-2000 | 9.85 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | M01UJM6PW6AN | 722AXY0619 | MCS-2000 | 10.88 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | M01UJM6PW6AN | 722AYE2613 | MCS-2000 | 53.59 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | M01UJM6PW6AN | 722AXY0623 | MCS-2000 | 66.31 |
| | Oconomowoc Lake Police Department Total | | | | | 176.96 |
| Oconomowoc Lake Total | | | | | | 176.96 |
| Oconomowoc Memorial Hospital | Oconomowoc Memorial Hospital | Motorola | L04UJH9PW9AN | 761CDA0111 | Base, low power | 31.18 |
| | Oconomowoc Memorial Hospital Total | | | | | 31.18 |
| Oconomowoc Memorial Hospital Total | | | | | | 31.18 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | H10UCH6DC5BN | 678SBE0276 | LTS-2000 w/scan | 0.39 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | H10UCH6DC5BN | 678SBE0306 | LTS-2000 w/scan | 1.87 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | H10UCH6DC5BN | 678SBC1106 | LTS-2000 w/scan | 8.43 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | H10UCH6DC5BN | 678SBC0862 | LTS-2000 w/scan | 18.87 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | H10UCH6DC5BN | 678SBC0946 | LTS-2000 w/scan | 20.02 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | H10UCH6DC5BN | 678SBE0308 | LTS-2000 w/scan | 22.21 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | H10UCH6DC5BN | 678SBE0297 | LTS-2000 w/scan | 24.25 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | H10UCH6DC5BN | 678SBC1110 | LTS-2000 w/scan | 24.81 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M10UGD6DC5BN | 760SBQ0917 | LCS-2000 w/scan | 0.35 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M10UGD6DC5BN | 760SBQ0926 | LCS-2000 w/scan | 0.37 |

| Oconomowoc, City | Oconomowoc City DPW | Motorola | M10UGD6DC5BN | 760SBQ0911 | LCS-2000 w/scan | 0.41 |
|------------------|---------------------------------|----------|--------------|------------|---------------------|--------|
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M10UGD6DC5BN | 760SBQ0938 | LCS-2000 w/scan | 0.45 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M10UGD6DC5BN | 760SBQ0896 | LCS-2000 w/scan | 0.68 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M10UGD6DC5BN | 760SBQ0937 | LCS-2000 w/scan | 0.69 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M10UGD6DC5BN | 760SBQ0923 | LCS-2000 w/scan | 0.77 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M10UGD6DC5BN | 760SBQ0909 | LCS-2000 w/scan | 0.85 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M10UGD6DC5BN | 760SBQ0930 | LCS-2000 w/scan | 1.23 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M10UGD6DC5BN | 760SBQ0908 | LCS-2000 w/scan | 1.75 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M10UGD6DC5BN | 760SBQ0899 | LCS-2000 w/scan | 3.97 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M10UGD6DC5BN | 760SEW0027 | LCS-2000 w/scan | 7.02 |
| | Oconomowoc City DPW Total | | | | | 139.41 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2331 | MTS-2000 Model I | 0.34 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2320 | MTS-2000 Model I | 0.42 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE1367 | MTS-2000 Model I | 0.43 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2321 | MTS-2000 Model I | 0.45 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2335 | MTS-2000 Model I | 0.47 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE1368 | MTS-2000 Model I | 0.76 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2318 | MTS-2000 Model I | 0.79 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2329 | MTS-2000 Model I | 0.81 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE1372 | MTS-2000 Model I | 1.37 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2332 | MTS-2000 Model I | 1.47 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2326 | MTS-2000 Model I | 2.01 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2333 | MTS-2000 Model I | 2.86 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2324 | MTS-2000 Model I | 2.88 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466CFH0298 | MTS-2000 Model I FM | 2.89 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466CFH0301 | MTS-2000 Model I FM | 9.69 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466CFH0302 | MTS-2000 Model I FM | 9.71 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466CFH0304 | MTS-2000 Model I FM | 10.32 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466CFH0303 | MTS-2000 Model I FM | 13.53 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466CFH0300 | MTS-2000 Model I FM | 17.60 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE5031 | MTS-2000 Model I | 18.47 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466CFH0299 | MTS-2000 Model I FM | 48.63 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H18UCF9PW6AN | 721CFC0895 | XTS-5000 Model II | 4.67 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H18UCF9PW6AN | 721CFC0904 | XTS-5000 Model II | 7.09 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722CFH1798 | MCS-2000 | 0.42 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722CFH1800 | MCS-2000 | 1.20 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1401 | MCS-2000 | 1.23 |

| Ta | Ta | 1 | I | | 1 | 1 |
|------------------|---------------------------------------|----------|--------------|------------|------------------|--------|
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1365 | MCS-2000 | 2.09 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1375 | MCS-2000 | 3.01 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1373 | MCS-2000 | 4.51 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1457 | MCS-2000 | 9.78 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722CFH1797 | MCS-2000 | 18.10 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1436 | MCS-2000 | 26.90 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1376 | MCS-2000 | 36.47 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2223 | MCS-2000 | 153.47 |
| | Oconomowoc City Fire Department Total | | | | | 414.83 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | H10UCH6DC5BN | 678SBC1139 | LTS-2000 w/scan | 0.84 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | H10UCH6DC5BN | 678SBC1133 | LTS-2000 w/scan | 1.49 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | H10UCH6DC5BN | 678SEW0399 | LTS-2000 w/scan | 21.40 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M10UGD6DC5BN | 760SBQ0066 | LCS-2000 w/scan | 0.37 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M10UGD6DC5BN | 760SAW0929 | LCS-2000 w/scan | 1.50 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M10UGD6DC5BN | 760SAW0922 | LCS-2000 w/scan | 1.52 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M10UGD6DC5BN | 760SAW3389 | LCS-2000 w/scan | 2.45 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M10UGD6DC5BN | 760SAW0976 | LCS-2000 w/scan | 2.54 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M10UGD6DC5BN | 760SBQ0111 | LCS-2000 w/scan | 2.96 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M10UGD6DC5BN | 760SAW0986 | LCS-2000 w/scan | 3.56 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M10UGD6DC5BN | 760SAW2749 | LCS-2000 w/scan | 5.55 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M10UGD6DC5BN | 760SBQ0067 | LCS-2000 w/scan | 7.01 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M10UGD6DC5BN | 760SBQ0068 | LCS-2000 w/scan | 7.74 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M10UGD6DC5BN | 760SBQ0119 | LCS-2000 w/scan | 13.61 |
| | Oconomowoc City Parks Total | | | | | 72.54 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE4929 | MTS-2000 Model I | 2.25 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE1381 | MTS-2000 Model I | 2.96 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE4919 | MTS-2000 Model I | 3.90 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE5011 | MTS-2000 Model I | 5.27 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE1373 | MTS-2000 Model I | 5.97 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE2303 | MTS-2000 Model I | 10.27 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE1362 | MTS-2000 Model I | 11.16 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE1365 | MTS-2000 Model I | 32.42 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE2322 | MTS-2000 Model I | 42.58 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE4924 | MTS-2000 Model I | 58.76 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE4918 | MTS-2000 Model I | 66.15 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE2292 | MTS-2000 Model I | 76.77 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE2306 | MTS-2000 Model I | 78.49 |

| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE2298 | MTS-2000 Model I | 78.85 |
|------------------|---|----------|--------------|------------|-----------------------|----------|
| | | | H01UCD6PW1BN | 466ABE1363 | MTS-2000 Model I | |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | | | | 84.65 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H18UCF9PW6AN | 721CFC0882 | XTS-5000 Model II | 9.77 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGL6PW4BN | 722ABE3132 | MCS-2000 Control Base | 2.20 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGL6PW4BN | 722ABE3134 | MCS-2000 Control Base | 3.57 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGL6PW4BN | 722ABE3131 | MCS-2000 Control Base | 79.61 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGL6PW4BN | 722ABE3137 | MCS-2000 Control Base | 110.37 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGL6PW4BN | 722ABE3135 | MCS-2000 Control Base | 394.40 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGL6PW4BN | 722ABE3133 | MCS-2000 Control Base | 576.46 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGM6PW6BN | 722ABS1388 | MCS-2000 | 15.97 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGM6PW6BN | 722ABS1389 | MCS-2000 | 22.74 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGM6PW6BN | 722ABS1369 | MCS-2000 | 28.62 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGM6PW6BN | 722ABS1378 | MCS-2000 | 66.92 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGM6PW6BN | 722ABS1396 | MCS-2000 | 228.57 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGM6PW6BN | 722ABS1400 | MCS-2000 | 286.09 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGM6PW6BN | 722ABS1386 | MCS-2000 | 404.30 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGM6PW6BN | 722ABS1399 | MCS-2000 | 421.69 |
| | Oconomowoc City Police Department Total | | | | | 3,211.72 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H10UCH6DC5BN | 678SBE0125 | LTS-2000 w/scan | 0.41 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H10UCH6DC5BN | 678SBE0146 | LTS-2000 w/scan | 1.75 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H10UCH6DC5BN | 678SBE0130 | LTS-2000 w/scan | 3.45 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H10UCH6DC5BN | 678SBC1109 | LTS-2000 w/scan | 3.67 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H10UCH6DC5BN | 678SBE0142 | LTS-2000 w/scan | 6.16 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M01UJM6PW6AN | 722AXY0621 | MCS-2000 | 5.27 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M01UJM6PW6AN | 722AXY0626 | MCS-2000 | 23.48 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760scl0545 | LCS-2000 w/scan | 0.41 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SAW0950 | LCS-2000 w/scan | 0.52 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SAW0999 | LCS-2000 w/scan | 0.68 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SBQ0931 | LCS-2000 w/scan | 0.72 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SBQ0950 | LCS-2000 w/scan | 0.76 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SEE0202 | LCS-2000 w/scan | 1.26 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SBQ0793 | LCS-2000 w/scan | 2.25 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SBQ0895 | LCS-2000 w/scan | 3.13 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SBQ0940 | LCS-2000 w/scan | 3.27 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SAW0985 | LCS-2000 w/scan | 4.18 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SBQ0946 | LCS-2000 w/scan | 6.17 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SBQ0927 | LCS-2000 w/scan | 6.63 |

| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SAW0918 | LCS-2000 w/scan | 10.63 |
|------------------------|-----------------------------------|----------|--------------|------------|------------------|----------|
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SAW3390 | LCS-2000 w/scan | 19.05 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SBQ0906 | LCS-2000 w/scan | 20.45 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SBQ0949 | LCS-2000 w/scan | 21.25 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M10UGD6DC5BN | 760SBQ0939 | LCS-2000 w/scan | 26.68 |
| | Oconomowoc City Utilities Total | | | | | 172.23 |
| Oconomowoc, City | Oconomowoc City Wastewater | Motorola | H10UCH6DC5BN | 678SBC1098 | LTS-2000 w/scan | 0.43 |
| Oconomowoc, City | Oconomowoc City Wastewater | Motorola | H10UCH6DC5BN | 678SBY6922 | LTS-2000 w/scan | 1.91 |
| Oconomowoc, City | Oconomowoc City Wastewater | Motorola | H10UCH6DC5BN | 678SBC1100 | LTS-2000 w/scan | 6.93 |
| Oconomowoc, City | Oconomowoc City Wastewater | Motorola | M10UGD6DC5BN | 760SBQ0073 | LCS-2000 w/scan | 2.39 |
| Oconomowoc, City | Oconomowoc City Wastewater | Motorola | M10UGD6DC5BN | 760SAW0962 | LCS-2000 w/scan | 5.05 |
| | Oconomowoc City Wastewater Total | | | | | 16.71 |
| Oconomowoc, City Total | | | | | | 4,027.44 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2996 | MTS-2000 Model I | 3.05 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2980 | MTS-2000 Model I | 5.43 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2981 | MTS-2000 Model I | 7.45 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABE1370 | MTS-2000 Model I | 7.84 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2903 | MTS-2000 Model I | 9.36 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2994 | MTS-2000 Model I | 15.39 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2986 | MTS-2000 Model I | 16.41 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2983 | MTS-2000 Model I | 16.47 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2987 | MTS-2000 Model I | 18.78 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2907 | MTS-2000 Model I | 19.53 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2992 | MTS-2000 Model I | 20.49 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2982 | MTS-2000 Model I | 21.04 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2993 | MTS-2000 Model I | 24.22 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2895 | MTS-2000 Model I | 25.19 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M01UGM6PW6BN | 722ABS1394 | MCS-2000 | 10.03 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M01UGM6PW6BN | 722ABS1384 | MCS-2000 | 11.33 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M01UGM6PW6BN | 722CEG1778 | MCS-2000 | 20.89 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M01UGM6PW6BN | 722ABS1356 | MCS-2000 | 28.14 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M01UGM6PW6BN | 722ABS1402 | MCS-2000 | 50.73 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M01UGM6PW6BN | 722ABS1393 | MCS-2000 | 76.06 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M01UGM6PW6BN | 722ABS1387 | MCS-2000 | 144.05 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M01UGM6PW6BN | 722ABS1382 | MCS-2000 | 176.71 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M10UGD6DC5BN | 760SBQ0041 | LCS-2000 w/scan | 2.91 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M10UGD6DC5BN | 760SBQ0120 | LCS-2000 w/scan | 6.87 |

| | Oconomowoc Town Police Department Total | | | | | 738.38 |
|--------------------------------|---|----------|--------------|------------|--------------------|--------|
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M10UGD6DC5BN | 760SBQ0098 | LCS-2000 w/scan | 0.48 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M10UGD6DC5BN | 760SBQ0071 | LCS-2000 w/scan | 0.77 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M10UGD6DC5BN | 760SBQ0097 | LCS-2000 w/scan | 1.05 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M10UGD6DC5BN | 760SBQ0100 | LCS-2000 w/scan | 1.24 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M10UGD6DC5BN | 760SBQ0123 | LCS-2000 w/scan | 1.47 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M10UGD6DC5BN | 760SBQ0102 | LCS-2000 w/scan | 2.41 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M28URS9PW1AN | 775TGA2016 | XTL-1500 Mobile | 4.02 |
| | Oconomowoc Town Public Works Total | | | | | 11.43 |
| Oconomowoc, Town Total | | | | | | 749.81 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3031 | MTS-2000 Model I | 0.77 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3032 | MTS-2000 Model I | 1.45 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3036 | MTS-2000 Model I | 1.51 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3000 | MTS-2000 Model I | 2.16 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3051 | MTS-2000 Model I | 3.30 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2979 | MTS-2000 Model I | 3.51 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3030 | MTS-2000 Model I | 3.59 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3046 | MTS-2000 Model I | 14.62 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3045 | MTS-2000 Model I | 21.73 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3004 | MTS-2000 Model I | 35.17 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCH6PW1BN | 466AAL4023 | MTS-2000 Model III | 2.93 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | M01UJM6PW6AN | 722AXY0634 | MCS-2000 | 0.41 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | M01UJM6PW6AN | 722AXY0635 | MCS-2000 | 0.47 |
| | Okauchee Fire Department Total | | | | | 91.61 |
| Okauchee Fire Department Total | | | | | | 91.61 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2916 | MTS-2000 Model I | 0.35 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABE1374 | MTS-2000 Model I | 0.37 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2971 | MTS-2000 Model I | 0.69 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2973 | MTS-2000 Model I | 0.80 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2902 | MTS-2000 Model I | 0.85 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2918 | MTS-2000 Model I | 1.33 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2974 | MTS-2000 Model I | 1.43 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2921 | MTS-2000 Model I | 1.54 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2977 | MTS-2000 Model I | 1.76 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2919 | MTS-2000 Model I | 1.83 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABE1379 | MTS-2000 Model I | 1.85 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2912 | MTS-2000 Model I | 2.41 |

| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2976 | MTS-2000 Model I | 3.25 |
|--------------------------|--------------------------|----------|--------------|------------|-------------------|-------|
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABE1376 | MTS-2000 Model I | 3.26 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2970 | MTS-2000 Model I | 4.09 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2922 | MTS-2000 Model I | 4.46 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2985 | MTS-2000 Model I | 4.40 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABE1375 | MTS-2000 Model I | 5.62 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2920 | MTS-2000 Model I | 6.06 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABE4934 | MTS-2000 Model I | 7.24 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCD6PW1BN | 466ABS2972 | MTS-2000 Model I | 8.75 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCF6PW1BN | 466ABE1899 | MTS-2000 Model II | 0.38 |
| ' | <u>'</u> | Motorola | H01UCF6PW1BN | 466ABS3430 | MTS-2000 Model II | 0.38 |
| Pewaukee Fire Department | Pewaukee Fire Department | | H01UCF6PW1BN | 466ABS3442 | MTS-2000 Model II | 0.38 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | | 466ABS3442 | | 2.28 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCF6PW1BN | | MTS-2000 Model II | |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCF6PW1BN | 466ABS3419 | MTS-2000 Model II | 2.87 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCF6PW1BN | 466ABS3417 | MTS-2000 Model II | 3.97 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCF6PW1BN | 466ABE1877 | MTS-2000 Model II | 4.25 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCF6PW1BN | 466ABS3437 | MTS-2000 Model II | 5.06 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCF6PW1BN | 466ABS3431 | MTS-2000 Model II | 6.25 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCF6PW1BN | 466ABE1902 | MTS-2000 Model II | 7.63 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCF6PW1BN | 466ABS3428 | MTS-2000 Model II | 7.83 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCF6PW1BN | 466ABE1887 | MTS-2000 Model II | 8.13 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCF6PW1BN | 466ABS3438 | MTS-2000 Model II | 14.09 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H01UCF6PW1BN | 466ACE1996 | MTS-2000 Model II | 23.03 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M01UGM6PW6AN | 722AWE0425 | MCS-2000 | 0.83 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M01UGM6PW6BN | 722ACE1411 | MCS-2000 | 1.10 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M01UGM6PW6BN | 722ACE1413 | MCS-2000 | 23.07 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M01UJM6PW6BN | 722AAG0693 | MCS-2000 | 1.85 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M10UGD6DC5BN | 760SBS0822 | LCS-2000 w/scan | 0.37 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M10UGD6DC5BN | 760SBS0867 | LCS-2000 w/scan | 0.94 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M10UGD6DC5BN | 760SBS0795 | LCS-2000 w/scan | 2.05 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M10UGD6DC5BN | 760SBS0914 | LCS-2000 w/scan | 2.86 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M10UGD6DC5BN | 760SBS0833 | LCS-2000 w/scan | 3.21 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M10UGD6DC5BN | 760SBS0840 | LCS-2000 w/scan | 5.86 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M10UGD6DC5BN | 760SBS0823 | LCS-2000 w/scan | 13.23 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M10UGD6DC5BN | 760SBS0901 | LCS-2000 w/scan | 14.51 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M10UGD6DC5BN | 760SBS0830 | LCS-2000 w/scan | 18.99 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M10UGD6DC5BN | 760SBS0947 | LCS-2000 w/scan | 24.73 |

| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M10UGD6DC5BN | 760SBS0831 | LCS-2000 w/scan | 43.07 |
|--------------------------------|--------------------------------------|----------|--------------|------------|-------------------|--------|
| | Pewaukee Fire Department Total | | | | | 306.11 |
| Pewaukee Fire Department Total | | | | | | 306.11 |
| Pewaukee, City | Pewaukee City Parks Department | Motorola | M10UGD6DC5BN | 760SBS1126 | LCS-2000 w/o scan | 1.42 |
| Pewaukee, City | Pewaukee City Parks Department | Motorola | M10UGD6DC5BN | 760SBS1075 | LCS-2000 w/o scan | 3.31 |
| Pewaukee, City | Pewaukee City Parks Department | Motorola | M10UGD6DC5BN | 760SBS1135 | LCS-2000 w/o scan | 3.96 |
| Pewaukee, City | Pewaukee City Parks Department | Motorola | M10UGD6DC5BN | 760SBS1175 | LCS-2000 w/scan | 4.35 |
| Pewaukee, City | Pewaukee City Parks Department | Motorola | M10UGD6DC5BN | 760SBS1206 | LCS-2000 w/scan | 5.26 |
| Pewaukee, City | Pewaukee City Parks Department | Motorola | M10UGD6DC5BN | 760SBS1127 | LCS-2000 w/o scan | 6.28 |
| Pewaukee, City | Pewaukee City Parks Department | Motorola | M10UGD6DC5BN | 760SBS0724 | LCS-2000 w/o scan | 7.26 |
| | Pewaukee City Parks Department Total | | | | | 31.84 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS3063 | MTS-2000 Model I | 3.45 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | h01ucd6pw1bn | 466ABS2893 | MTS-2000 Model I | 3.60 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS3053 | MTS-2000 Model I | 4.19 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2896 | MTS-2000 Model I | 4.79 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2899 | MTS-2000 Model I | 5.47 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2885 | MTS-2000 Model I | 6.05 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS3054 | MTS-2000 Model I | 7.03 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2898 | MTS-2000 Model I | 9.19 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2884 | MTS-2000 Model I | 9.57 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2887 | MTS-2000 Model I | 9.92 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2892 | MTS-2000 Model I | 10.53 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2883 | MTS-2000 Model I | 10.79 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2882 | MTS-2000 Model I | 11.84 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS3059 | MTS-2000 Model I | 12.13 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2889 | MTS-2000 Model I | 12.96 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2894 | MTS-2000 Model I | 16.93 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS3057 | MTS-2000 Model I | 18.91 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2886 | MTS-2000 Model I | 21.53 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2891 | MTS-2000 Model I | 23.75 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H01UCD6PW1BN | 466ABS2890 | MTS-2000 Model I | 27.88 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CEG0139 | XTS-5000 Model II | 0.86 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CEG0123 | XTS-5000 Model II | 3.14 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CEG0130 | XTS-5000 Model II | 4.25 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CFC0893 | XTS-5000 Model II | 4.59 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CFC0894 | XTS-5000 Model II | 5.17 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CEG0131 | XTS-5000 Model II | 5.56 |

| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CEG0140 | XTS-5000 Model II | 5.72 |
|----------------|---------------------------------------|----------|--------------|------------|-------------------|----------|
| • | · | | | | | 5.72 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CEG0127 | XTS-5000 Model II | |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CFC0903 | XTS-5000 Model II | 6.70 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CEG0136 | XTS-5000 Model II | 7.51 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CFC0900 | XTS-5000 Model II | 11.88 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CEG0134 | XTS-5000 Model II | 13.15 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CFC0899 | XTS-5000 Model II | 15.31 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CEG0126 | XTS-5000 Model II | 16.85 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CFC0891 | XTS-5000 Model II | 17.33 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | H18UCF9PW6AN | 721CEG0135 | XTS-5000 Model II | 18.80 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722ABW0850 | MCS-2000 | 6.74 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722CDY2378 | MCS-2000 | 6.80 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722ABW0852 | MCS-2000 | 7.45 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722ABW0857 | MCS-2000 | 12.91 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722CDY2377 | MCS-2000 | 13.53 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722ABW0858 | MCS-2000 | 50.70 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722ABW0853 | MCS-2000 | 58.57 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722CEN2073 | MCS-2000 | 78.44 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722ABW0854 | MCS-2000 | 106.23 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722ABW0859 | MCS-2000 | 112.02 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722ABW0855 | MCS-2000 | 124.90 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722ABW0851 | MCS-2000 | 129.27 |
| Pewaukee, City | Pewaukee City Police Department | Motorola | M01UGM6PW6BN | 722ABW0856 | MCS-2000 | 190.65 |
| | Pewaukee City Police Department Total | | | | | 1,271.33 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | h10uch6dc5bn | 678sbe0342 | LTS-2000 w/scan | 1.34 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | h10uch6dc5bn | 678sbe0356 | LTS-2000 w/scan | 1.57 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | m10ugd6dc5bn | 760sbs0238 | LCS-2000 w/scan | 0.35 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | m10ugd6dc5bn | 760sbs1212 | LCS-2000 w/scan | 0.38 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | m10ugd6dc5bn | 760sbs0160 | LCS-2000 w/scan | 0.39 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M10UGD6DC5BN | 760SBS0209 | LCS-2000 w/scan | 0.42 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | m10ugd6dc5bn | 760sbs0146 | LCS-2000 w/scan | 0.43 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | m10ugd6dc5bn | 760sbs0207 | LCS-2000 w/scan | 0.49 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | m10ugd6dc5bn | 760sbs1202 | LCS-2000 w/scan | 0.71 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | m10ugd6dc5bn | 760sbs1172 | LCS-2000 w/scan | 1.06 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M10UGD6DC5BN | 760SBS0208 | LCS-2000 w/scan | 1.51 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M10UGD6DC5BN | 760SBS0237 | LCS-2000 w/scan | 1.79 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | m10ugd6dc5bn | 760sbs0124 | LCS-2000 w/scan | 1.91 |

| Pewaukee, City | Pewaukee City Public Works Department | Motorola | m10ugd6dc5bn | 760sbs0203 | LCS-2000 w/scan | 2.15 |
|----------------------|---|----------|--------------|------------|-------------------|----------|
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M10UGD6DC5BN | 760SBS1214 | LCS-2000 w/scan | 2.21 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M10UGD6DC5BN | 760SEC0235 | LCS-2000 w/scan | 4.37 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M10UGD6DC5BN | 760SBS0204 | LCS-2000 w/scan | 5.26 |
| | Pewaukee City Public Works Department Total | | | | | 26.33 |
| Pewaukee, City Total | | | | | | 1,329.51 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466ABE1382 | MTS-2000 Model I | 3.23 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466CFE0117 | MTS-2000 Model I | 5.22 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466CFE0298 | MTS-2000 Model I | 8.45 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466ABE1369 | MTS-2000 Model I | 9.52 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466ABE1378 | MTS-2000 Model I | 10.97 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466ABE2313 | MTS-2000 Model I | 14.50 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466ABE1377 | MTS-2000 Model I | 16.14 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466abs3061 | MTS-2000 Model I | 18.43 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466ABE2309 | MTS-2000 Model I | 19.58 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466ABE2310 | MTS-2000 Model I | 21.53 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466ABE2316 | MTS-2000 Model I | 23.88 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466ABE2314 | MTS-2000 Model I | 26.13 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466ABE1384 | MTS-2000 Model I | 28.89 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466ABE2307 | MTS-2000 Model I | 32.37 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H01UCD6PW1BN | 466ABE2289 | MTS-2000 Model I | 58.72 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M01UGM6PW6BN | 722ABS1363 | MCS-2000 | 2.47 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M01UGM6PW6BN | 722ACE1415 | MCS-2000 | 8.07 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M01UGM6PW6BN | 722ABS1411 | MCS-2000 | 30.77 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M01UGM6PW6BN | 722ABS1406 | MCS-2000 | 78.84 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M01UGM6PW6BN | 722ABS1383 | MCS-2000 | 82.37 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M01UGM6PW6BN | 722ABS1391 | MCS-2000 | 132.05 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M01UGM6PW6BN | 722ABS1392 | MCS-2000 | 174.43 |
| | Pewaukee Village Police Department Total | | | | | 806.55 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | H10UCH6DC5BN | 678SBN0736 | LTS-2000 w/o scan | 0.35 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | H10UCH6DC5BN | 678SBN0724 | LTS-2000 w/o scan | 0.48 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | H10UCH6DC5BN | 678SBN0730 | LTS-2000 w/o scan | 0.74 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0406 | LCS-2000 w/o scan | 0.39 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0362 | LCS-2000 w/o scan | 0.40 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBL1203 | LCS-2000 w/o scan | 0.40 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0417 | LCS-2000 w/o scan | 0.44 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0237 | LCS-2000 w/o scan | 0.44 |

| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0375 | LCS-2000 w/o scan | 0.47 |
|----------------------------------|---|----------|--------------|------------|-----------------------|--------|
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0423 | LCS-2000 w/o scan | 0.69 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0238 | LCS-2000 w/o scan | 0.73 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0425 | LCS-2000 w/o scan | 0.75 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0409 | LCS-2000 w/o scan | 1.46 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0005 | LCS-2000 w/o scan | 1.72 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0410 | LCS-2000 w/o scan | 1.74 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0424 | LCS-2000 w/o scan | 1.93 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBN0004 | LCS-2000 w/o scan | 6.05 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M10UGD6DC5BN | 760SBL1201 | LCS-2000 w/o scan | 8.95 |
| | Pewaukee Village Public Works Departments Total | | | | | 28.13 |
| Pewaukee, Village Total | | | | | | 834.67 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H10UCH6DC5BN | 678SBE0139 | LTS-2000 w/scan | 0.46 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H10UCH6DC5BN | 678SBC1147 | LTS-2000 w/scan | 0.69 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H10UCH6DC5BN | 678SBC1153 | LTS-2000 w/scan | 0.72 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H10UCH6DC5BN | 678SBE0155 | LTS-2000 w/scan | 0.80 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H10UCH6DC5BN | 678SBE0134 | LTS-2000 w/scan | 0.85 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H10UCH6DC5BN | 678SBE0157 | LTS-2000 w/scan | 1.86 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H10UCH6DC5BN | 678SBC1134 | LTS-2000 w/scan | 1.95 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H10UCH6DC5BN | 678SBE0117 | LTS-2000 w/scan | 2.75 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H10UCH6DC5BN | 678SBE0136 | LTS-2000 w/scan | 6.73 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H10UCH6DC5BN | 678SBE0116 | LTS-2000 w/scan | 13.88 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCH9PW7AN | 205CFP1186 | XTS-2500 Model III FM | 1.59 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCH9PW7AN | 205CFP1184 | XTS-2500 Model III FM | 4.54 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCH9PW7AN | 205CFP1185 | XTS-2500 Model III FM | 7.75 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0091 | LCS-2000 w/scan | 0.39 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0115 | LCS-2000 w/scan | 0.47 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0062 | LCS-2000 w/scan | 0.47 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0042 | LCS-2000 w/scan | 0.81 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M10UGD6DC5BN | 760SAYER38 | LCS-2000 w/scan | 16.76 |
| | Stone Bank Fire Department Total | | | | | 63.47 |
| Stone Bank Fire Department Total | | | | | | 63.47 |
| Summit | Summit Highway Department | Motorola | H10UCH6DC5BN | 678SBE0960 | LTS-2000 w/o scan | 0.41 |
| Summit | Summit Highway Department | Motorola | H10UCH6DC5BN | 678SBE0854 | LTS-2000 w/o scan | 0.73 |
| Summit | Summit Highway Department | Motorola | M10UGD6DC5BN | 760SBG0116 | LCS-2000 w/o scan | 0.36 |
| Summit | Summit Highway Department | Motorola | M10UGD6DC5BN | 760SBE0568 | LCS-2000 w/o scan | 1.04 |
| Summit | Summit Highway Department | Motorola | M10UGD6DC5BN | 760SBG0114 | LCS-2000 w/o scan | 1.35 |

| Summit | Summit Highway Department | Motorola | M10UGD6DC5BN | 760SBG0115 | LCS-2000 w/o scan | 3.37 |
|----------------------|---------------------------------|----------|--------------|------------|-------------------|--------|
| | Summit Highway Department Total | | | | | 7.25 |
| Summit | Summit Police Department | Motorola | H01UCD6PW1BN | 466AUL3029 | MTS-2000 Model I | 4.57 |
| Summit | Summit Police Department | Motorola | H01UCF6PW1BN | 466AYN2260 | MTS-2000 Model II | 19.95 |
| Summit | Summit Police Department | Motorola | H10UCH6DC5BN | 678SBG0067 | LTS-2000 w/scan | 0.48 |
| Summit | Summit Police Department | Motorola | H10UCH6DC5BN | 678SBG0149 | LTS-2000 w/scan | 1.83 |
| Summit | Summit Police Department | Motorola | H10UCH6DC5BN | 678SBG0193 | LTS-2000 w/scan | 3.75 |
| Summit | Summit Police Department | Motorola | H10UCH6DC5BN | 678SBG0194 | LTS-2000 w/scan | 4.71 |
| Summit | Summit Police Department | Motorola | H10UCH6DC5BN | 678SBG0057 | LTS-2000 w/scan | 5.40 |
| Summit | Summit Police Department | Motorola | H10UCH6DC5BN | 678SBG0033 | LTS-2000 w/scan | 9.24 |
| Summit | Summit Police Department | Motorola | H10UCH6DC5BN | 678SBG0202 | LTS-2000 w/scan | 11.71 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CFC0886 | XTS-5000 Model II | 7.00 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CFC0883 | XTS-5000 Model II | 7.71 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CFC0885 | XTS-5000 Model II | 10.91 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CFC0884 | XTS-5000 Model II | 13.27 |
| Summit | Summit Police Department | Motorola | M01UGM6PW6BN | 722ABL1338 | MCS-2000 | 36.28 |
| Summit | Summit Police Department | Motorola | M01UGM6PW6BN | 722ABL1313 | MCS-2000 | 37.37 |
| Summit | Summit Police Department | Motorola | M01UGM6PW6BN | 722ABL1308 | MCS-2000 | 93.63 |
| Summit | Summit Police Department | Motorola | M01UGM6PW6BN | 722ABL1306 | MCS-2000 | 134.80 |
| Summit | Summit Police Department | Motorola | M10UGD6DC5BN | 760SAS4475 | LCS-2000 w/scan | 2.83 |
| | Summit Police Department Total | | | | | 405.45 |
| Summit Total | | | | | | 412.69 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCD6PW1BN | 466ABS2989 | MTS-2000 Model I | 0.34 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCD6PW1BN | 466ABS3015 | MTS-2000 Model I | 0.46 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCD6PW1BN | 466ABS2999 | MTS-2000 Model I | 1.16 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCD6PW1BN | 466ABS3013 | MTS-2000 Model I | 1.67 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCD6PW1BN | 466ABS3009 | MTS-2000 Model I | 3.36 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCD6PW1BN | 466ABS3011 | MTS-2000 Model I | 3.42 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCD6PW1BN | 466ABS3019 | MTS-2000 Model I | 3.54 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCD6PW1BN | 466ABS2991 | MTS-2000 Model I | 5.39 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCD6PW1BN | 466ABS3017 | MTS-2000 Model I | 8.62 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCF6PW1BN | 466ABW2327 | MTS-2000 Model II | 1.02 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCF6PW1BN | 466AVJ0746 | MTS-2000 Model II | 2.89 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCF6PW1BN | 466AVG5779 | MTS-2000 Model II | 5.26 |
| Summit Fire District | Summit Fire Department | Motorola | H01UCF6PW1BN | 466ABW2574 | MTS-2000 Model II | 6.02 |
| Summit Fire District | Summit Fire Department | Motorola | M01UGM6PW6AN | 722AWE0623 | MCS-2000 | 0.36 |
| Summit Fire District | Summit Fire Department | Motorola | M01UJM6PW6AN | 722AXY0630 | MCS-2000 | 0.44 |

| Summit Fire District | Summit Fire Department | Motorola | M01UJM6PW6AN | 722AYE2122 | MCS-2000 | 0.44 |
|----------------------------|-----------------------------------|----------|--------------|------------|-------------------|--------|
| Summit Fire District | Summit Fire Department | Motorola | M01UJM6PW6AN | 722AXY0624 | MCS-2000 | 0.92 |
| Summit Fire District | Summit Fire Department | Motorola | M01UJM6PW6AN | 722AXY0629 | MCS-2000 | 0.95 |
| Summit Fire District | Summit Fire Department | Motorola | M01UJM6PW6AN | 722AXY0625 | MCS-2000 | 1.63 |
| Summit Fire District | Summit Fire Department | Motorola | M01UJM6PW6AN | 722AXY0628 | MCS-2000 | 1.79 |
| Summit Fire District | Summit Fire Department | Motorola | M01UJM6PW6AN | 722AXY0632 | MCS-2000 | 4.61 |
| | Summit Fire Department Total | | | | | 54.31 |
| Summit Fire District Total | | | | | | 54.31 |
| Sussex | Sussex Emergency Government | Motorola | H10UCH6DC5BN | 678SBS0553 | LTS-2000 w/scan | 0.73 |
| | Sussex Emergency Government Total | | | | | 0.73 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3386 | MTS-2000 Model II | 0.44 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3406 | MTS-2000 Model II | 0.79 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3373 | MTS-2000 Model II | 1.13 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3375 | MTS-2000 Model II | 1.62 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3407 | MTS-2000 Model II | 1.91 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3392 | MTS-2000 Model II | 2.49 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3377 | MTS-2000 Model II | 2.78 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3397 | MTS-2000 Model II | 3.04 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3409 | MTS-2000 Model II | 3.27 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3374 | MTS-2000 Model II | 5.39 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3401 | MTS-2000 Model II | 8.78 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3376 | MTS-2000 Model II | 8.97 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3413 | MTS-2000 Model II | 9.37 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3390 | MTS-2000 Model II | 9.44 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3379 | MTS-2000 Model II | 10.29 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3380 | MTS-2000 Model II | 16.87 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3408 | MTS-2000 Model II | 28.66 |
| Sussex | Sussex Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0065 | LCS-2000 w/scan | 0.77 |
| Sussex | Sussex Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0043 | LCS-2000 w/scan | 1.23 |
| Sussex | Sussex Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0064 | LCS-2000 w/scan | 1.25 |
| Sussex | Sussex Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0076 | LCS-2000 w/scan | 1.49 |
| Sussex | Sussex Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0039 | LCS-2000 w/scan | 1.89 |
| Sussex | Sussex Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0078 | LCS-2000 w/scan | 3.31 |
| Sussex | Sussex Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0112 | LCS-2000 w/scan | 5.51 |
| Sussex | Sussex Fire Department | Motorola | M10UGD6DC5BN | 760SBQ0126 | LCS-2000 w/scan | 17.88 |
| Sussex | Sussex Fire Department | Motorola | M10UGD6DC5BN | 760SAW0973 | LCS-2000 w/scan | 31.79 |
| | Sussex Fire Department Total | | | | | 180.37 |

| Sussex | Sussex Public Works Department | Motorola | H10UCH6DC5BN | 678SBU0571 | LTS-2000 w/scan | 0.35 |
|-------------------------------------|--------------------------------------|----------|--------------|------------|-----------------------|--------|
| Sussex | Sussex Public Works Department | Motorola | H10UCH6DC5BN | 678SBW0060 | LTS-2000 w/scan | 0.36 |
| Sussex | Sussex Public Works Department | Motorola | H10UCH6DC5BN | 678SBU0563 | LTS-2000 w/scan | 0.43 |
| Sussex | Sussex Public Works Department | Motorola | H10UCH6DC5BN | 678SBW0034 | LTS-2000 w/scan | 0.44 |
| Sussex | Sussex Public Works Department | Motorola | H10UCH6DC5BN | 678SBU0766 | LTS-2000 w/scan | 0.68 |
| Sussex | Sussex Public Works Department | Motorola | H10UCH6DC5BN | 678SBU1077 | LTS-2000 w/scan | 0.79 |
| Sussex | Sussex Public Works Department | Motorola | H10UCH6DC5BN | 678SBU0767 | LTS-2000 w/scan | 2.29 |
| Sussex | Sussex Public Works Department | Motorola | M10UGD6DC5BN | 760SBS0876 | LCS-2000 w/scan | 0.40 |
| | Sussex Public Works Department Total | | | | | 5.75 |
| Sussex Total | | | | | | 186.85 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3194 | MTS-2000 Model II | 0.35 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3203 | MTS-2000 Model II | 0.37 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3154 | MTS-2000 Model II | 0.43 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3178 | MTS-2000 Model II | 0.71 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466AZY5344 | MTS-2000 Model II | 0.81 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3159 | MTS-2000 Model II | 0.86 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3192 | MTS-2000 Model II | 1.02 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3220 | MTS-2000 Model II | 1.15 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3164 | MTS-2000 Model II | 1.49 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3173 | MTS-2000 Model II | 1.49 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3166 | MTS-2000 Model II | 3.44 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3221 | MTS-2000 Model II | 7.05 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3177 | MTS-2000 Model II | 11.28 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3189 | MTS-2000 Model II | 13.25 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1328 | MCS-2000 | 2.29 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1315 | MCS-2000 | 3.03 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1301 | MCS-2000 | 4.36 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1342 | MCS-2000 | 4.81 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1314 | MCS-2000 | 6.40 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1310 | MCS-2000 | 7.41 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1339 | MCS-2000 | 20.75 |
| | Wales/Genesee Fire Department Total | | | | | 92.73 |
| Wales/Genesee Fire Department Total | | | | | | 92.73 |
| Waukesha County | Waukesha County Communications | Motorola | M01UGL6PW4BN | 722CEC0629 | MCS-2000 Control Base | 6.98 |
| Waukesha County | Waukesha County Communications | Motorola | M01UGM6PW6BN | 722CEC0652 | MCS-2000 Control Base | 1.51 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758209 | None | 0.37 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759050 | None | 0.40 |

| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758301 | None | 0.47 |
|-----------------|--------------------------------|----------|---------|----------|------|-------|
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758614 | None | 0.76 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758309 | None | 0.78 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758501 | None | 0.80 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758802 | None | 0.81 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759108 | None | 0.84 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758404 | None | 0.87 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759144 | None | 1.16 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758609 | None | 1.36 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758203 | None | 1.37 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758314 | None | 1.45 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758202 | None | 1.51 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758610 | None | 1.51 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759008 | None | 1.57 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758128 | None | 1.73 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759027 | None | 2.75 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759328 | None | 3.27 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758604 | None | 3.34 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758809 | None | 3.53 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759044 | None | 3.87 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758804 | None | 3.94 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758315 | None | 4.95 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758810 | None | 5.05 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759128 | None | 6.31 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758808 | None | 6.52 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758927 | None | 6.97 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758307 | None | 6.97 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758602 | None | 8.85 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758827 | None | 8.99 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758201 | None | 9.03 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758601 | None | 9.10 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758645 | None | 9.31 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758304 | None | 9.89 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758207 | None | 12.16 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758807 | None | 13.55 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758801 | None | 13.73 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758844 | None | 13.97 |

| | | | Т | 1 | | |
|-----------------|---|----------|--------------|------------|-------------------|-----------|
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758344 | None | 14.53 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758845 | None | 17.55 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758615 | None | 22.15 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758308 | None | 23.03 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758204 | None | 24.32 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758607 | None | 28.65 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759028 | None | 32.03 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758244 | None | 32.79 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758208 | None | 56.73 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758608 | None | 137.38 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758828 | None | 139.36 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758644 | None | 145.03 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758345 | None | 152.62 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758245 | None | 153.19 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759600 | None | 406.27 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758707 | None | 471.10 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758928 | None | 1,207.80 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758744 | None | 2,849.35 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758508 | None | 2,905.47 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758445 | None | 4,105.01 |
| | Waukesha County Communications Total | | | | | 13,116.69 |
| Waukesha County | Waukesha County Fleet Maintenance | Motorola | H10UCH6DC5BN | 678SBE0068 | LTS-2000 w/scan | 2.84 |
| Waukesha County | Waukesha County Fleet Maintenance | Motorola | H10UCH6DC5BN | 678SBE0123 | LTS-2000 w/scan | 20.41 |
| Waukesha County | Waukesha County Fleet Maintenance | Motorola | M10UGD6DC5BN | 760SBN0119 | LCS-2000 w/o scan | 0.82 |
| Waukesha County | Waukesha County Fleet Maintenance | Motorola | M10UGD6DC5BN | 760SBN0013 | LCS-2000 w/o scan | 2.49 |
| Waukesha County | Waukesha County Fleet Maintenance | Motorola | M10UGD6DC5BN | 760SBL1223 | LCS-2000 w/o scan | 7.67 |
| Waukesha County | Waukesha County Fleet Maintenance | Motorola | M10UGD6DC5BN | 760SBL1206 | LCS-2000 w/o scan | 12.63 |
| | Waukesha County Fleet Maintenance Total | | | | | 46.86 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3035 | MTS-2000 Model I | 2.45 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3038 | MTS-2000 Model I | 11.57 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3037 | MTS-2000 Model I | 21.79 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3027 | MTS-2000 Model I | 32.50 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3040 | MTS-2000 Model I | 53.38 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3050 | MTS-2000 Model I | 60.91 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3026 | MTS-2000 Model I | 61.51 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4291 | LTS-2000 w/o scan | 0.43 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4330 | LTS-2000 w/o scan | 0.76 |

| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4000 | LTS-2000 w/o scan | 1.10 |
|-----------------|--|----------|--------------|------------|-------------------|--------|
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4342 | LTS-2000 w/o scan | 1.65 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4328 | LTS-2000 w/o scan | 3.53 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4198 | LTS-2000 w/o scan | 4.01 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4047 | LTS-2000 w/o scan | 4.11 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4152 | LTS-2000 w/o scan | 5.34 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4347 | LTS-2000 w/o scan | 5.95 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4327 | LTS-2000 w/o scan | 6.27 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4306 | LTS-2000 w/o scan | 6.47 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4322 | LTS-2000 w/o scan | 6.51 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4258 | LTS-2000 w/o scan | 6.72 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU3987 | LTS-2000 w/o scan | 6.75 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4220 | LTS-2000 w/o scan | 8.64 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4118 | LTS-2000 w/o scan | 8.99 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4323 | LTS-2000 w/o scan | 9.73 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4186 | LTS-2000 w/o scan | 9.87 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4139 | LTS-2000 w/o scan | 10.47 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4144 | LTS-2000 w/o scan | 11.15 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4305 | LTS-2000 w/o scan | 11.45 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4285 | LTS-2000 w/o scan | 12.29 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4289 | LTS-2000 w/o scan | 12.37 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4268 | LTS-2000 w/o scan | 12.44 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4302 | LTS-2000 w/o scan | 13.59 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4290 | LTS-2000 w/o scan | 13.73 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4288 | LTS-2000 w/o scan | 14.57 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4143 | LTS-2000 w/o scan | 15.90 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4160 | LTS-2000 w/o scan | 18.17 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4200 | LTS-2000 w/o scan | 19.38 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAW0133 | LTS-2000 w/o scan | 19.43 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4255 | LTS-2000 w/o scan | 20.19 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4158 | LTS-2000 w/o scan | 21.71 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4082 | LTS-2000 w/o scan | 23.39 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4130 | LTS-2000 w/o scan | 23.40 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4314 | LTS-2000 w/o scan | 25.04 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H10UCH6DC5BN | 678SAU4134 | LTS-2000 w/o scan | 25.70 |
| | Waukesha County Maintenance Department Total | | | | | 665.34 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2847 | LTS-2000 w/scan | 0.48 |

| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2877 | LTS-2000 w/scan | 0.69 |
|-----------------|------------------------------------|----------|--------------|------------|-----------------|-------|
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2815 | LTS-2000 w/scan | 0.74 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2876 | LTS-2000 w/scan | 0.77 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2886 | LTS-2000 w/scan | 1.08 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2827 | LTS-2000 w/scan | 1.09 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2805 | LTS-2000 w/scan | 1.16 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2825 | LTS-2000 w/scan | 1.17 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | h10uch6dc5bn | 678sby6944 | LTS-2000 w/scan | 1.29 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2816 | LTS-2000 w/scan | 1.39 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2724 | LTS-2000 w/scan | 1.67 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2879 | LTS-2000 w/scan | 1.75 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2802 | LTS-2000 w/scan | 1.87 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SEE0151 | LTS-2000 w/scan | 2.23 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2845 | LTS-2000 w/scan | 2.23 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2881 | LTS-2000 w/scan | 2.59 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2891 | LTS-2000 w/scan | 3.92 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2851 | LTS-2000 w/scan | 4.57 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2866 | LTS-2000 w/scan | 4.86 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2882 | LTS-2000 w/scan | 4.89 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2873 | LTS-2000 w/scan | 5.11 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2792 | LTS-2000 w/scan | 6.23 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2853 | LTS-2000 w/scan | 6.28 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2800 | LTS-2000 w/scan | 7.57 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2833 | LTS-2000 w/scan | 8.53 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2837 | LTS-2000 w/scan | 8.62 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SCA1371 | LTS-2000 w/scan | 9.55 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | h10uch6dc5bn | 678scc0523 | LTS-2000 w/scan | 9.94 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2835 | LTS-2000 w/scan | 11.21 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2880 | LTS-2000 w/scan | 11.73 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2717 | LTS-2000 w/scan | 12.00 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2785 | LTS-2000 w/scan | 12.23 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2884 | LTS-2000 w/scan | 12.57 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2859 | LTS-2000 w/scan | 13.69 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2814 | LTS-2000 w/scan | 13.69 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | h10uch6dc5bn | 678scc0527 | LTS-2000 w/scan | 13.76 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2834 | LTS-2000 w/scan | 13.97 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SBY6957 | LTS-2000 w/scan | 14.53 |

| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SBY6955 | LTS-2000 w/scan | 15.11 |
|-----------------|------------------------------------|----------|--------------|------------|-----------------|-------|
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2850 | LTS-2000 w/scan | 15.55 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SCA1411 | LTS-2000 w/scan | 16.79 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2821 | LTS-2000 w/scan | 17.61 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2810 | LTS-2000 w/scan | 18.98 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2818 | LTS-2000 w/scan | 20.38 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2803 | LTS-2000 w/scan | 20.95 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2807 | LTS-2000 w/scan | 21.17 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2856 | LTS-2000 w/scan | 21.98 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2808 | LTS-2000 w/scan | 22.13 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2721 | LTS-2000 w/scan | 22.54 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SCA1384 | LTS-2000 w/scan | 23.43 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2775 | LTS-2000 w/scan | 23.50 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2823 | LTS-2000 w/scan | 23.81 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2868 | LTS-2000 w/scan | 24.21 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2869 | LTS-2000 w/scan | 24.31 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | h10uch6dc5bn | 678sca1417 | LTS-2000 w/scan | 25.40 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2812 | LTS-2000 w/scan | 25.97 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2839 | LTS-2000 w/scan | 28.93 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2822 | LTS-2000 w/scan | 29.29 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2889 | LTS-2000 w/scan | 34.98 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2719 | LTS-2000 w/scan | 37.78 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2836 | LTS-2000 w/scan | 38.85 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2829 | LTS-2000 w/scan | 41.83 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2777 | LTS-2000 w/scan | 42.94 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2860 | LTS-2000 w/scan | 43.90 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2883 | LTS-2000 w/scan | 45.49 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2831 | LTS-2000 w/scan | 46.64 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2867 | LTS-2000 w/scan | 54.40 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SDG0271 | LTS-2000 w/scan | 65.68 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | h10uch6dc5bn | 678sby6939 | LTS-2000 w/scan | 70.54 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H10UCH6DC5BN | 678SAQ2838 | LTS-2000 w/scan | 92.15 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0483 | LCS-2000 w/scan | 0.41 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0610 | LCS-2000 w/scan | 0.70 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0485 | LCS-2000 w/scan | 0.88 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0611 | LCS-2000 w/scan | 1.21 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0498 | LCS-2000 w/scan | 1.22 |

| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0506 | LCS-2000 w/scan | 1.23 |
|-----------------|--|----------|--------------|------------|-----------------------|----------|
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0604 | LCS-2000 w/scan | 1.58 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0488 | LCS-2000 w/scan | 1.78 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0618 | LCS-2000 w/scan | 1.80 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0491 | LCS-2000 w/scan | 2.22 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0595 | LCS-2000 w/scan | 5.28 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0507 | LCS-2000 w/scan | 6.63 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0486 | LCS-2000 w/scan | 8.35 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0620 | LCS-2000 w/scan | 12.07 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0484 | LCS-2000 w/scan | 12.49 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0505 | LCS-2000 w/scan | 21.86 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M10UGD6DC5BN | 760SAW0513 | LCS-2000 w/scan | 130.73 |
| | Waukesha County Parks and Land Use Total | | | | | 1,499.28 |
| Waukesha County | Waukesha County Radio Services | Motorola | H01UCF6PW1BN | 466AAG2587 | MTS-2000 Model II DES | 1.19 |
| Waukesha County | Waukesha County Radio Services | Motorola | H01UCF6PW1BN | 466ABL3292 | MTS-2000 Model II DES | 5.57 |
| Waukesha County | Waukesha County Radio Services | Motorola | H01UCF6PW1BN | 466AAG2588 | MTS-2000 Model II DES | 8.35 |
| Waukesha County | Waukesha County Radio Services | Motorola | H01UCF6PW1BN | 466AAG2589 | MTS-2000 Model II DES | 9.86 |
| Waukesha County | Waukesha County Radio Services | Motorola | M01UGM6PW6BN | 722ABE1283 | MCS-2000 | 3.58 |
| | Waukesha County Radio Services Total | | | | | 28.55 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3629 | MTS-2000 Model I DES | 0.35 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3622 | MTS-2000 Model I DES | 0.37 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3600 | MTS-2000 Model I DES | 0.41 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3474 | MTS-2000 Model I DES | 0.43 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3464 | MTS-2000 Model I DES | 0.44 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3462 | MTS-2000 Model I DES | 0.48 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3584 | MTS-2000 Model I DES | 0.52 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3601 | MTS-2000 Model I DES | 0.72 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3597 | MTS-2000 Model I DES | 0.81 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3467 | MTS-2000 Model I DES | 0.81 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3621 | MTS-2000 Model I DES | 0.83 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3476 | MTS-2000 Model I DES | 1.22 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3618 | MTS-2000 Model I DES | 1.34 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABS3058 | MTS-2000 Model I | 2.14 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABS3064 | MTS-2000 Model I | 2.85 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3626 | MTS-2000 Model I DES | 2.91 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3599 | MTS-2000 Model I DES | 3.06 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3477 | MTS-2000 Model I DES | 4.53 |

| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3630 | MTS-2000 Model I DES | 5.48 |
|-----------------|------------------------------------|----------|--------------|------------|----------------------|-------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3631 | MTS-2000 Model I DES | 5.98 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3471 | MTS-2000 Model I DES | 7.31 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3602 | MTS-2000 Model I DES | 7.76 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3473 | MTS-2000 Model I DES | 8.71 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3623 | MTS-2000 Model I DES | 8.95 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3588 | MTS-2000 Model I DES | 8.96 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3620 | MTS-2000 Model I DES | 9.39 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3586 | MTS-2000 Model I DES | 9.51 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3587 | MTS-2000 Model I DES | 9.84 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3594 | MTS-2000 Model I DES | 10.07 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3615 | MTS-2000 Model I DES | 10.23 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3595 | MTS-2000 Model I DES | 10.33 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3627 | MTS-2000 Model I DES | 12.00 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3466 | MTS-2000 Model I DES | 12.32 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABS3065 | MTS-2000 Model I | 14.13 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3465 | MTS-2000 Model I DES | 14.30 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3603 | MTS-2000 Model I DES | 14.47 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3585 | MTS-2000 Model I DES | 14.55 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABS3055 | MTS-2000 Model I | 15.94 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3614 | MTS-2000 Model I DES | 17.23 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3593 | MTS-2000 Model I DES | 19.49 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3461 | MTS-2000 Model I DES | 21.03 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3475 | MTS-2000 Model I DES | 22.18 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABS3066 | MTS-2000 Model I | 22.81 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3591 | MTS-2000 Model I DES | 36.08 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABS3042 | MTS-2000 Model I | 41.71 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCF6PW1BN | 466ABW4079 | MTS-2000 Model II | 0.49 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCF6PW1BN | 466ABW5072 | MTS-2000 Model II | 48.71 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ0897 | LTS-2000 w/scan | 0.37 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1055 | LTS-2000 w/scan | 0.38 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ2757 | LTS-2000 w/scan | 1.07 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1139 | LTS-2000 w/scan | 1.39 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SBY6948 | LTS-2000 w/scan | 1.42 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ2759 | LTS-2000 w/scan | 1.80 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1046 | LTS-2000 w/scan | 1.97 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1092 | LTS-2000 w/scan | 2.47 |

| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ2599 | LTS-2000 w/scan | 2.81 |
|-----------------|------------------------------------|----------|--------------|------------|-----------------|-------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1045 | LTS-2000 w/scan | 3.27 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ0898 | LTS-2000 w/scan | 4.13 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | h10uch6dc5bn | 678sce0808 | LTS-2000 w/scan | 4.23 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1587 | LTS-2000 w/scan | 5.36 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1090 | LTS-2000 w/scan | 5.52 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1048 | LTS-2000 w/scan | 5.67 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | h10uch6dc5bn | 678scc0406 | LTS-2000 w/scan | 6.01 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SBA0641 | LTS-2000 w/scan | 7.84 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SCE0822 | LTS-2000 w/scan | 8.09 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SBA0586 | LTS-2000 w/scan | 8.26 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ2755 | LTS-2000 w/scan | 9.23 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SBA0552 | LTS-2000 w/scan | 9.72 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1105 | LTS-2000 w/scan | 10.23 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1054 | LTS-2000 w/scan | 10.25 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1096 | LTS-2000 w/scan | 10.63 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1050 | LTS-2000 w/scan | 10.85 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SBA0639 | LTS-2000 w/scan | 11.28 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | h10uch6dc5bn | 678scc0451 | LTS-2000 w/scan | 12.53 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ0828 | LTS-2000 w/scan | 13.05 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1079 | LTS-2000 w/scan | 13.54 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ2663 | LTS-2000 w/scan | 13.55 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ2756 | LTS-2000 w/scan | 13.86 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SBA0644 | LTS-2000 w/scan | 14.09 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1099 | LTS-2000 w/scan | 14.82 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ0919 | LTS-2000 w/scan | 15.00 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1087 | LTS-2000 w/scan | 16.34 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SBA0538 | LTS-2000 w/scan | 17.27 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SBA0562 | LTS-2000 w/scan | 17.48 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SBA0645 | LTS-2000 w/scan | 18.08 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SBA0555 | LTS-2000 w/scan | 18.13 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SCE0750 | LTS-2000 w/scan | 19.07 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ2682 | LTS-2000 w/scan | 20.23 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SBA0634 | LTS-2000 w/scan | 20.69 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1085 | LTS-2000 w/scan | 21.31 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ0895 | LTS-2000 w/scan | 27.63 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H10UCH6DC5BN | 678SAQ1058 | LTS-2000 w/scan | 32.45 |

| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4993 | XTS-5000 Model II | 1.92 |
|-----------------|------------------------------------|----------|--------------|------------|-------------------|-------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0132 | XTS-5000 Model II | 2.03 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CFX2226 | XTS-5000 Model II | 2.77 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5000 | XTS-5000 Model II | 3.61 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4991 | XTS-5000 Model II | 4.68 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEA5005 | XTS-5000 Model II | 4.71 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0122 | XTS-5000 Model II | 6.94 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5004 | XTS-5000 Model II | 7.51 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5006 | XTS-5000 Model II | 7.83 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0211 | XTS-5000 Model II | 9.15 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CFX2219 | XTS-5000 Model II | 9.19 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CFX2223 | XTS-5000 Model II | 9.19 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5008 | XTS-5000 Model II | 10.00 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5002 | XTS-5000 Model II | 10.20 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4990 | XTS-5000 Model II | 10.64 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4999 | XTS-5000 Model II | 11.11 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5009 | XTS-5000 Model II | 12.27 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0208 | XTS-5000 Model II | 13.88 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5001 | XTS-5000 Model II | 13.99 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0133 | XTS-5000 Model II | 14.49 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4995 | XTS-5000 Model II | 14.89 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4992 | XTS-5000 Model II | 14.99 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4998 | XTS-5000 Model II | 15.18 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0205 | XTS-5000 Model II | 15.33 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0212 | XTS-5000 Model II | 16.11 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0141 | XTS-5000 Model II | 16.63 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0129 | XTS-5000 Model II | 16.73 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0125 | XTS-5000 Model II | 17.21 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CFX2225 | XTS-5000 Model II | 18.86 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4996 | XTS-5000 Model II | 19.59 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5003 | XTS-5000 Model II | 20.15 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0128 | XTS-5000 Model II | 20.56 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0138 | XTS-5000 Model II | 20.76 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CFX2224 | XTS-5000 Model II | 21.57 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4997 | XTS-5000 Model II | 24.73 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0137 | XTS-5000 Model II | 24.91 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CFX2221 | XTS-5000 Model II | 28.27 |

| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CFX2222 | XTS-5000 Model II | 28.95 |
|-----------------|------------------------------------|----------|--------------|------------|-------------------|--------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4994 | XTS-5000 Model II | 29.79 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4989 | XTS-5000 Model II | 30.15 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0124 | XTS-5000 Model II | 36.20 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1440 | MCS-2000 DES | 0.87 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1447 | MCS-2000 DES | 2.19 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1437 | MCS-2000 DES | 2.21 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1442 | MCS-2000 DES | 3.33 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1451 | MCS-2000 DES | 3.39 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABS1463 | MCS-2000 DES | 4.64 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1443 | MCS-2000 DES | 5.77 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1445 | MCS-2000 DES | 6.05 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1306 | MCS-2000 | 7.13 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1439 | MCS-2000 DES | 9.93 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1452 | MCS-2000 DES | 13.25 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1450 | MCS-2000 DES | 16.49 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1278 | MCS-2000 | 24.72 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1267 | MCS-2000 | 29.57 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1315 | MCS-2000 | 31.94 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1312 | MCS-2000 | 32.86 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1280 | MCS-2000 | 34.28 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1303 | MCS-2000 | 36.29 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1285 | MCS-2000 | 38.10 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1275 | MCS-2000 | 41.39 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1295 | MCS-2000 | 49.11 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1270 | MCS-2000 | 52.81 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1284 | MCS-2000 | 53.77 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1277 | MCS-2000 | 71.07 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1273 | MCS-2000 | 95.64 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ACJ2590 | MCS-2000 | 96.15 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1298 | MCS-2000 | 97.23 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1279 | MCS-2000 | 109.89 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1274 | MCS-2000 | 120.45 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1282 | MCS-2000 | 126.11 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1305 | MCS-2000 | 134.67 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1304 | MCS-2000 | 149.75 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1281 | MCS-2000 | 162.95 |

| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1286 | MCS-2000 | 163.69 |
|-----------------|---|----------|--------------|------------|-------------------|----------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1268 | MCS-2000 | 173.51 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1272 | MCS-2000 | 175.05 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1276 | MCS-2000 | 177.17 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1311 | MCS-2000 | 177.79 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1308 | MCS-2000 | 187.83 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1290 | MCS-2000 | 214.39 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1271 | MCS-2000 | 234.65 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UJM6PW6AN | 722AYE2516 | MCS-2000 | 86.51 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0720 | LCS-2000 w/scan | 0.40 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0809 | LCS-2000 w/scan | 0.73 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0609 | LCS-2000 w/scan | 0.83 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0812 | LCS-2000 w/scan | 0.88 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SAYFM68 | LCS-2000 w/scan | 0.91 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0760 | LCS-2000 w/scan | 0.91 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0759 | LCS-2000 w/scan | 1.06 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0776 | LCS-2000 w/scan | 1.13 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0834 | LCS-2000 w/scan | 1.56 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0818 | LCS-2000 w/scan | 2.13 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0631 | LCS-2000 w/scan | 2.35 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0714 | LCS-2000 w/scan | 2.40 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0566 | LCS-2000 w/scan | 2.63 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0767 | LCS-2000 w/scan | 2.97 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SAYFM74 | LCS-2000 w/scan | 3.69 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0704 | LCS-2000 w/scan | 5.59 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0821 | LCS-2000 w/scan | 6.00 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0754 | LCS-2000 w/scan | 6.25 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0770 | LCS-2000 w/scan | 7.47 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0737 | LCS-2000 w/scan | 8.17 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SAYFM64 | LCS-2000 w/scan | 8.34 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0698 | LCS-2000 w/scan | 8.71 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0749 | LCS-2000 w/scan | 10.73 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0709 | LCS-2000 w/scan | 15.53 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0717 | LCS-2000 w/scan | 22.53 |
| | Waukesha County Sheriff Department Total | | | | | 4,943.69 |
| Waukesha County | Waukesha County Transportation Department | Motorola | H10UCH6DC5BN | 678SBE1861 | LTS-2000 w/o scan | 0.69 |
| Waukesha County | Waukesha County Transportation Department | Motorola | H10UCH6DC5BN | 678SBE1889 | LTS-2000 w/o scan | 1.15 |

| Waukesha County | Waukesha County Transportation Department | Motorola | M01UGM6PW6BN | 722ABS1442 | MCS-2000 | 1.21 |
|-----------------|---|----------|--------------|------------|-----------------------|-------|
| Waukesha County | Waukesha County Transportation Department | Motorola | M01UGM6PW6BN | 722ABS1451 | MCS-2000 Control Base | 13.29 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0444 | LCS-2000 w/o scan | 0.35 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0341 | LCS-2000 w/o scan | 0.35 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0250 | LCS-2000 w/o scan | 0.35 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0342 | LCS-2000 w/o scan | 0.36 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0401 | LCS-2000 w/o scan | 0.37 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0304 | LCS-2000 w/o scan | 0.37 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SCA0292 | LCS-2000 w/o scan | 0.37 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0344 | LCS-2000 w/o scan | 0.39 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0302 | LCS-2000 w/o scan | 0.39 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0297 | LCS-2000 w/o scan | 0.40 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0352 | LCS-2000 w/o scan | 0.40 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0378 | LCS-2000 w/o scan | 0.41 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0217 | LCS-2000 w/o scan | 0.42 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0209 | LCS-2000 w/o scan | 0.43 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0350 | LCS-2000 w/o scan | 0.47 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0219 | LCS-2000 w/o scan | 0.49 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0242 | LCS-2000 w/o scan | 0.68 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0104 | LCS-2000 w/o scan | 0.69 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0369 | LCS-2000 w/o scan | 0.70 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0259 | LCS-2000 w/o scan | 0.73 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0278 | LCS-2000 w/o scan | 0.77 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0211 | LCS-2000 w/o scan | 0.83 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0287 | LCS-2000 w/o scan | 0.84 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0100 | LCS-2000 w/o scan | 0.85 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0296 | LCS-2000 w/o scan | 1.11 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0397 | LCS-2000 w/o scan | 1.15 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0249 | LCS-2000 w/o scan | 1.16 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0254 | LCS-2000 w/o scan | 1.19 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0459 | LCS-2000 w/o scan | 1.42 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0337 | LCS-2000 w/o scan | 1.49 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0323 | LCS-2000 w/o scan | 1.49 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0379 | LCS-2000 w/o scan | 1.79 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0349 | LCS-2000 w/o scan | 2.06 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0213 | LCS-2000 w/o scan | 2.39 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0228 | LCS-2000 w/o scan | 2.97 |

| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0348 | LCS-2000 w/o scan | 3.09 |
|----------------------------------|---|-----------|-----------------|-------------|---------------------|-----------|
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0368 | LCS-2000 w/o scan | 3.16 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0277 | LCS-2000 w/o scan | 3.17 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0267 | LCS-2000 w/o scan | 3.33 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0027 | LCS-2000 w/o scan | 3.64 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0290 | LCS-2000 w/o scan | 3.75 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0084 | LCS-2000 w/o scan | 5.22 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M10UGD6DC5BN | 760SBN0293 | LCS-2000 w/o scan | 7.96 |
| Wadiosha County | Waukesha County Transportation Department Total | Wiotoroia | WITOOGBODOOBIN | 7000B110200 | 200 2000 W/O 000H | 80.25 |
| Waukesha County Total | Transportation Soparation (Car | | | | | 20,380.65 |
| Waukesha Memorial Hospital | Waukesha Memorial Hospital | Motorola | L04UJH9PW9AN | 761ABQ2247 | Base, low power | 29.97 |
| Waddoona Wernenar Floophar | Waukesha Memorial Hospital Total | Wiotoroia | LOTOGRADI WOTAN | 70171DQLL47 | Base, low power | 29.97 |
| Waukesha Memorial Hospital Total | Transcola memoria ricoptar rotal | | | | | 29.97 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H10UCH6DC5BN | 678SAU3830 | LTS-2000 w/o scan | 1.91 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H10UCH6DC5BN | 678SAU3838 | LTS-2000 w/o scan | 2.17 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H10UCH6DC5BN | 678SAW0182 | LTS-2000 w/o scan | 3.97 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H10UCH6DC5BN | 678SAU2804 | LTS-2000 w/o scan | 4.57 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H10UCH6DC5BN | 678SAW0183 | LTS-2000 w/o scan | 5.04 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H10UCH6DC5BN | 678SCA1187 | LTS-2000 w/o scan | 6.69 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H10UCH6DC5BN | 678SAU3960 | LTS-2000 w/o scan | 10.11 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H10UCH6DC5BN | 678SAW0181 | LTS-2000 w/o scan | 18.35 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H10UCH6DC5BN | 678SAU2761 | LTS-2000 w/o scan | 39.50 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | M10UGD6DC5BN | 760SAW0246 | LCS-2000 w/o scan | 0.45 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | M10UGD6DC5BN | 760SAW0253 | LCS-2000 w/o scan | 1.09 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | M10UGD6DC5BN | 760SAW0277 | LCS-2000 w/o scan | 2.15 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | M10UGD6DC5BN | 760SAW0265 | LCS-2000 w/o scan | 2.34 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | M10UGD6DC5BN | 760SAW0248 | LCS-2000 w/o scan | 2.77 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | M10UGD6DC5BN | 760SAS3892 | LCS-2000 w/o scan | 4.57 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | M10UGD6DC5BN | 760SAW0279 | LCS-2000 w/o scan | 5.88 |
| | Waukesha City Engineering Department Total | | | | | 111.54 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0741 | MTS-2000 Model I | 0.34 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0781 | MTS-2000 Model I | 0.39 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0753 | MTS-2000 Model I | 0.45 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0751 | MTS-2000 Model I | 0.70 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466CFA0330 | MTS-2000 Model I FM | 0.95 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0775 | MTS-2000 Model I | 1.43 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0934 | MTS-2000 Model I | 1.86 |

| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466CFA0329 | MTS-2000 Model I FM | 2.25 |
|----------------|-------------------------------|----------|--------------|------------|---------------------|-------|
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466CFA0327 | MTS-2000 Model I FM | 2.64 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0768 | MTS-2000 Model I | 3.31 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0758 | MTS-2000 Model I | 3.91 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0933 | MTS-2000 Model I | 5.37 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0777 | MTS-2000 Model I | 8.43 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0778 | MTS-2000 Model I | 9.28 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466CEJ0367 | MTS-2000 Model I | 10.67 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0754 | MTS-2000 Model I | 11.62 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0743 | MTS-2000 Model I | 12.45 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0746 | MTS-2000 Model I | 13.33 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0930 | MTS-2000 Model I | 13.39 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466CFA0331 | MTS-2000 Model I FM | 14.63 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466CFA0332 | MTS-2000 Model I FM | 14.72 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0740 | MTS-2000 Model I | 14.88 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0755 | MTS-2000 Model I | 16.52 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H01UCD6PW1BN | 466CFA0328 | MTS-2000 Model I FM | 38.81 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1419 | MCS-2000 | 0.49 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722CDJ1207 | MCS-2000 | 4.57 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722CDJ1212 | MCS-2000 | 5.48 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722CDJ1209 | MCS-2000 | 17.16 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722CFA0321 | MCS-2000 | 43.33 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1389 | MCS-2000 | 48.35 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1387 | MCS-2000 | 68.57 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1426 | MCS-2000 | 87.91 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SAYFJ91 | LCS-2000 w/scan | 0.36 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SBA0593 | LCS-2000 w/scan | 0.71 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SBA0750 | LCS-2000 w/scan | 1.76 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SAYFK76 | LCS-2000 w/scan | 1.83 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SBA0781 | LCS-2000 w/scan | 2.04 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SAYFJ87 | LCS-2000 w/scan | 2.23 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SAYFK66 | LCS-2000 w/scan | 2.79 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SAYFL59 | LCS-2000 w/scan | 2.80 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SAYFK54 | LCS-2000 w/scan | 4.62 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SBA0802 | LCS-2000 w/scan | 11.55 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SAYFL67 | LCS-2000 w/scan | 12.91 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SBA0794 | LCS-2000 w/scan | 27.87 |

| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SBA0789 | LCS-2000 w/scan | 40.18 |
|----------------|-------------------------------------|----------|--------------|------------|-------------------|--------|
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SAYFK13 | LCS-2000 w/scan | 51.22 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SAYFL60 | LCS-2000 w/scan | 52.97 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SAYFL69 | LCS-2000 w/scan | 72.21 |
| | Waukesha City Fire Department Total | | | | | 766.25 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | H10UCH6DC5BN | 678SAW0129 | LTS-2000 w/o scan | 6.35 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | H10UCH6DC5BN | 678SAW0128 | LTS-2000 w/o scan | 86.93 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | H10UCH6DC5BN | 678SAW0149 | LTS-2000 w/o scan | 95.47 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | H10UCH6DC5BN | 678SAW0125 | LTS-2000 w/o scan | 109.48 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | H10UCH6DC5BN | 678SAW0111 | LTS-2000 w/o scan | 112.35 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1402 | LCS-2000 w/o scan | 0.35 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1330 | LCS-2000 w/o scan | 0.49 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1284 | LCS-2000 w/o scan | 2.69 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1265 | LCS-2000 w/o scan | 6.20 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1424 | LCS-2000 w/o scan | 10.29 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1341 | LCS-2000 w/o scan | 10.93 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1379 | LCS-2000 w/o scan | 11.27 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1389 | LCS-2000 w/o scan | 11.75 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1372 | LCS-2000 w/o scan | 12.11 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1391 | LCS-2000 w/o scan | 15.21 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1327 | LCS-2000 w/o scan | 17.32 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1396 | LCS-2000 w/o scan | 20.36 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1404 | LCS-2000 w/o scan | 20.81 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1413 | LCS-2000 w/o scan | 21.41 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1334 | LCS-2000 w/o scan | 31.07 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1398 | LCS-2000 w/o scan | 32.48 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1397 | LCS-2000 w/o scan | 35.99 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1429 | LCS-2000 w/o scan | 36.08 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1335 | LCS-2000 w/o scan | 36.62 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1387 | LCS-2000 w/o scan | 38.75 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1425 | LCS-2000 w/o scan | 39.62 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1403 | LCS-2000 w/o scan | 39.77 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1414 | LCS-2000 w/o scan | 43.29 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1370 | LCS-2000 w/o scan | 43.45 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1333 | LCS-2000 w/o scan | 44.13 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1416 | LCS-2000 w/o scan | 44.34 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1392 | LCS-2000 w/o scan | 44.63 |

| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1367 | LCS-2000 w/o scan | 45.85 |
|----------------|--|----------|--------------|------------|-------------------|----------|
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1412 | LCS-2000 w/o scan | 47.45 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1423 | LCS-2000 w/o scan | 47.47 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1332 | LCS-2000 w/o scan | 49.73 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1436 | LCS-2000 w/o scan | 52.35 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1385 | LCS-2000 w/o scan | 55.04 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M10UGD6DC5BN | 760SAW1383 | LCS-2000 w/o scan | 55.84 |
| | Waukesha City Metro Transit System Total | | | | | 1,435.67 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4231 | LTS-2000 w/o scan | 1.55 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SCE1006 | LTS-2000 w/scan | 1.93 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4250 | LTS-2000 w/o scan | 2.01 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4240 | LTS-2000 w/o scan | 2.51 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4241 | LTS-2000 w/o scan | 2.81 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4218 | LTS-2000 w/o scan | 2.85 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4214 | LTS-2000 w/o scan | 2.95 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4238 | LTS-2000 w/o scan | 9.01 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4243 | LTS-2000 w/o scan | 15.57 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4216 | LTS-2000 w/o scan | 20.84 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4203 | LTS-2000 w/o scan | 21.77 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4205 | LTS-2000 w/o scan | 25.21 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4242 | LTS-2000 w/o scan | 30.01 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4217 | LTS-2000 w/o scan | 34.88 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4213 | LTS-2000 w/o scan | 37.69 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4284 | LTS-2000 w/o scan | 49.93 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1253 | LCS-2000 w/o scan | 0.45 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0073 | LCS-2000 w/o scan | 0.50 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1149 | LCS-2000 w/o scan | 0.50 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1323 | LCS-2000 w/o scan | 0.71 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0064 | LCS-2000 w/o scan | 0.84 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1151 | LCS-2000 w/o scan | 0.85 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1252 | LCS-2000 w/o scan | 1.14 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SCL0683 | LCS-2000 w/o scan | 1.42 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0062 | LCS-2000 w/o scan | 1.58 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1255 | LCS-2000 w/o scan | 2.04 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1169 | LCS-2000 w/o scan | 2.28 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0045 | LCS-2000 w/o scan | 2.39 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1177 | LCS-2000 w/o scan | 2.63 |

| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1363 | LCS-2000 w/o scan | 3.53 |
|----------------|--|----------|--------------|------------|-------------------|--------|
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1138 | LCS-2000 w/o scan | 3.64 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1257 | LCS-2000 w/o scan | 3.87 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1251 | LCS-2000 w/o scan | 3.91 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1254 | LCS-2000 w/o scan | 3.99 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1362 | LCS-2000 w/o scan | 4.25 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1368 | LCS-2000 w/o scan | 4.45 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SBS0341 | LCS-2000 w/scan | 4.95 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1201 | LCS-2000 w/o scan | 5.15 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1263 | LCS-2000 w/o scan | 6.18 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0058 | LCS-2000 w/o scan | 6.29 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0082 | LCS-2000 w/o scan | 6.30 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1200 | LCS-2000 w/o scan | 6.42 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | m10ugd6dc5bn | 760scu0090 | LCS-2000 w/o scan | 6.47 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0079 | LCS-2000 w/o scan | 7.09 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1359 | LCS-2000 w/o scan | 7.27 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SBE0470 | LCS-2000 w/o scan | 8.84 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1165 | LCS-2000 w/o scan | 9.73 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1159 | LCS-2000 w/o scan | 9.81 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0080 | LCS-2000 w/o scan | 10.44 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SBE0570 | LCS-2000 w/o scan | 11.72 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0063 | LCS-2000 w/o scan | 12.21 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0060 | LCS-2000 w/o scan | 17.00 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1256 | LCS-2000 w/o scan | 32.97 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1225 | LCS-2000 w/o scan | 36.19 |
| | Waukesha City Park and Recreation Department Total | | | | | 511.50 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4995 | MTS-2000 Model I | 0.43 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4912 | MTS-2000 Model I | 0.45 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4878 | MTS-2000 Model I | 0.70 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4927 | MTS-2000 Model I | 0.73 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4796 | MTS-2000 Model I | 0.74 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4875 | MTS-2000 Model I | 0.77 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4891 | MTS-2000 Model I | 0.81 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4887 | MTS-2000 Model I | 0.83 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4877 | MTS-2000 Model I | 1.37 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4893 | MTS-2000 Model I | 1.47 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4895 | MTS-2000 Model I | 1.53 |

| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE5010 | MTS-2000 Model I | 1.81 |
|----------------|---------------------------------|----------|--------------|------------|----------------------|-------|
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4794 | MTS-2000 Model I | 2.04 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4991 | MTS-2000 Model I | 2.32 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4896 | MTS-2000 Model I | 2.53 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4902 | MTS-2000 Model I DES | 2.53 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE5008 | MTS-2000 Model I | 2.57 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4870 | MTS-2000 Model I | 2.75 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4916 | MTS-2000 Model I DES | 3.69 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4922 | MTS-2000 Model I DES | 3.80 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4879 | MTS-2000 Model I | 4.77 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4874 | MTS-2000 Model I | 5.36 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE5009 | MTS-2000 Model I | 6.15 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4793 | MTS-2000 Model I | 8.02 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4915 | MTS-2000 Model I DES | 8.71 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE5004 | MTS-2000 Model I DES | 9.47 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4861 | MTS-2000 Model I | 10.33 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4805 | MTS-2000 Model I | 11.29 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4830 | MTS-2000 Model I | 11.89 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4932 | MTS-2000 Model I | 12.03 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4993 | MTS-2000 Model I DES | 12.04 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4844 | MTS-2000 Model I | 13.13 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4994 | MTS-2000 Model I | 14.33 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4810 | MTS-2000 Model I | 14.53 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4814 | MTS-2000 Model I | 20.43 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE5007 | MTS-2000 Model I | 21.64 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4868 | MTS-2000 Model I | 22.94 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4817 | MTS-2000 Model I | 25.79 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4996 | MTS-2000 Model I | 25.91 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4824 | MTS-2000 Model I | 25.92 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4860 | MTS-2000 Model I | 26.69 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4797 | MTS-2000 Model I | 27.39 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4997 | MTS-2000 Model I | 31.63 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4998 | MTS-2000 Model I | 36.02 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4799 | MTS-2000 Model I | 37.65 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4815 | MTS-2000 Model I | 39.38 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4825 | MTS-2000 Model I | 42.03 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4841 | MTS-2000 Model I | 42.31 |

| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4835 | MTS-2000 Model I | 46.88 |
|----------------|---------------------------------|----------|--------------|------------|-----------------------|----------|
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4806 | MTS-2000 Model I | 47.28 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4795 | MTS-2000 Model I | 47.31 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4834 | MTS-2000 Model I | 47.67 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4800 | MTS-2000 Model I | 49.13 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4910 | MTS-2000 Model I | 49.62 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4792 | MTS-2000 Model I | 57.59 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4865 | MTS-2000 Model I | 58.01 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4803 | MTS-2000 Model I | 58.34 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4857 | MTS-2000 Model I | 61.40 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4804 | MTS-2000 Model I | 64.78 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4802 | MTS-2000 Model I | 66.35 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4849 | MTS-2000 Model I | 66.79 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4911 | MTS-2000 Model I | 67.06 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4818 | MTS-2000 Model I | 68.33 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4816 | MTS-2000 Model I | 68.97 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4992 | MTS-2000 Model I | 69.38 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4842 | MTS-2000 Model I | 73.33 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4820 | MTS-2000 Model I | 76.11 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4859 | MTS-2000 Model I | 84.74 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGL6PW4BN | 722ABE0568 | MCS-2000 Control Base | 17.71 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGL6PW4BN | 722ABE0570 | MCS-2000 Control Base | 409.85 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGL6PW4BN | 722ABE0572 | MCS-2000 Control Base | 3,336.63 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1424 | MCS-2000 | 4.40 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1430 | MCS-2000 | 24.74 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1434 | MCS-2000 | 28.83 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1417 | MCS-2000 | 48.16 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1425 | MCS-2000 | 53.69 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1416 | MCS-2000 | 55.39 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1409 | MCS-2000 | 67.86 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1432 | MCS-2000 | 72.36 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1405 | MCS-2000 | 92.83 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1388 | MCS-2000 | 114.33 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1431 | MCS-2000 | 142.52 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1410 | MCS-2000 | 149.93 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1435 | MCS-2000 | 162.71 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1390 | MCS-2000 | 173.90 |

| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1412 | MCS-2000 | 187.79 |
|----------------|---------------------------------------|----------|--------------|------------|-------------------|----------|
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1422 | MCS-2000 | 209.15 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1391 | MCS-2000 | 213.69 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1401 | MCS-2000 | 215.33 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1415 | MCS-2000 | 217.26 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1414 | MCS-2000 | 222.43 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1428 | MCS-2000 | 226.29 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1396 | MCS-2000 | 233.78 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1394 | MCS-2000 | 259.25 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFK69 | LCS-2000 w/scan | 0.73 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFK85 | LCS-2000 w/scan | 1.39 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFK48 | LCS-2000 w/scan | 1.92 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFJ96 | LCS-2000 w/scan | 3.51 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFK11 | LCS-2000 w/scan | 5.61 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFJ85 | LCS-2000 w/scan | 7.45 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFJ76 | LCS-2000 w/scan | 8.66 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFK62 | LCS-2000 w/scan | 9.38 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFL63 | LCS-2000 w/scan | 9.46 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFL66 | LCS-2000 w/scan | 9.89 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFJ75 | LCS-2000 w/scan | 11.63 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFJ81 | LCS-2000 w/scan | 14.62 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFK42 | LCS-2000 w/scan | 14.89 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFL68 | LCS-2000 w/scan | 16.67 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFK20 | LCS-2000 w/scan | 20.72 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFK55 | LCS-2000 w/scan | 23.21 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFK51 | LCS-2000 w/scan | 24.23 |
| | Waukesha City Police Department Total | | | | | 8,955.43 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H01UCD6PW1BN | 466ABA1023 | MTS-2000 Model I | 2.70 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H01UCD6PW1BN | 466ABA1024 | MTS-2000 Model I | 10.57 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H01UCD6PW1BN | 466ABA1025 | MTS-2000 Model I | 49.09 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H10UCH6DC5BN | 678SAU4135 | LTS-2000 w/o scan | 0.51 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H10UCH6DC5BN | 678SAU4123 | LTS-2000 w/o scan | 1.03 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H10UCH6DC5BN | 678SAQ2776 | LTS-2000 w/scan | 2.13 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H10UCH6DC5BN | 678SAU4197 | LTS-2000 w/o scan | 3.92 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H10UCH6DC5BN | 678SAU4092 | LTS-2000 w/o scan | 13.01 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H10UCH6DC5BN | 678SAU4096 | LTS-2000 w/o scan | 22.86 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H10UCH6DC5BN | 678SAQ2783 | LTS-2000 w/scan | 31.75 |

| Waukesha, City | Waukesha City Public Works Department | Motorola | H10UCH6DC5BN | 678SAU4149 | LTS-2000 w/o scan | 35.33 |
|----------------|---------------------------------------|----------|--------------|------------|-------------------|-------|
| Waukesha, City | Waukesha City Public Works Department | Motorola | H10UCH6DC5BN | 678SAU4090 | LTS-2000 w/o scan | 40.87 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1250 | LCS-2000 w/o scan | 0.35 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1191 | LCS-2000 w/o scan | 0.38 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1433 | LCS-2000 w/o scan | 0.42 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1239 | LCS-2000 w/o scan | 0.46 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1432 | LCS-2000 w/o scan | 0.67 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEY58 | LCS-2000 w/o scan | 0.68 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1411 | LCS-2000 w/o scan | 0.73 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1237 | LCS-2000 w/o scan | 0.73 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1375 | LCS-2000 w/o scan | 0.75 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1431 | LCS-2000 w/o scan | 1.44 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1442 | LCS-2000 w/o scan | 1.50 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1277 | LCS-2000 w/o scan | 1.57 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1419 | LCS-2000 w/o scan | 1.59 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1388 | LCS-2000 w/o scan | 1.67 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1417 | LCS-2000 w/o scan | 1.69 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0241 | LCS-2000 w/o scan | 2.05 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ77 | LCS-2000 w/o scan | 2.30 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1234 | LCS-2000 w/o scan | 2.31 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ48 | LCS-2000 w/o scan | 2.65 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1300 | LCS-2000 w/o scan | 2.74 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1406 | LCS-2000 w/o scan | 2.81 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1203 | LCS-2000 w/o scan | 2.81 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1435 | LCS-2000 w/o scan | 2.95 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1324 | LCS-2000 w/o scan | 3.24 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1281 | LCS-2000 w/o scan | 3.58 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1280 | LCS-2000 w/o scan | 3.58 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1420 | LCS-2000 w/o scan | 3.66 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1434 | LCS-2000 w/o scan | 3.83 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1193 | LCS-2000 w/o scan | 3.96 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1438 | LCS-2000 w/o scan | 4.60 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1189 | LCS-2000 w/o scan | 4.61 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1283 | LCS-2000 w/o scan | 4.64 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1104 | LCS-2000 w/o scan | 4.86 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1285 | LCS-2000 w/o scan | 5.53 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1291 | LCS-2000 w/o scan | 5.69 |

| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1399 | LCS-2000 w/o scan | 5.82 |
|----------------|---|----------|--------------|------------|-------------------|--------|
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1428 | LCS-2000 w/o scan | 5.91 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1182 | LCS-2000 w/o scan | 6.13 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1279 | LCS-2000 w/o scan | 8.40 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1171 | LCS-2000 w/o scan | 8.65 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1400 | LCS-2000 w/o scan | 8.73 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1366 | LCS-2000 w/o scan | 9.37 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1212 | LCS-2000 w/o scan | 11.95 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1369 | LCS-2000 w/o scan | 14.70 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1232 | LCS-2000 w/o scan | 14.97 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1209 | LCS-2000 w/o scan | 16.05 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0515 | LCS-2000 w/scan | 20.55 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0535 | LCS-2000 w/scan | 22.49 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1373 | LCS-2000 w/o scan | 30.71 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0514 | LCS-2000 w/scan | 31.99 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M28URS9PW1AN | 775TFS0160 | XTL-1500 Mobile | 5.51 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M28URS9PW1AN | 775TFS0152 | XTL-1500 Mobile | 6.31 |
| | Waukesha City Public Works Department Total | | | | | 529.03 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW1572 | LTS-2000 w/o scan | 0.35 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAYDV97 | LTS-2000 w/o scan | 1.09 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW1567 | LTS-2000 w/o scan | 1.27 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW1534 | LTS-2000 w/o scan | 1.36 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW1564 | LTS-2000 w/o scan | 1.41 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SEL1206 | LTS-2000 w/o scan | 1.47 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW1558 | LTS-2000 w/o scan | 1.49 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAYDV95 | LTS-2000 w/o scan | 1.83 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW1579 | LTS-2000 w/o scan | 1.87 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW2405 | LTS-2000 w/o scan | 2.08 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW1580 | LTS-2000 w/o scan | 2.18 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SDS0380 | LTS-2000 w/o scan | 2.63 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW1542 | LTS-2000 w/o scan | 2.93 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW1541 | LTS-2000 w/o scan | 2.94 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAYDV77 | LTS-2000 w/o scan | 3.49 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW1543 | LTS-2000 w/o scan | 5.13 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW2406 | LTS-2000 w/o scan | 5.39 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H10UCH6DC5BN | 678SAW1545 | LTS-2000 w/o scan | 7.02 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | M10UGD6DC5BN | 760SAYEZ92 | LCS-2000 w/o scan | 0.70 |

| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | M10UGD6DC5BN | 760SAYEY52 | LCS-2000 w/o scan | 1.23 |
|----------------------|--|----------|--------------|------------|---------------------|-----------|
| | Waukesha City Wastewater Treatment Plant Total | | | | | 47.83 |
| Waukesha, City | Waukesha City Water Utility | Motorola | H10UCH6DC5BN | 678SAW1570 | LTS-2000 w/o scan | 0.46 |
| Waukesha, City | Waukesha City Water Utility | Motorola | H10UCH6DC5BN | 678SAW1555 | LTS-2000 w/o scan | 0.49 |
| Waukesha, City | Waukesha City Water Utility | Motorola | H10UCH6DC5BN | 678SAW1547 | LTS-2000 w/o scan | 0.68 |
| Waukesha, City | Waukesha City Water Utility | Motorola | H10UCH6DC5BN | 678SAYDV85 | LTS-2000 w/o scan | 1.28 |
| Waukesha, City | Waukesha City Water Utility | Motorola | H10UCH6DC5BN | 678SAYDV90 | LTS-2000 w/o scan | 1.99 |
| Waukesha, City | Waukesha City Water Utility | Motorola | H10UCH6DC5BN | 678SAW1563 | LTS-2000 w/o scan | 3.27 |
| Waukesha, City | Waukesha City Water Utility | Motorola | H10UCH6DC5BN | 678SAW2412 | LTS-2000 w/o scan | 3.75 |
| Waukesha, City | Waukesha City Water Utility | Motorola | H10UCH6DC5BN | 678SAW2433 | LTS-2000 w/o scan | 4.80 |
| Waukesha, City | Waukesha City Water Utility | Motorola | H10UCH6DC5BN | 678SAYDV79 | LTS-2000 w/o scan | 5.58 |
| Waukesha, City | Waukesha City Water Utility | Motorola | H10UCH6DC5BN | 678SAW1546 | LTS-2000 w/o scan | 9.54 |
| Waukesha, City | Waukesha City Water Utility | Motorola | H10UCH6DC5BN | 678SAYDV89 | LTS-2000 w/o scan | 16.53 |
| Waukesha, City | Waukesha City Water Utility | Motorola | H10UCH6DC5BN | 678SAW2439 | LTS-2000 w/o scan | 26.17 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760SAYFB59 | LCS-2000 w/o scan | 0.37 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760SBA0392 | LCS-2000 w/o scan | 0.38 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760SAYEZ78 | LCS-2000 w/o scan | 0.40 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760SAYFB75 | LCS-2000 w/o scan | 0.83 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760SAYEZ62 | LCS-2000 w/o scan | 1.09 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760SAYFC50 | LCS-2000 w/o scan | 1.15 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760SBA0391 | LCS-2000 w/o scan | 1.45 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760SAYFB82 | LCS-2000 w/o scan | 2.17 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760SAYFD13 | LCS-2000 w/o scan | 2.71 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760SAYFA00 | LCS-2000 w/o scan | 4.57 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760SAYFB78 | LCS-2000 w/o scan | 7.76 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760SAYFB99 | LCS-2000 w/o scan | 10.77 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M10UGD6DC5BN | 760scg0298 | LCS-2000 w/scan | 54.03 |
| | Waukesha City Water Utility Total | | | | | 162.21 |
| Waukesha, City Total | | | | | | 12,519.47 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ACG1252 | MTS-2000 Model I FM | 0.37 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2929 | MTS-2000 Model I FM | 0.38 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2947 | MTS-2000 Model I FM | 1.25 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2931 | MTS-2000 Model I FM | 1.27 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2930 | MTS-2000 Model I FM | 1.39 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2928 | MTS-2000 Model I FM | 1.54 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2935 | MTS-2000 Model I FM | 1.67 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2934 | MTS-2000 Model I FM | 3.30 |

| Grand Total | | | | | | 61,658.28 |
|---------------------------|---|----------|--------------|------------|---------------------|-----------|
| | | | | | | |
| Wisconsin, State of Total | | | | | | 8.51 |
| | Wisconsin State Patrol Total | | | | | 5.97 |
| Wisconsin, State of | Wisconsin State Patrol | Motorola | M01UJN6PW6BN | 722CEA0634 | MCS-2000 | 3.46 |
| Wisconsin, State of | Wisconsin State Patrol | Motorola | M01UJN6PW6BN | 722CEA0633 | MCS-2000 | 1.71 |
| Wisconsin, State of | Wisconsin State Patrol | Motorola | H01UCF6PW1BN | 466ABQ3785 | MTS-2000 Model II | 0.80 |
| | Wisconsin Department of Natural Resources Total | | | | | 2.53 |
| Wisconsin, State of | Wisconsin Department of Natural Resources | Motorola | H10UCH6DC5BN | 678SAQ3246 | LTS-2000 w/scan | 0.67 |
| Wisconsin, State of | Wisconsin Department of Natural Resources | Motorola | H01UCF6PW1BN | 466CCJ1955 | MTS-2000 Model II | 1.86 |
| Waukesha, Town Total | | | | | | 61.93 |
| | Waukesha Town Fire Department Total | | | | | 61.93 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1435 | MCS-2000 | 12.86 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1461 | MCS-2000 | 7.00 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1441 | MCS-2000 | 6.69 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1456 | MCS-2000 | 4.91 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1417 | MCS-2000 | 0.81 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1462 | MCS-2000 | 0.80 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1454 | MCS-2000 | 0.48 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ACG1251 | MTS-2000 Model I FM | 8.93 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2926 | MTS-2000 Model I FM | 8.27 |